FINAL REPORT Catch Basin Inserts for Ohio Roadways SEPTEMBER 2018

Prepared For:



Ohio Department of Transportation Office of Statewide Planning and Research

Columbus, Ohio

Prepared By:



GS&P/OH,INC.
AN AFFILIATE OF
GRESHAM
SMITH AND
PARTNERS

15E East Broad Street, Suite 900 Columbus, OH 43215

www.greshamsmith.com GS&P Project No. 42299.00 ODOT PID 103684 State Job No. 135444

i

Technical Report Documentation Page

1. Report No.	2. Government Accession No.			og No.	
FHWA/OH-2018-16					
4. Title and Subtitle			5. Report Date		
			September 2018		
Catch Basin Inserts for Ohio	o Roadways		6. Performing Orga	nization Code	
7. Author(s)			8. Performing Organization Report No.		
Tom Dietrich, Mark McCabe	e, Kathryn Gruver				
9. Performing Organization N	ame and Address		10. Work Unit No. (TRAIS)	
Gresham, Smith and Partne 155 East Broad Street, Suite			11. Contract or Gra	nt No.	
Columbus, Ohio 43215			SJN 135444		
			PID 103684		
12. Sponsoring Agency Name	e and Address		13. Type of Report	and Period Covered	
Ohio Department of Transp	ortation		Final Report, November 2016-September 2018		
1980 West Broad Street Columbus, Ohio 43223			14. Sponsoring Agency Code		
15. Supplementary Notes					
16. Abstract					
Detailed evaluation of roadside catch basin inserts (CBIs) for the removal of TSS. Study consisted of both field and laboratory testing. Field testing evaluated the installation, maintenance and removal needs for CBIs during a year-long installation period. The Lab testing evaluated the sediment retention associated with each CBI. Since none of the units met both the sediment removal and installation requirements, and due to the high effort and cost to maintain, the CBIs tested do not appear to be a viable option to be added as post-construction stormwater BMPs for ODOT.					
17. Keywords			18. Distribution Statement		
Catch basins, Catch basin inserts, water quality, storm water, stormwater, sediment retention, TSS, roadway BMP, post-construction BMP, OK 110, TARP			No restrictions. This document is available to the public through the National Technical Information Service, Springfield, Virginia 22161		
19. Security Classification (of this report)	20. Security Classification (of this page)	9 .	1. No. of Pages	22. Price	
Unclassified	Unclassified		03	LL. I HOG	
Form DOT F 1700.7 (8-72)	-			npleted pages authorized	

Gresham, Smith & Partners - Columbus GS&P Project: 42299.00

ODOT PID 103684

Catch Basin Inserts for Ohio Roadways

Prepared by:

GRESHAM, SMITH AND PARTNERS

In collaboration with:

AUBURN UNIVERSITY

DAVEY RESOURCE GROUP

September 2018

Prepared for and in cooperation with the Ohio Department of Transportation

The contents of this report reflect the views of the author(s) who is (are) responsible for the facts and the accuracy of the data presented herein. The contents do not necessarily reflect the official views or policies of the Ohio Department of Transportation. This report does not constitute a standard, specification, or regulation

Acknowledgments

Gresham, Smith and Partners would like to thank the following members of the ODOT team for their input on the development of the research:

Kelly Nye, Division of Planning - Statewide Planning and Research, Research Coordinator

Jeff Syar, P.E., Administrator, Office of Hydraulic Engineering

Becky Humphreys, P.E., Office of Hydraulic Engineering

Jon Prier, P.E., Office of Hydraulic Engineering

Jason Hoschak, District 1 - Transportation Administrator

Brian Rader, District 1 – Transportation Manager

The Highway Workers from District 1 for assisting with the field testing and maintenance of traffic

EXECUTIVE SUMMARY

The Ohio Department of Transportation (ODOT) is required to comply with Ohio Environmental Protection Agency (EPA) permit requirements in order to discharge stormwater runoff from roadway right of ways. ODOT has been working with the Ohio EPA to research, identify, implement, operate, and maintain sustainable stormwater best management practices (BMPs) that meet the post-construction water quality requirements. This research is assessing the viability of catch basin inserts (CBIs) as acceptable BMPs which ODOT could incorporate into its Location and Design Manual Volume 2 (L&Dv2).

From a water quality perspective, permit compliance is primarily focused on the removal of total suspended solids (TSS). Eight vendor CBI post-construction water quality products were chosen to be evaluated within the study using two primary selection criteria: (1) meeting 80% TSS removal per manufacturer's claims or independent testing and (2) the capability to be installed in an ODOT Catch Basin Type 3A (CB-3A). This research focused on collecting field and laboratory data that documents the performance of each CBI. The field testing evaluated each CBI's installation, maintenance, removal requirements and procedures over a twelve month period. The lab testing evaluated the solids removal associated with each CBI.

Field data results show that, except for the Triton™ CBI, all the other units do not comply with ODOT's design criteria for the CB-3A because the curb opening had to be obstructed for the CBI to function. However, the Triton™ installation and removal was the most labor intensive and time consuming. Installation was also difficult for the rigid frame type CBIs, including the DrainPac™ and FlexStorm®, due to inconsistent construction of the existing CB-3A's. All the CBIs required maintenance within the first three months after installation. Five CBI products became clogged (i.e., contained standing water) and were removed prior to the completion of the twelve month field study period. Three CBI products remained in the field for the entire duration of the study.

Lab data results for the performance evaluation testing showed that only two CBIs, DrainPac[™] and Adsorb-It[™], achieved 80% sediment retention. Longevity testing was also performed for all CBIs to determine the unit's ability to maintain performance and structural integrity over a more strenuous testing cycle. During longevity testing, the DrainPac[™] and Adsorb-It[™] fell below the cumulative sediment retention at approximately 80% for up to four tests for the OK110 silica sand before falling below the 80% threshold.

Although the research selection criteria were met individually by some of the CBIs evaluated, none of the CBIs met both of two primary selection criteria. Since none of the units met both the sediment removal and installation requirements, and due to the high level of effort and cost to maintain, the CBIs tested do not appear to be a viable option as a post-construction stormwater BMP within ODOT's L&Dv2 manual.

TABLE OF CONTENTS

1	Introduction	
2	Literature Review	
	Basket Type	
	Bag Type	
	Cartridge Type	
3	Catch Basin Insert Selection	5
	Criteria	5
	Selection	5
4	Field Testing	11
	Location Selection	11
	Catch Basin Modifications	
	Installation	13
	Storm event and Rainfall accumulation.	16
	Inspection	17
	Maintenance	18
	CBI Removal	23
	Field testing summary	23
	General Field testing conclusions	24
5	Lab Testing	26
	Literature review	26
	Overview of Lab Testing Plan	28
	Determination of Flow Characteristics	
	Sediment Introduction	30
	Equipment and Methodology	32
	Performance Evaluation of CBIs	
	Lab Results	37
	Longevity Testing	39
6	General Laboratory Conclusions	
7	Conclusion	

TABLES

Table 2-1 Primary Advantages and Disadvantages of CBI Types	3
Table 3-1 CBI Product List	6
Table 3-2 CBI Descriptions	7
Table 4-1 Installation Summary	16
Table 4-2 Manufacturer Recommended Maintenance	20
Table 4-3 CBI June 2017 Maintenance Summary	21
Table 4-4 CBI August 2017 Maintenance Summary	21
Table 4-5 CBI October 2017 Maintenance Summary	22
Table 4-6 CBI December 2017 Maintenance Summary	22
Table 4-7 CBI Removal Summary	23
Table 4-8 CBI Inspection Log	24
Table 5-1 Summary of Previous CBI Lab Testing	28
Table 5-2 Summary of Drainage Areas and Corresponding Testing Flow Rates and Volumes	3.30
Table 5-3 Summary of Sediment Retention Percentage of Performance Evaluation Testing	38
Table 5-4 Summary of Sediment Retention Percentage of Longevity Tests	40
Table 7-1 CBI Overall Results Summary	46

FIGURES

Figure 4-2: Standard CB-3A	12
Figure 4-3: Cross section view of CB-3A	12
Figure 4-4: Throat block top view	13
Figure 4-5: Throat block front view	13
Figure 4-6: Sheet metal in front of throat block	13

Figure 4-7: Throat block adhesive attachment	13
Figure 4-8: Site 1 catch basin locations w/ corresponding ID no's	14
Figure 4-9: Site 2 catch basin locations w/ corresponding ID no's	14
Figure 4-10 Catch Basin Connecting Conduit	15

Figure 4-11: Rainfall Accumulation Data	17
Figure 4-12: Typical Visual Inspection	18
Figure 5-1: ASTM D7351 channel schematic	26

Figure 5-2: Soil mixing process	31
Figure 5-3: USDA soil classification triangular chart	31
Figure 5-4: Comparison of soil types used for testing	32
Figure 5-5: Schematic of CBI testing apparatus	33

. Igair o or conomatio or obritosting apparation	
Figure 5-6: Catch Basin Insert (CBI) testing apparatus.	34
Figure 5-7: Modifications to flow conveyance system based on flow rate	
Figure 5.9: Dynago allowed between discharge methods	20

APPENDICES

Appendix A: Literature Review

Appendix B: CBI Field Testing Inspection, Maintenance and Removal Forms

Appendix C: Laboratory CBI Performance Evaluation Testing

ACRONYMS AND ABBREVIATIONS

The listing of acronyms and abbreviations.

ac Acres

ADT Average Daily Traffic

AU-ESCTF Auburn University Erosion and Sediment Control Test Facility

BMP Best Management Practice

CB Catch Basin
CBI Catch Basin Insert
CB-3A Catch Basin Type 3A

CGP Construction General Permit DOT Department of Transportation

F Fahrenheit

FHWA Federal Highway Administration

ft Feet ft³ Cubic feet

ft³/s Cubic feet per second ID# Identification Number

lb Pounds

lb/ft³ Pounds per cubic foot

L&Dv2 Location and Design Manual Volume 2

min Minutes

mg/L Milligrams per liter

MS4 Municipal Separate Storm Sewer System

NPDES National Pollutant Discharge Elimination Systems

NRCS National Resources Conservation Service

ODOT Ohio Department of Transportation
Ohio EPA Ohio Environmental Protection Agency

PVC Polyvinyl Chloride SR State Route

SRD Sediment retention device SS995 Supplemental Specification 995

TARP Technology Acceptance Reciprocity Partnership

TSS Total Suspended Solids

USDA United States Department of Agriculture

WQf Water Quality Flow

I

INTRODUCTION

The Ohio Department of Transportation (ODOT) is required to comply with the Ohio Environmental Protection Agency (Ohio EPA) National Pollutant Discharge Elimination Systems (NPDES) Construction General Permit (CGP) and the Municipal Separate Storm Sewer System (MS4) Permit in order to discharge stormwater runoff from roadway right of ways. From a water quality perspective, compliance with the post-construction stormwater requirements of the CGP is primarily focused on total suspended solids (TSS). Compliance with the NPDES regulations also allows ODOT to meet their Federal Highway Administration (FHWA) required environmental commitments for projects that require post-construction water quality controls per the CGP.

ODOT has been working with Ohio EPA since 2009 to identify, implement, operate, and maintain sustainable post-construction stormwater best management practices (BMPs) that address Ohio EPA's CGP requirements. ODOT has unique challenges as a non-traditional MS4 entity that include limited right-of-way space to design and construct stormwater BMPs. ODOT also has a responsibility to understand individual BMPs' maintenance requirements and likely performance. This research is intended to assess the viability of catch basin inserts (CBIs) as potential alternative stormwater BMPs to meet the post-construction water quality requirements. CBIs have the potential to reduce the TSS loads and are accepted by other state DOTs (e.g., Virginia, Oregon, and New York). ODOT continues to receive requests from vendors to consider and accept CBIs as post-construction water quality products for use on ODOT projects.

While CBIs have shown potential to remove TSS, whether or not the extent of the TSS removal meets Ohio EPA requirements remains unclear. If it is demonstrated that the performance of CBIs met Ohio EPA's requirements and that the levels of maintenance are reasonable and economical, Ohio EPA could approve the CBIs to become an acceptable alternative BMP, which ODOT could incorporate into its Location and Design Manual Volume 2 (L&Dv2).

This research will provide a third party evaluation of eight vendor CBI post-construction water quality products. The research is focused on collecting laboratory and field data that documents the lab performance of each CBI to remove sediment as the CGP requires and also documents the field performance based on each CBI's maintenance requirements.

2 LITERATURE REVIEW

The research planned for this study was built upon existing documentation of CBI performance and maintenance, with special attention to reports associated with roadside catch basins. Several documents, studies and reports were identified and used as reference for selecting the CBIs for lab and field testing. Appendix A lists the documents used to identify the types and characteristics of CBIs to be included in the study.

Many of these documents served as the basis for determining the types and characteristics of each of the CBIs. The CBIs fell into three distinct types: basket, bag, and cartridge. The basket type has a rigid structure with internal media providing the treatment. The bag type does not have a rigid structure, the bag itself provides the treatment. The cartridge systems are contained within a rigid frame with the treatment provided within a manufacturer provided cylinder.

BASKET TYPE

The basket type consists of a rigid frame containing a fabric liner or media packet. The basket is supported by the frame of the catch basin and the grate is placed on top holding the basket in place. The basket usually has large orifice holes that would not facilitate the capture of fine materials. The basket fabric liner or internal media provide the majority of the TSS removal.




Figure 2-1: Basket Type CBI (Source: Old Castle)

BAG TYPE

The bag type CBI is similar to the basket type. The bag CBI is constructed of fabric bag material attached to a frame. The frame is supported within the catch basin underneath the grate. Treatment is provided by the fabric bag or media packets located within the fabric bag. There is no rigid support structure around the fabric bag, the bag provides all the needed support to contain the accumulation of debris. The bag fabric or media provide the TSS removal.




Figure 2-2: Bag CBI (Source: Advanced Drainage Systems)

CARTRIDGE TYPE

The cartridge type CBI contains a tray with filter media contained within a cartridge. The tray is installed within the catch basin below both the grate and curb openings. The cartridge can sit above or below the tray. The tray will contain any collected gross solids, with the cartridge providing the TSS removal.




Figure 2-3: Cartridge Type (Source: REM Filtration)

TABLE 2-1 provides a summary of advantages and disadvantages of the three primary CBI types.

Table 2-1 Primary Advantages and Disadvantages of CBI Types

CBI Type	Advantages	Disadvantages
Cartridge	Disposable cartridges allow for easy maintenance.	Most are too large for smaller, single grate catch basins.
Bag	Ponding of water inside bag allows for some settling of finer particles.	Material can often be easily clogged with sediment or ripped, requiring maintenance or replacement.
Basket	Baskets are often durable and long-lasting.	Structural frames can add weight to CBI, making installation and removal more difficult.

The literature review was also used to document characteristic categories for the CBIs. The main characteristic categories were identified as: (1) general, (2) installation, (3) maintenance, and (4) performance. Within each category several criteria were identified as differentiators between the CBIs. A matrix was developed using the categories and criteria to assess and gather information on each CBI's characteristics. Although these characteristics were not used in the selection of the CBIs for testing, the information may be useful to end users of the products. Table 2-2 summarizes the characteristics documented through the literature search.

Table 2-2 CBI Characteristic Categories

General	Installation	Maintenance	Performance
Vendor location	Size: Base fits within	Vendor maintenance	80% TSS removal
Warehouse location	CB-3A	guide available	performance, of TARP or OK110 soil
Coat of CDI	Size: Frame/Grate with	Frequency of inspection	types
Cost of CBI	no corrections to frame/grate	Frequency of media	Maximum flow rate
# of media units needed	Size: CBI Depth	replacement	before
per CB-3A	Зіге. Сы Беріп	Frequency of cleaning	overflow/bypass
Cost of media replacement	Size: CBI available for other ODOT standard	Cleaning methods	Maximum bypass/overflow rate.
	inlets/catch basins	Cleaning methods	
Specifications/ standard drawings available	Vendor supplied	Cleaning procedures	Testing available
	installation instructions	# of personnel needed	Tested by outside
CBIs approved for use by other DOT's	Vendor to supply	to inspect/maintain unit	agency
	installation support	Time required to	
CBI used in other industries	Number of personnel	clean/replace filter	
	needed to install (not	Does the outlet pipe	
	including MOT)	require plugging to clean CBI	
	Time Required to install		
		Specialized equipment needed to maintain or	
		clean	

3 CATCH BASIN INSERT SELECTION

The first step in the process was to identify potential CBIs for inclusion in the study. A review of the information compiled from documents, internet searches, and discussions with industry personnel was completed to identify possible CBIs for the study.

CRITERIA

The research was limited to testing up to 10 units, with the purpose of studying a variety of types to determine the applicably of using CBIs as post-construction water quality BMPs to meet regulatory performance requirements, as well as the potential operational and maintenance needs. Although the CBIs were tested on an individual basis, this study is not intended to represent approval or acceptance by ODOT or Ohio EPA.

There are two primary criteria a CBI unit needed to satisfy for inclusion into the study:

- 1.) The unit must be able to meet the 80% sediment retention¹, and;
- 2.) The unit needs to be able to be installed in a standard ODOT CB-3A.

SELECTION

A total of 16 CBIs were initially identified as having the potential to satisfy the 80% sediment retention criteria. Seven of the 16 CBIs did not have a standard size available that could be installed in ODOTs CB-3A, therefore these units were removed from further consideration. One other potential CBI was removed due to the unit's very low flow rate. The flow rate for this unit was an order of magnitude lower than others reviewed. The remaining eight CBI vendor products were selected for the field and laboratory testing part of the study. The testing included eight CBI products (Table 3-1) that provided three different types of inserts: basket, bag, and cartridge, which were evaluated in the field at two different sites (i.e., Site 1 and Site 2 – described further in Section 4), as well as in a controlled testing setting at the Auburn University's-Erosion and Sediment Control Test Facility (AU-ESCTF).

From the vendor perspective, the Gullywasher© had a bag and basket version of the same product, only the bag type was included in the study in an attempt to balance the study between insert types. Only one cartridge type CBI was identified to be included.

¹ From testing data or manufacturer's claim.

Table 3-1 CBI Product List

CBI Name	CBI Manufacturer	CBI Type	Site 1	Site 2
Adsorb-It™	Stormwater BMP Products, LLC	Basket	114	205
DrainPac™	United Storm Water, Inc.	Basket	104	n/a
Flo-Gard Plus®	KriStar / Oldcastle Stormwater Solutions	Basket	110	208
WQS	Water Quality Solutions, LLC	Basket	111	209
FlexStorm® Inlet Filters	Advanced Drainage Systems(ADS), Inc,	Bag	105	210
Gullywasher©	Gullywasher, LLC	Bag	109	211
Storm Sentinel®	Enpac, LLC	Bag	101	213
Triton™	REM Filtration	Cartridge	113	207

All the CBIs were used in both the field and laboratory testing. The CBIs were installed in existing ODOT standard CB-3As constructed in 1977, 2013, and 2015. The following Table 3-2 includes a brief description and photographs for each CBI.

Table 3-2 CBI Descriptions			
CBI Name	General description		
Profile view	Top view		
Adsorb-It [™]	Basket-type CBI consisting of a heavy-duty Polyvinyl Chloride (PVC) coated wire mesh steel basket supported by a rigid stainless steel frame. An internal filtration fabric material is supported by the PCV basket.		
DrainPac™	Basket type CBI with a stainless steel metal basket lined with a filter fabric bag. The filter fabric is on the outside of the basket. A plastic netting attached to the metal frame provides support to the fabric.		

Table 3-2 CBI Descriptions	
CBI Name	General description
Profile view	Top view
Flo-Gard Plus®	Basket type CBI with a plastic, large-mesh basket structure. The plastic basket provides supports for a woven filter fabric liner that is attached to a stainless steel frame. The CBI contains two media packets.
WQS	Basket type CBI consisting of a hard-plastic outer shell with layers of filters stacked inside for a staged-treatment approach. The upper half of the CBI consists of four plastic mesh filters, each decreasing in mesh size deeper into the shell. The bottom half of the CBI consists of two fine mesh metal screens.

Table 3-2 CBI Descriptions	
CBI Name	General description
Profile view	Top view
FlexStorm® Inlet Filters	Bag type CBI with a stainless steel frame and a woven geotextile filtration bag. The bag is lined with carpet fiber material to treat water exiting the bag. An additional more permeable fabric sits between the filtration bag and the stainless steel frame.
	PACK PACK
Gullywasher©	Bag type CBI with a non-woven geotextile filter fabric mounted on a rectangular metal frame. The bag is also supported by nylon straps that wrap under the bottom of the bag and support loads when the bag is full.
	THE THIRD WITH THE THE THE THE THE THE THE THE THE T

Table 3-2 CBI Descriptions	
CBI Name	General description
Profile view	Top view
Storm Sentinel®	Bag-type CBI constructed of a nonwoven geotextile fabric that is supported by an adjustable steel wire frame.
Triton™	Cartridge type CBI with a filter cartridge consisting of a fine mesh medium, enclosed by a stainless steel housing that prevents debris from damaging the filter media. Filter sits on a base which fits down into the catch basin and is sealed against the catch basin structure, preventing water from exiting the catch basin without passing through the replaceable filter cartridge.

4 FIELD TESTING

LOCATION SELECTION

Two field testing locations of curbed roadway owned by ODOT were needed to provide replication to support valid test results and support the consistency of data at each site. The field testing areas needed to provide a relatively long stretch of roadway with consistent roadway characteristics, such as lane width, average daily traffic (ADT), drainage area, impervious area and weather patterns. Two field testing locations meeting these conditions were identified in Allen County, Ohio (refer to Figure 4-1). The field testing occurred on two state routes within the urbanized area around Lima, Ohio. Site 1 was located on SR 117 between Lost Creek Boulevard and Bowman Road. Site 2 was located on SR 81 between South Sugar Street and I-75. The two sites both provided a large number of catch basins for the installation of the CBIs. The site characteristics were similar enough between the two sites to provide an adequate basis of comparison.

Site 1 was located near the Allen County Fairgrounds on SR 117. The surrounding parcels are the County fairgrounds and agricultural land uses. SR 117 has two 12-foot lanes, a two-foot curb and gutter, with an ADT of 8,042. The drainage areas range from 0.10 to 0.16 acres of impervious surface.

Site 2 was located on SR 81 west of I-75. SR 81 has four 12-foot lanes with a two-foot curb and gutter. The surrounding parcels are mostly commercial and retail. The ADT is 11,366. The drainage areas range from 0.07 to 0.17 acres of impervious surface.



Figure 4-1: Field Testing Sites (Source: GoogleMaps, 2018)

CATCH BASIN MODIFICATIONS

The standard ODOT CB-3A is a single grated curb inlet with a grate and throat opening along the curb. See Figure 4-2 for an image of ODOT's Standard CB-3A. Stormwater flow in the gutter is captured by both the grate and curb throat opening. Most of the CBI units are designed to be installed within the grate, which provides treatment to only the stormwater flowing through the grate (refer to Figure 4-3). Stormwater flowing into the curb throat opening would bypass seven of the eight CBI units installed under the grate and the stormwater would not receive treatment. To prevent stormwater from entering the curb throat opening, the opening was blocked with a device called a "throat block". The throat block covers the entire curb opening, forcing stormwater into the grate. ODOTs design requirements for pavement spread and inlet spacing includes the stormwater flow to be captured in both the grate and curb throat opening. Blocking the curb inlet permanently would restrict flows below the design standard used for determining catch basin spacing. The design spacing is calculated assuming the curb throat opening is the only inlet, and the grate inlet is used as a safety factor. Intentionally blocking the curb opening was allowed by ODOT for this study only, but would not otherwise be considered an acceptable practice.



CATCH BASIN INSERT

Figure 4-2: Standard CB-3A

Figure 4-3: Cross section view of CB-3A

The throat block for the catch basins was accomplished by cutting 2"x6" treated dimensional lumber to fit the opening. Using slightly oversized pieces, the device was forced into the throat, which would affix the wood plug in place. Pliable sheet metal (26-gage) was cut to cover the wood plug and provide additional coverage over the catch basin throat. The sheet metal was fastened to the wood plug, protecting the wood and providing additional cover over the throat. The sheet metal was screwed into the wood and any gaps were sealed with caulk (See Figure 4-4, Figure 4-5, and Figure 4-6).





Figure 4-4: Throat block top view




Figure 4-5: Throat block front view




Figure 4-6: Sheet metal in front of throat block

Figure 4-7: Throat block adhesive attachment

INSTALLATION

The CBIs were installed between March and June 2017, with the majority installed in March. The manufacturers provided installation guidelines and procedures for each CBI as part of the delivery. Each CBI was installed in accordance with the manufacturer's recommendations and guidelines. Deviations from the manufacturer's recommendations were recorded on the installation forms. See Appendix B for the completed installation forms.

At Site 1, eight CBIs were installed. Three bag types, four basket types, and one cartridge type. All the bags and three of the baskets were installed in March, 2017. The cartridge unit was installed in April, 2017. The final basket was installed in June, 2017. Figure 4-8 shows the distribution of the CBIs at Site 1 with their corresponding CBI ID numbers shown in Table 4-1.



Figure 4-8: Site 1 catch basin locations w/ corresponding ID no's. (Source: GoogleMaps, 2018)

At Site 2, seven CBIs were installed. Three bag types, three basket types and one cartridge. All the bags and two of the baskets were installed in March, 2017. The cartridge unit was installed in April, 2017. The final basket was installed in June, 2017. One CBI could not be installed at Site 2 because the basket unit had a very rigid housing which caused it to impact the connecting conduits or the rim of the concrete catch basin. Figure 4-9 shows the distribution of the CBIs at Site 2 with their corresponding CBI ID numbers shown in Table 4-1.



Figure 4-9: Site 2 catch basin locations w/ corresponding ID no's. (Source: GoogleMaps, 2018)

During the installation process, all of the units, excluding the Triton[™], could be lifted and installed by one person. The time to install the CBI includes time associated with the following

activities: removal of grate, clean debris, adjustments to CBIs, insert CBI, and reset grate. The standard equipment needed for installation included a grate lifter, brush, and scraper.

The time to install each unit and any additional observations are included in Table 4-1. The installation of the throat block required 10 minutes and was not included in the total unit installation times. Six of the CBI products were installed in 15-minutes or less. The remaining two CBIs required longer than 30-minutes, ranging from 37 to 83 minutes. As noted above, one of the basket units had a very rigid housing which limited the ability to install this CBI when connecting conduits created conflicts or the rim of the concrete catch basin was somewhat irregularly shaped. Installation of this CBI was possible in only one of the catch basins in the study area. Figure 4-10 shows an example of the potential issue for a CBI to impact a connecting conduit within the catch basin. Another CBI had a very rectangular frame which would not fit within the rounded corners of the catch basin frames. The corners of the CBI were ground down or cut off to allow for installation. Appendix B contains copies of all the installation logs.



Figure 4-10 Catch Basin Connecting Conduit

Table 4-1 Installation Summary

- 4510		Tarring y		
			Total time	
ID#	CBI Name	Type	(min)	Installation Notes
101	Storm Sentinel®	bag	6	No issues
104	DrainPac™	basket	7	shape of the unit limited install locations. 10 catch basins were tried, site 104 was the only successful install location (other locations attempted 101, 105, 109, 110, 111, 205, 206, 209, and 210)
105	FlexStorm®	bag	37	Frame required trimming with circular saw to fit within the CB Required two people because of cutting.
109	Gullywasher©	bag	8	No issues
110	Flo-Gard Plus®	basket/bag	8	No issues
111	WQS	basket	11	Needed to adjust the handles to not impact the grate. The bolts on the handles were adjusted to let them sit lower into the CBI.
113	Triton™	cartridge	83	Installation of tray was difficult and required cutting of tray to fit within the CB, required two people.
114	Adsorb-It™	basket	15	No issues
205	Adsorb-It™	basket	10	Outlet pipe in CB prevented basket from fitting within CB. The basket was reshaped to avoid the outlet pipe allowing the insert to be installed.
207	Triton™	cartridge	75	Top hat location had to be moved closer to the front of the base to allow the unit to be installed within the catch basin. New holes were drilled and the vacated screw holes were filled with spray foam. required two people.
208	Flo-Gard Plus®	basket/bag	9	No issues
209	WQS	basket	10	Handles are higher than the basket, without modification the grate would sit on the handles. The handles were removed, bent slightly and reattached.
210	FlexStorm®	bag	65	Frame required trimming with saw to fit within the CB. Required two people because of cutting.
211	Gullywasher©	bag	12	No issues
213	Storm Sentinel®	bag	13	No issues

STORM EVENT AND RAINFALL ACCUMULATION

Storm event and rainfall data was collected during the study to validate the conditions were representative of typical weather and precipitation events. The rainfall data was obtained from the weather station at the Lima Allen County Airport, three miles from Site 1 and seven miles from Site 2. Over the course of the study, 133 events occurred with measurable precipitation and seventeen rain events exceeded 0.75 inches per day (i.e., Ohio EPA's water quality storm depth). The total rainfall accumulation for the year was 39.39 inches. The largest rainfall event occurred in November with 2.27 inches measured. Gathering rainfall data also allowed the inspection team to conduct six monthly inspections during or within 24 hours of a storm event to

visually monitor performance and potential impacts to traffic conditions. Figure 4-11 shows the rainfall accumulation and installation, maintenance and inspection activities at the two research locations.




Figure 4-11: Rainfall Accumulation Data

INSPECTION

A monthly inspection was conducted for each CBI to monitor performance and condition in the field over the year testing period. Six of the inspections were performed during wet weather events or within 24 hours of measurable precipitation to evaluate the units' performance after a recent stormwater runoff collection event. Each inspection included an assessment of the CBI and throat blockage function and debris accumulation within and around each unit. Current roadway and weather conditions were also observed. Photos were taken to document each CBI's condition and surrounding conditions at the time of inspection. The CBI inspection, while monitoring performance, also aided in determination of maintenance needs for each individual unit. All inspection items were logged in a standard monthly inspection form, provided in Appendix B

Inspection of the CBIs were performed without the removal of the grate or removing the units from the catch basin. The observations were based solely on conditions visible through the catch basin grate and the observed accumulated debris contents of the CBIs. Several of the CBIs with filter media layers or external filter pieces proved difficult to inspect during the monthly visits due to lack of visibility through the grate openings to all sections of the unit. Specifically,

for basket type units with a fabric lining, the outside of the unit only allowed a partial visual inspection. The external fabric liner was not visible through the catch basin and only the internal basket could be inspected. Any accumulation of debris within that portion of the filter fabric could not be determined. Any basket types with internal layered filter media also posed a problem in obtaining a complete visual inspection. The top layer of the media could only be viewed while any debris or water accumulation within the unit below that top layer was not visible. Figure 4-12 provides an example of the typical visual inspection view of a CBI unit showing standing water.



Figure 4-12: Typical Visual Inspection

An analysis of the inspection details was completed each month to determine the current condition of the CBIs and if the condition of the CBI could pose a potential safety risk to the traveling public. This analysis was used to determine the nature of the next month's activities. The activity could be an inspection, maintenance, or removal of the CBI.

MAINTENANCE

The original maintenance schedule and activities for each CBI was set based on review of the vendor information provided with the unit. The amount of maintenance and replacement information included varied between CBI units. Most included recommendations as to how often to maintain the unit, however the details on the exact type of maintenance to perform was often excluded. Two of the vendors did not provide any maintenance information, with one of the two only including details for removal of the unit. The field research team recommended frequency of maintenance based on inspection of the CBI and its performance in the field. If the unit had accumulated a certain volume of solids or water, then maintenance would be required.

For consistency between all CBIs, if a unit was observed with standing water or half full of debris during the monthly inspection, then maintenance would be performed the following month. This maintenance schedule follows most vendor recommendations and provided a maintenance plan approach for other units that did not provide details pertaining to maintenance. The schedule did not decrease recommended maintenance frequency for any CBI units. All units were provided the same, and in some cases more, maintenance than detailed by the vendor.

Units that were shipped without maintenance instructions or guidance were maintained based on a similar CBI vendor-provided maintenance recommendations. It was determined, if a CBI required maintenance, that all units would have removal of debris by a shop vacuum on site. After the removal and disposal of debris, every bag and most basket type CBIs were removed and taken to a nearby facility to back flushed with water. Each unit was back flushed until water ran clear and positive flow through the filter was achieved. While most bag type CBIs were not recommended to be back flushed, this extra step in maintenance was added to ensure all bag types were cleaned as well as possible and equal to the other CBI types. Cartridge type CBIs were only vacuumed to remove debris, but were not flushed with water. These units were difficult to remove to perform back flushing maintenance due to the seal and fastening of the units to the CB. Table 4-2 provides a comparison of vendor recommended maintenance to maintenance performed in the field.

Table 4-2 Manufacturer Recommended Maintenance

							ID	#									
	Storm Sentinel®		DrainPac™	FlexStorm®		Gullywasher©		Flo-Gard Plus®		WQS		Triton™		Adsorb-It™			
	101	213	104	105	105 210 109		211	110	10 208		111 209		113 207		205		
	ba	ag	basket	ba	ag	ba	ag	bas	ket	bas	ket	cartr	idge	bas	ket		
Vendor Recommended Maintenance Schedule	None		Clean 3-4 times per year	If solids accumulate or		Clean 3 times per year		Annual cleaning		Clean 3 times per year		Remove accumulated debris monthly. Every 6 months, wash					
Vendor Recommended Maintenance Type	None		None	Vacuur flush w mediun spray.	ith	Dump of and was pressure	h with	None		None	e	None)	Vacuui flush wi water			
Vendor Recommended Replacement	If 50% or eve month	ery 6	None	If torn of puncture >1/2" diameter lower he bag.	red er on			Replace filter medium annually		None		None		Filter m to be re every 6 months	placed -12		
Actual Maintenance	Back flushe after month	ed three	Debris removed twice, back flushed in Oct	Back fli after th months	ree	Back flushed after three months		Debris removed twice, back flushed in Oct		twice, back		Debris removed Aug, Oct, Dec		Debris removed Aug, Oct, Dec		Debris removed twice, back flushed in Oct	

While performing the maintenance, the amount and type of debris collected was documented. Site 1 and Site 2, while being relatively close in proximity, varied in the type and amount of debris collected in each CBI. Site 2 units collected larger amounts of debris, mainly fine road grit and trash. Site 1 units collected more organic materials, such as grass clippings, as well as some larger road grit. While the type of debris collected varied between sites, both field study sites required the same number of maintenance visits.

By the end of the second month several CBIs were clogged and contained standing water. During the third month maintenance was performed on the clogged units. The maintenance consisted of removing debris from the CBI, removing the CBI from the catch basin, back flushing the CBI to achieve positive drainage, and reinstalling the CBI in the original catch basin. The volume of debris removed was measured and disposed of at ODOT's Allen County Garage. See Table 4-3 for a summary of the June 2017 Maintenance.

Table 4-3 CBI June 2017 Maintenance Summary

Product Name	ID#	Туре	Maintenance activity	Volume of Debris Removed						
Storm Sentinel®	101	bag	Debris removed and back flushed	< 1 gallon						
FlexStorm®	105	bag	Debris removed and back flushed	< 1 gallon						
Gullywasher©	109	bag	Debris removed and back flushed	< 1 gallon						
FlexStorm®	210	bag	Debris removed and back flushed	< 1 gallon						
Gullywasher©	211	bag	Debris removed and back flushed	< 1 gallon						
Storm Sentinel®	213	bag	Debris removed and back flushed	< 1 gallon						

In the fifth month all the units received maintenance based on the amount of debris accumulation noted in the July 2017 monthly inspection. The maintenance consisted of removing debris from the CBI. The volume of debris removed was measured and disposed of at ODOT's Allen County Garage. See Table 4-4 for a summary of the August 2017 maintenance activities.

Table 4-4 CBI August 2017 Maintenance Summary

Product Name	ID#	Туре	Maintenance activity	Volume of Debris Removed
Storm Sentinel®	101	bag	Vacuum debris	< 1 gallon
DrainPac™	104	basket	Vacuum debris	1.5 gallons
FlexStorm®	105	bag	Vacuum debris	1.5 gallons
Gullywasher©	109	bag	Vacuum debris	< 1 gallon
Flo-Gard Plus®	110	basket	Vacuum debris	< 1 gallon
WQS	111	basket	Vacuum debris	1 gallon
Triton™	113	cartridge	Vacuum debris	1 gallon
Adsorb-It™	114	basket	Vacuum debris	< 1 gallon
Adsorb-It™	205	basket	Vacuum debris	3.5 gallons
Triton™	207	cartridge	Vacuum debris	4 gallons

Gresham, Smith & Partners - Columbus

GS&P Project: 42299.00 ODOT PID 103684 Table 4-4 CBI August 2017 Maintenance Summary

Product Name	ID#	Туре	Maintenance activity	Volume of Debris Removed
Flo-Gard Plus®	208	basket	Vacuum debris	8 gallons
WQS	209	basket	Vacuum debris	3 gallons
FlexStorm®	210	bag	Vacuum debris	< 1 gallon

During the sixth month several CBIs were observed to be clogged and contained standing water. During the seventh month maintenance was performed on the clogged units. The maintenance consisted of removing debris from the CBI, removing the CBI from the catch basin, back flushing the CBI to achieve positive drainage, and reinstalling in the original catch basin. The cartridge and two of the basket types were not back flushed, only the debris was removed. For all CBIs, the volume of debris removed was measured and disposed of at ODOT's Allen County Garage. See Table 4-5 for summary of October 2017 maintenance activities.

Table 4-5 CBI October 2017 Maintenance Summary

Table 4-5 CBI October 2017 Maintenance Summary									
Product Name	oduct Name ID# Type Ma		Maintenance activity	Volume of Debris Removed					
DrainPac™	104	basket	Debris removed and back flushed	< 1 gallon					
Flo-Gard Plus®	110	basket	Debris removed and back flushed	< 1 gallon					
WQS	111	basket	Vacuum debris	< 1 gallon					
Triton™	113	cartridge	Vacuum debris	1 gallon					
Adsorb-It™	114	basket	Debris removed and back flushed	< 1 gallon					
Adsorb-It™	205	basket	Debris removed and back flushed	1 gallon					
Triton™	207	cartridge	Vacuum debris	2 gallons					
Flo-Gard Plus®	o-Gard Plus® 208 basket De		Debris removed and back flushed	1 gallon					
WQS	209	basket	Vacuum debris	< 1 gallon					

During the eighth month two of the CBIs were observed to have accumulated debris between the grate and the CBI. The maintenance consisted of removing debris from the CBI. The volume of debris removed was measured and disposed of at ODOT's Allen County Garage. See Table 4-6 for a summary of the December 2017 maintenance activities.

Table 4-6 CBI December 2017 Maintenance Summary

Product Name	ID#	Туре	Maintenance activity	Volume of Debris Removed
WQS	111	basket	Vacuum debris	< 1 gallon
WQS	209	basket	Vacuum debris	4 gallons

For all maintenance performed, debris removed was measured and photos taken to document conditions before and after maintenance. Any additional tools or steps needed to clean each CBI or deviations from vendor recommendations were also noted in the maintenance forms. All completed field maintenance forms are provided in Appendix B.

CBI REMOVAL

Over the duration of the study, decisions were made to remove specific CBIs based on observed field performance. The units were removed from further field testing after the second observation of standing water within the CBI, which indicated the unit required replacement. A summary of the CBI removal is provided in Table 4-7

Table 4-7 CBI Removal Summary

Table 4-7 CBI	Remova	Summary				
Product Name	ID#	Month Installed	Month Removed	Reason for removal	Length of time installed	Time required to remove
Storm Sentinel®	101	March	October 2017	Clogged	7 months	2 minutes
DrainPac™	104	March	March 2018	End of study/fabric damaged	12 months	6 minutes
FlexStorm®	105	March	October 2017	Clogged	7 months	2 minutes
Gullywasher©	109	March	October 2017	Clogged	7 months	3 minutes
Flo-Gard Plus®	110	March	March 2018	End of study	12 months	13 minutes
WQS	111	March	March 2018	End of study	12 months	18 minutes
Triton™	113	May	December 2017	Clogged	7 months	48 minutes
Adsorb-It™	114	June	December 2017	Clogged	6 months	4 minutes
Adsorb-It™	205	June	December 2017	Clogged	6 months	7 minutes
Triton™	207	May	March 2018	Clogged	8 months	70 minutes
Flo-Gard Plus®	208	March	March 2018	End of study	12 months	12 minutes
WQS	209	March	March 2018	End of study/frozen	12 months	8 minutes
FlexStorm®	210	March	October 2017	Clogged	7 months	2 minutes
Gullywasher©	211	March	August 2017	Clogged	5 months	3 minutes
Storm Sentinel®	213	March	August 2017	Clogged	5 months	4 minutes

FIELD TESTING SUMMARY

The conditions of each CBI observed in the field were broadened to five status categories: installed (I), functional (F), clogged (C), maintenance completed (M), and removed (R). The status of a unit provided insight into their performance as well if activities such as maintenance or removal would be required in the following month. Table 4-8 outlines these monthly inspection statuses of each unit over the year timeframe and give a generalized view of performance.

Table 4-8 CBI Inspection Log

Table 4-6 CE	ןטווווסן	Mar	April	May	June	July	Aug	Sept	Oct	Nov	Dec	Jan	Feb	Mar
			1	2	3	4	5	6	7	8	9	10	11	12
Wet Weath Inspectio			Х	Х	Х	Х	Х			snow	snow			
Product Name	ID#						Cond	ition S	tatus					
Adsorb-It™	114				I	F	M	С	M	C	R			
Adsorb-It™	205				I	F	М	С	M	O	R			
DrainPac™	104	- 1	F	F	F	F	M	F	M	F	F	F	F	R
FlexStorm®	105	- 1	F	С	M	F	M	С	R					
FlexStorm®	210	- 1	F	С	M	F	M	С	R					
Flo-Gard Plus®	110	_	F	F	F	H	M	F	M	F	F	F	F	R
I PIUS(R)	208	_	ш	ш	F	ш	M	ш	M	ш	F	I	O	R
Gullywasher ©		_	ш	O	М	ш	M	O	R					
Gullywasher ©	211	_	H	С	М	C	R							
Storm Sentinel®	101	_	ш	O	М	ш	M	O	R					
Storm Sentinel®	213	_	H	O	М	O	R							
Triton™	113			I	F	F	M	F	M	F	R			
Triton™	207			I	F	F	M	F	M	F	F	F	С	R
WQS	111		F	F	F	F	M	F	M	F	M	F	С	R
WQS	209		F	F	F	F	M	F	M	F	M	F	С	R

GENERAL FIELD TESTING CONCLUSIONS

Installation

- Except for the Triton™ CBI, all the other units do not comply with ODOT's design criteria for the CB-3A because the curb opening had to be obstructed for the CBI to be effective.
- All units, excluding the Triton[™], during the installation process could be lifted by one person and could have been installed by one person.
- The Storm Sentinel®, DrainPac™, FlexStorm®, Gullywasher©, Flo-Gard Plus®, and WQS CBIs were installed in 15 minutes or less.
- The Triton™ and FlexStorm® required longer than 30-minutes for installation, ranging from 37 to 87 minutes. Also, additional tools were needed that were not listed with manufacturer's installation instructions.
- The DrainPac[™] had a very rigid housing, which caused it to impact the connecting conduits or the rim of the concrete catch basin. Installation was possible in only one of the catch basins in the study area.
- The FlexStorm® had a very rectangular frame, which would not fit within the rounded corners of the catch basin frames. The corners of the CBI were ground down or cut off to allow for installation.

 Catch basins themselves are not always constructed exactly per the ODOT CB-3A standards. The catch basin frame is not always set directly over the concrete casting causing a slight offset. Also, the connecting conduits and underdrains create additional obstructions if they are not cut off flush with the concrete casting. Proper installation of the more rigid-framed CBIs can be impacted by the non-flush construction and conduit intrusions.

Inspection

- Inspection was completed without removing the CBIs from the catch basins.
 Observations were limited to what could be seen through the grate opening, including the presence of debris and standing water.
- Any internal or external parts of the CBIs could not be inspected without removing the CBI from the catch basin.

Maintenance

- In general, the manufacturer recommended maintenance to be performed three to four times per year. The study confirmed this requirement. All of the units required maintenance at least three times during the study.
- Back flushing was conducted on the bags and three of the basket units. Back flushing was not recommended for all the CBIs in the manufacturers' requirements.
- During maintenance, a shop vacuum was used in place of vacuum truck to remove accumulated debris. The volume of debris collected by the shop vac were measured for each unit.

Rainfall

- Most of the CBIs manufacturers did not provide information on the volume or number of storm water events the unit could treat. This is likely due to potential variability in site conditions, including sediment concentrations and loads.
- During the study period 133 events occurred with measurable precipitation, with seventeen rain events exceeding 0.75 inches per day. The total rainfall accumulation for the year was 39.39 inches.

Removal

- Nine of the 15 CBIs were removed within the first seven months of the study due to clogging failure. Failure was determined by standing water observed in the CBI.
- Most of the units were easy to remove and required only one person.
- All of the CBIs needed a grate lifter. Only the Triton™ CBI required additional equipment.
- The Triton™ CBI required extended removal times to remove the tray constructed within the catch basin. Two personnel were required to remove this CBI.
- Five CBI units (two WQS, two Flo-Gard Plus®, and one DrainPac™) remained installed for the entire 12-month study.
- The time to remove the curb throat block and measuring the final volume of material collected was included in the removal times.

5 LAB TESTING

LITERATURE REVIEW

A literature review was conducted to study common methods of evaluating CBIs from a lab testing procedure.

Methods of Evaluating CBIs

To properly evaluate CBIs as a post-construction stormwater BMP, many different criteria can be considered. The lab testing for this research focused on sediment retention and long term performance. The CBI sediment removal rate were compared to the water quality standards and regulations set forth by the Ohio EPA. Evaluation of long term performance and maintenance requirements should also be considered. Other studies have shown that over time, CBIs can become clogged with sediment or saturated with oils, causing the CBIs to lose their ability to effectively treat influent stormwater (Kostaleros et al. 2010). A thorough literature review was conducted to evaluate existing procedures used for testing of CBIs through other studies.

Standard Test Methods

ASTM International (ASTM) D7351, titled *Standard Test Method for Determination of Sediment Retention Device (SRD) Effectiveness in Sheet Flow Applications*, establishes the standardized procedures for evaluating the effectiveness of a SRD in retaining sediment when exposed to sediment-laden sheet flow conditions. While modifications were made to this testing standard to make the testing methodology more applicable to ODOT conditions, the general design of the AU-ESCTF testing apparatus was developed around this model.




Figure 5-1: ASTM D7351 channel schematic (ASTM D7351 2013).

ASTM D5141, titled Standard Test Method for Determining Filtering Efficiency and Flow Rate of the Filtration Component of a Sediment Retention Device, details a standard testing procedure used to determine filtering efficiency and flow rate of the filtration component of a SRD. In this testing method, the filtration component of a SRD is placed vertically or over a horizontal opening at the end of a flume and sediment-laden water is allowed to pass through the filter. The amount of time for the mixture to pass through the filter and the amount of suspended sediment passing through the filter are measured. From this data, the amount of soil retained,

September 2018

filtering efficiency, and flow rate of the SRD are then calculated (ASTM D5141, 2011). This standard is not as detailed as ASTM D7351 and doesn't specify a particular storm event or flow rate, meaning the test method can be modified to simulate different flow and sediment conditions. However, this standard does include measuring for sediment retention of the SRD, which AU-ESCTF used for evaluation of CBI products.

CBI Studies from Controlled Testing Environments

AU-ESCTF reviewed the following references from previously conducted studies on CBIs in controlled testing environments. Review of these studies helped inform our lab testing methods and research plan.

A study performed by *Water Environment Research* (Remley et al. 2005) conducted bench-scale testing of four CBIs (AbTech Ultra Urban Filter®, AquaShield™ I, DrainPac™, Hydro-Cartridge®) using an average flow rate for the 6-month, 30-minute, National Resource Conservation Service (NRCS) Type II storm at typical pollutant loads for a transportation facility. The products were subjected to similar flow rates of 207 to 213 gpm (0.46 to 0.47 ft³/s) and TSS concentrations of 0.027 oz/gal (225 mg/L) for a total of 30 minutes. Influent samples were taken at the 2, 15, 17, and 30-minute marks during each test to ensure consistency. Effluent samples were taken at the 5, 10, 20, and 25 minute marks. Each product underwent 10 tests, with clean CBIs being used for each test, and the samples were averaged for a single effluent value. Analysis for TSS was conducted in accordance with the American Public Health Association (APHA) 2540D standard test method (APHA 2540D 1997) with TSS removal efficiencies ranging between 10 to 42%.

University of Arkansas also conducted lab testing on four products (AbTech Ultra Urban Filter, AquaShield™ II, Hydro-Cartridge, Suntree Technologies™) using similar testing methods. The AquaShield filters used in this study and the last were different CBIs from the same manufacturer. However, the AbTech and Hydro-Cartridge were used in both studies. Each different CBI type was tested five times for a total of 20 tests at influent rates of 0.007 ft³/s and SSC concentrations of 0.022 oz/gal (180 mg/L), with clean CBIs being used for each test. Average SSC removal efficiency ranged from 25 to 62% for the four products (Remley et al. 2005).

Analytical Industrial Research Laboratories tested the sediment removal efficiency of the Aqua-FilterTM Cartridge at a target influent rate of 0.045 ft³/s and target sediment concentrations of 0.013, 0.020, 0.026, 0.040 oz/gal. Prior to testing, 800 gallons of sediment free water was run through the cartridge, removing any possible residual dust from the media and simulating wet operating conditions. Ten simulation tests were performed at each target influent TSS concentration. Tests were run for four minutes for a total of 80 gallons of water per test. It was found that average sediment removal rates were calculated between 78 to 83% for all tests and therefore, influent concentrations had little effect on sediment removal efficiency based upon this test method (NJCAT 2005).

A study from California Polytechnic State University (MacLure 2009) performed bench testing using a DrainPac[™] Filter. The product was inserted in a flume intended to simulate a large-scale catch basin. Pond water was fed to the flume with sediment concentration measured to range between 0.004 and 0.007 oz/gal. Suspended solids removal efficiency was tested at flow rates of 0.045, 0.134, 0.334, and 0.446 ft³/s. For each test, roughly 200 gallons of pond water

was conveyed through the filter before sampling was performed to build up solids in the bottom of the filter, simulating preloading. Three influent and three effluent samples were collected using clean 0.13 gal plastic sample bottles. Influent and effluent samples were taken simultaneously at the spillway prior to the filter and at the concrete channel located after the flume. Average sediment removal efficiency for the different flowrates ranged from 82.9% to 90.9%.

Table 5-1 provides an overview of results obtained from lab testing of CBI TSS removal efficiency for several studies that were reviewed. TSS removal efficiencies varied greatly in some of these studies because of the differences in influent flow rates and concentrations.

Table 5-1 Summary of Previous CBI Lab Testing

	Table 5 1 California 9 51 10 10 ab 521 Lab 10 cang				
Study	# of Products	Influent Flow Rate [ft³/s]	Influent Concentration [oz/gal (mg/L)]	TSS Removal Efficiency Ranges (Average)	
Morgan et al. 2003	4	0.46-0.48	0.030 (225)	10-42% (29.5%)	
Remley et al. 2005	4	0.46	0.024 (180)	25-62% (48.3%)	
NJCAT 2005 (AIRL)	1	0.04	0.013-0.040 (100-300)	78-83% (80.5%)	
MacLure 2009	1	0.045-0.45	0.004-0.007 (30-50)	83-91% (86.6%)	

OVERVIEW OF LAB TESTING PLAN

The Auburn University Erosion and Sediment Control Test Facility (AU-ESCTF) tested the performance of CBI products with influent flow rates and volumes based upon design requirements specified in ODOT's L&Dv2 (ODOT, 2017). The lab testing plan used to accomplish this was two-phased: (1) performance evaluation testing and (2) longevity testing.

During performance evaluation testing, each CBI was tested at a low, medium, and high flow rates for a period of 70 minutes using two different soil types. The performance of each CBI was evaluated to determine whether the product captured 80% of the sediment introduced. Each test was performed using a new CBI unit. The first soil type was an OK110 silica sand, used in accordance with ODOT Supplemental Specification 995 (SS995) "Precast Water Quality Structure" (ODOT, 2012), and the second soil type was a United States Department of Agriculture (USDA) classified sandy loam soil that corresponds to standards specified in the "Technology Acceptance Reciprocity Partnership: Protocol for Stormwater Best Management Practices Demonstrations" (TARP) (TARP, 2003). Sediment retention was measured to determine each CBI's performance.

The purpose of longevity testing was to determine the CBI's ability to maintain structural integrity and sediment removal performance over a more strenuous testing cycle. Longevity testing consisted of multiple consecutive tests on a single installed CBI. The flow rates for the tests were at the maximum flow rate that the CBI was capable of providing 80% sediment retention determined from the performance evaluation test. Sediment retention percentage was calculated for each individual test, as well as cumulatively across all longevity tests. The

longevity testing cycle continued until it was determined that the CBI would not be able to provide 80% sediment retention or until the CBI failed structurally. The longevity testing methodology provides a representative understanding of how many storm events the CBI can withstand without maintenance or removal in the field, while still satisfying water quality standards. Similar to the methods used in performance evaluation testing, sediment retention was measured to determine each CBI's longevity performance.

DETERMINATION OF FLOW CHARACTERISTICS

L&Dv2 Section 1115 specifies that pre-manufactured, post-construction BMPs should be designed according to the runoff flow rate resulting from a 0.65 in/hr storm event over the drainage area associated with the catch basin under consideration. Water quality flow (WQ_i) is calculated by the rational equation, found in L&Dv2 Section 1101.2.2, which specifies:

$$WQ_f = kCiA (5-1)$$

WQ_f = Water Quality Flow (ft³/s) k = unit conversion factor (1.0)

C = Coefficient of Runoff (0.9 for impervious)

i = Rainfall Intensity (in/hr)

A = Contributing Drainage Area (acre)

"k" is a unit conversion factor, usually taken as 1.0 for standard units. While the coefficient of runoff (i.e., 0.9 for impervious areas) and rainfall intensity, 0.65 in/hr, are specified by L&Dv2, an appropriate drainage area must be selected to determine the flow rate that CBI products are expected to treat based upon ODOT typical conditions (Equation 5-1). An examination of ODOT field installation sites concluded that typical drainage areas contributing runoff to catch basins ranged from approximately 0.10 to 0.25 acres. As a result, it was determined that each CBI would be evaluated at three different flow rates, representative of a small drainage area of 0.1 acre, medium drainage area of 0.2 acre, and large drainage area of 0.3 acre. Flow rates associated with the small, medium, and large drainage area according to the rational equation can be found in Table 5-2Table 5-3.

While L&Dv2 does not specify that pre-manufactured, post-construction BMPs be designed to manage a water quality volume (WQ $_{v}$), Ohio EPA's CGP specifies that "Alternative Post-Construction BMPs" could be used in place of BMPs typically used to treat stormwater runoff volumes with the requirement that the BMPs be able to treat the water quality volume (WQ_{v}) discharge rate (OHIO EPA, 2013). Therefore, the water quality volume calculation method (Equation 5-2) was used to determine the total volume of water and flow durations for each test. WQ_{v} was calculated according to the following equation as specified in L&Dv2:

$$WQ_{V} = \frac{PAC_{q}}{12} \tag{5-2}$$

WQ_V = Water Quality Volume (acre-feet)

P = Precipitation (0.75 in.)

A = Contributing Drainage Area (acre)

C_q = coefficient of runoff (0.9 for Impervious Drainage Areas)

Catch Basin Inserts for Ohio Roadways

 WQ_v can be divided by WQ_f to determine the duration for each test. This will ensure that each practice is exposed to an adequate amount of runoff volume to determine overall performance. Table 5-2 summarizes the water quality flow rate, water quality volume, and duration of testing for each of the proposed drainage areas.


Table 5-2 Summary of Drainage Areas and Corresponding Testing Flow Rates and Volumes

Drainage Area	Drainage	Flow	Volu	ıme	Duration
Size	Area [ac. (ha)]	Rate [ft ³ /s]	[acre-ft (m ³)]	[ft ³ (m ³)]	[min]
Small	0.1 (0.04)	0.06	0.00579 (7.14)	252 (7.14)	70
Medium	0.2 (0.08)	0.12	0.01157 (14.27)	504 (14.27)	70
Large	0.3 (0.12)	0.18	0.01736 (21.41)	756 (21.41)	70

SEDIMENT INTRODUCTION

CBIs were tested using two different soil types. First, CBIs were tested in accordance with ODOT Supplemental Specification 995 (SS995) "Precast Water Quality Structure", which specifies a laboratory test influent concentration of 0.028 lb/ft³ (450 mg/L) while using an OK110 particle distribution with a specific gravity of 2.65 or less (ODOT, 2012). This influent concentration can be multiplied by the volume of water used during each test for the small, medium, and large drainage areas resulting in total sediment loads of 7.08, 14.16, and 21.24 lb., respectively.

CBIs were also tested using a United States Department of Agriculture (USDA) classified sandy loam soil type that corresponds to standards specified in the "Technology Acceptance Reciprocity Partnership: Protocol for Stormwater Best Management Practices Demonstrations" (TARP) (TARP, 2003). TARP specifies that the sandy loam soil be introduced at a target concentration of 0.012 lb/ft³ (185 mg/L). Over the duration of a test, this concentration results in target loads of 2.91, 5.82, and 8.73 lb, respectively. To obtain the required particle size distribution to meet the TARP standards, soil was taken from an onsite stock pile at the AU-ESCTF. The soil was sifted to separate larger sand particles from finer silt and clay particles, and then mixed together at the appropriate ratio to create a particle size distribution which met the sandy loam classification. The soil sifting and mixing process is illustrated in Figures 5-2(a-d) below.





(d) seperated soils Figure 5-2: Soil mixing process.

To determine the gradation of the mixed soil, a wet sieve analysis was conducted to determine the ratio of sands to fines. A sample of the fines were then collected and used to perform a hydrometer analysis, further determining the ratio of silt to clay particles. The final distribution of the mixed soil was determined to be 64% sand, 27% silt, and 9% clay. Using the USDA soil classification triangular chart, seen in Figure 5-3, we can verify that this distribution does meet the required classification of a sandy loam.





Figure 5-3: USDA soil classification triangular chart. (NRCS Soils, 2018)

To compare the two soil types, the opposing particle size distribution curves for each soil can be seen in Figure 5-4(a). While the OK110 silica sand is primarily composed of sand particles ranging in diameter from 100-200 microns, the sandy loam soil is much more diverse, and contains clay particles, which can cause filtration materials to become clogged, or blinded, affecting sediment removal performance. This also is supported by Figure 5-4(b) and Figure 5-4(c). Particle sizes range greatly in the sandy loam soil, whereas there is little difference in particle size in the OK110 silica sand. By testing CBIs with both soil types, we gained a greater understanding of how the products will perform under different sediment loading conditions.






Figure 5-4: Comparison of soil types used for testing.

EQUIPMENT AND METHODOLOGY

The construction of the CBI testing apparatus consisted of three primary components that included the water and sediment introduction system, flow conveyance system, and the discharge platform. Figure 5-5 provides the schematic design of the testing apparatus and major

components. Figure 5-6 provides photographs of individual components of the testing apparatus.




Figure 5-5: Schematic of CBI testing apparatus.



(a) water and sediment introduction system



(b) sediment introduction zone




(c) Schenck Process Model 106M Material Feeder



(d) flow conveyance and transition point



(e) discharge and test platform



(f) catch basin grate



(g) effluent collection platform Figure 5-6: Catch Basin Insert (CBI) testing apparatus.

Water and Sediment Introduction System

Water is pumped from an on-site supply pond into a water equalization tank located at the upstream end of the apparatus, shown in Figure 5-6(a). To ensure that the water provided by the on-site supply pond had no impact on the lab testing process, water quality samples were taken from the pond at different times throughout each test. This allowed the research group to

remove any test in which the supply water was deemed higher than the acceptable standard. However, this was also avoided through careful planning of when to run tests based upon the visual quality of the supply pond. Average concentrations from pond samples were below 0.001 lb/ft³ (20 mg/L). The water equalization tank is equipped with a calibrated, 90-degree, V-notch weir that allows for controlled discharge into the flow conveyance system by adjusting drainage valves to maintain the water level in the tank at a desired depth. Effective head, or depth according to the weir, can be calculated according to Equation 5-3.

$$h_{e} = \frac{Q}{4.27997C} \times 12 \tag{5-3}$$

 h_e = effective head, in.

Q = flow rate, ft^3/s

C = discharge constant (0.578)

Using Equation 5-3, the calculated effective heads for each of the three flow rates are 2.71, 3.58, and 4.21 in., respectively. These effective heads were verified using timed flow capture to further calibrate and validate the desired discharges.

The V-notch weir discharges into a 6-inch polyvinyl chloride (PVC) flow conveyance system. Just downstream of the water introduction point, a vertical tee is placed in the flow conveyance system that allows for the introduction of sediment into the flow, shown in Figure 5-6(b).

A Schenck AccuRate® series auger type volumetric feeder with a 0.75 in. diameter helix and a 0.25 ft³ hopper was used for sediment introduction, which is shown in Figure 5-6(c). This system is equipped with a three-digit thumbwheel speed potentiometer for enhanced repeatability that provides a consistent and accurate means of sediment introduction. The auger discharges into the flow conveyance system through a pre-drilled hole placed on the vertical tee end cap that was used to protect falling sediment from being disrupted by wind.

Flow Conveyance System

The flow conveyance system consists of 20 ft in length by 6 in. inside diameter PVC pipe laid at a 2% slope that conveys sediment-laden water from the upstream introduction point to the drainage platform, as shown in Figure 5-6(d). A transition point was constructed in the middle of the flow conveyance system to produce turbulent flow for the sediment-laden water and cause soil particles to mix more evenly.

Discharge Platform

The discharge platform was constructed on a stable and level area so that influent would spread evenly across the platform. The lower support frame was then constructed using treated 4 \times 4 lumber with treated 2 \times 4 lumber as cross-bracing. The manufactured ODOT CB-3A frame was then placed on top of the lower support frame, and the upper platform was constructed around the catch basin frame. The upper platform consists of two 4 ft \times 8 ft \times 0.75 in. plywood sheets to create an 8-foot by 8-foot surface. The plywood was installed at a 2% slope both in the downstream direction and toward the middle of the platform to direct sheet flow into the catch basin from the discharge point of the flow conveyance system. The 2% slope was selected to be representative of a typical roadway cross-sectional slope. Additional plywood was installed at a location similar to the slope of the catch basin frame to simulate the curb.

The platform was then sealed with silicon caulking and covered with a rubber sealant material. The platform was sprayed with a LINE-X® coating to provide a watertight seal. Finally, 14-gauge sheet metal was placed on top of the platform as a finished surface that would allow influent to flow as sheet flow into the catch basin without causing disturbances that could result in sediment falling out of suspension prematurely. Edges and corners were again sealed with silicone caulking to prevent leaking. The completed drainage platform is pictured in Figure 5-6(e).

A 6 in. PVC coupling was placed at the upstream side of the drainage platform. This allows the operator to change the length of pipe based upon the flow rate that the test is being performed at, as seen in Figure 5-7. For low flow rate tests, the flow conveyance pipe is extended closer to the catch basin, and for high flow rate tests, the conveyance system ends at the coupling, and no additional piping is used. The purpose of this adjustment is to ensure flow enters the catch basin grate at a consistent velocity across all three flow rates and prevent particles from falling out of suspension on the platform prematurely due to slowed velocity. Modifications were also made to the system to allow water to be directly discharged into the inlet opposed to influent sheet flow. Direct discharge modifications can be seen in Figure 5-7(d).



(a) low flow rate

(b) medium flow rate



(c) high flow rate

(d) direct discharge

Figure 5-7: Modifications to flow conveyance system based on flow rate.

PERFORMANCE EVALUATION OF CBIS

The primary focus of the CBI testing was to characterize performance by quantifying sediment removal efficiency by measuring the percentage of sediment captured in the CBI (Equation 5-4). Prior to installation, the CBI's pre-test weight was determined to compare to the post-test weight of the CBI and captured sediment. Each product was installed based upon manufacturer installation protocols. Upon completion of the test, the saturated CBI is placed in an industrial

oven at approximately 217°F for at least 12 hours to ensure that all moisture was removed from the sediment or the filter media. The weight of the sediment introduction system was also recorded before and after the test so that the amount of sediment introduced could be determined. Any lost sediment that may have fallen out of suspension on the platform during sheet flow testing prior to entering the inlet was also collected and allowed to dry in the oven for at least 12 hours before being weighed and accounted for as lost sediment.

$$SRE = \frac{(A-B)}{(C-D-E)}$$
 (5-4)

SRE = sediment removal efficiency, %

A = weight of CBI, post-test, lb B = weight of CBI, pre-test, lb

C = weight of sediment introduction system, pre-test, lb
 D = weight of sediment introduction system, post-test, lb

E = weight of lost sediment, lb

During each test, photo and video documentation was also performed to capture important flow characteristics. Photo documentation was performed from predetermined and ad hoc locations to visually show pre- and post-test conditions.

LAB RESULTS

Performance Evaluation Testing

The following section discusses the installation, testing, and performance of each CBI based upon performance testing. Each product was tested at the low, medium, and high flow rates of 0.06, 0.12, and 0.18 ft³/s. Target sediment introductions for the low, medium, and high tests were 7.08, 14.16, and 21.24 lb for OK110 tests and 2.91, 5.82, and 8.73 lb for sandy loam tests.

A common issue observed during many of the tests was that a majority of the products allowed water to bypass the treatment material. Many of the products did not fit tightly to the catch basin frame, allowing some influent to bypass the entire product, and hindering treatment potential. Because of this, the testing was modified to the direct discharge method, which forced the influent directly into the CBI, eliminating potential for bypass. Figure 5-8 provides an example of the bypass allowed during sheet flow testing compared to that allowed during direct discharge testing. Figure 5-8(a) shows the water bypassing the CBI by flowing down the outside of the device during sheet flow testing. Figure 5-8(b) shows only water flowing out of the bottom of the device during direct discharge testing. While the WQS is shown as an example, all CBI products except the Triton™ experienced similar issues and had some volume of water bypassing due to the lack of a watertight seal between the CBI frame and the catch basin frame. The bypass volume varied between these units, depending on the CBI's frame and fit, but was not quantified.



(a) sheet flow (b) direct discharge Figure 5-8: Bypass allowed between discharge methods.

Summary of Performance Evaluation Testing

Table 5-3 summarizes all sediment retention percentage data for all performance evaluation tests. It can be seen that the Adsorb-It™ exceeded the 80% target removal rate multiple times, while other products failed to exceed the threshold. However, the FlexStorm®, Storm Sentinel®, Gullywasher©, and DrainPac™ nearly met the target threshold, with sediment retention values reaching above 70% for one of the low flow tests.

Table 5-3 Summary of Sediment Retention Percentage of Performance Evaluation Testing

	Sheet Flow OK110		Direct Discharge OK110		Direct Discharge Sandy Loam				
Product Name	0.06 ft ³ /s	0.12 ft ³ /s	0.18 ft ³ /s	0.06 ft ³ /s	0.12 ft ³ /s	0.18 ft ³ /s	0.06 ft ³ /s	0.12 ft ³ /s	0.18 ft ³ /s
Adsorb-It™	77.2	64.4	48.7	96.2	82.5	64.3	85.4	64.2	50.5
DrainPac™	36.0	46.1	47.1	79.8	64.8	62.7	68.1	46.8	38.4
FlexStorm®	51.2	56.8	46.5	71.3	50.2	36.3	65.4	58.3	43.9
Flo-Gard Plus®	7.3	1.0	0.7	10.4	0.8	2.2	24.7	19.8	22.0
Gullywasher©	75.8	58.8	41.0	67.1	47.8	35.7	51.7	38.1	33.4
Storm Sentinel®	59.2	41.0	21.7	71.3	38.5	26.0	41.6	30.1	20.3
Triton™	59.4	49.0	45.2	68.5	59.7	44.9	40.4	38.4	36.4
WQS	2.7	27.3	26.8	27.1	51.4	53.9	42.7	49.4	50.5

A multiple linear regression was conducted to determine the relative impact that each of the four variables (e.g., product, discharge method, soil type, flow rate) has on sediment retention, independent of other factors. This analysis helped to isolate the impacts influencing factors (i.e., independent variables) had on sediment retention and to explain the relationship between the dependent variable and independent variables. The dependent variable selected for the analysis was the sediment retention value associated with each test.

September 2018

The detailed discussion and results of the statistical analysis of the sediment retention data are provided in Appendix C. In summary, the following conclusions can be drawn from these analyses.

- 1. The Adsorb-It[™] retained sediment at a statistically significant higher rate than any of the other CBI products, while the Flo-Gard Plus® retained sediment at a statistically significant lower rate than any of the other CBI products.
- 2. CBIs exhibited a statistically significant decrease in sediment retention as flow rates increased, suggesting that CBIs are more effective in smaller drainage areas, which tend to contribute lower flows. Higher flow rates also led to more overflow conditions of the CBIs, thus bypassing treatment.
- 3. The direct discharge test method showed a statistically significant increase in sediment retention over the sheet flow method. This supports the observation that most of the CBIs did not create a water tight seal between the CBI frame and the catch basin frame. During testing, runoff leaked through this space and was not filtered (or treated) through the CBI.
- 4. While the data do show that there was a small decrease in sediment retention between tests with sandy loam compared to tests with the OK110 silica sand, there was not a statistically significant difference.

LONGEVITY TESTING

Longevity testing was performed to better understand the performance characteristics of the products over time. Based upon performance testing it was determined that the low flow rate of 0.06 ft³/s would be used to test the products for longevity because, with the exception of the Adsorb-It™, no CBI successfully captured 80% of the introduced sediment at the 0.12 ft³/s or 0.18 ft³/s flow rates. Therefore, target sediment introductions for the tests were 7.08 lb. for OK110 tests and 2.91 lb. for sandy loam tests. As with the performance testing, sediment capture was determined by pre- and post-test weight of the dried CBI. However, since the purpose of longevity testing is to determine temporal performance, pre- and post-test weights were determined for each longevity test, providing both an individual and a cumulative sediment retention for each CBI tested. Table 5-4 and Figure 5-9 are presented to show the overall performance of each CBI product. Furthermore, figures with graphs showing the trends in the weight of sediment introduced, captured, and bypassed during the longevity tests are included in Appendix C. For example, when evaluating the graphs, the difference between the sediment introduction line and the sediment captured line will determine sediment capture performance over time. This is determined by the difference in the lines increasing or decreasing over time. If the difference increases, sediment retention decreases over time and vice versa. This distance is also equivalent to the value of the sediment bypassed line shown on each graph, which shows the amount of sediment bypassing, or not being captured, by the products. Appendix C contains additional detailed testing results for each CBI.

Summary of Longevity Testing

Table 5-4 summarizes all sediment retention percentage data for all longevity tests. The DrainPac[™] was tested eight consecutive times with OK110 silica sand. While individual tests values varied, it can be seen that there was a gradual decrease in cumulative retention rate from test to test. Despite this performance, the DrainPac[™] was only tested twice with the sandy

loam due to low retention rates. The Adsorb-It™ performed similarly to the performance evaluation testing, having the highest retention values of all CBIs. While most products were tested at least twice to ensure that they were not meeting the 80% target rate, the Flo-Gard Plus® was only tested once per soil type due to its low performance, both during the first longevity test (i.e., L1) tests and the performance evaluation testing.

Table 5-4 Summary of Sediment Retention Percentage of Longevity Tests

Indiv. Soc. Soc.		(a)	Longev	ity Tests	with OK	110 Silica	Sand			
Adsorb-It™ Cumul.								L6	L7	L8
DrainPac™	Adaarb I+TM	Indiv.	95.6%	88.4%	72.4%	55.7%	-	-	-	-
DrainPac™ Cumul. - 80.9% 76.7% 77.0% 69.7% 69.8% 68.5% 68.0%	Adsorb-It***	Cumul.	-	92.0%	85.7%	78.9%	-	-	-	-
FlexStorm® Indiv. 88.3% 64.5% 58.8% 31.2% - - - - - - - - -	Due in Dee TM	Indiv.	80.0%	81.7%	68.4%	78.1%	40.6%	70.5%	60.7%	64.3%
FlexStorm®	DrainPac ····	Cumul.	-	80.9%	76.7%	77.0%	69.7%	69.8%	68.5%	68.0%
Flo-Gard Plus8	Fl	Indiv.	88.3%	64.5%	58.8%	31.2%	-	-	-	-
Flo-Gard Plus®	FlexStorm®	Cumul.	-	76.8%	71.1%	61.3%	-	-	-	-
Cumul. - - - - - - - - -	Fla Caral Division	Indiv.	2.3%	-	-	-	-	-	-	-
Gullywasher® Cumul. - 70.4% 64.2% -	FIO-Gard Plus®	Cumul.	-	-	-	-	-	-	-	-
Storm Indiv. 46.2% 44.1% -	.	Indiv.	75.9%	64.9%	50.8%					
Sentinel® Cumul.	Gullywasner©	Cumul.	-	70.4%	64.2%					
Sentinel® Cumul. - 45.2% -	Storm	Indiv.	46.2%	44.1%	-					
Triton™		Cumul.	-	45.2%	-					
MQS		Indiv.	66.2%	20.8%	14.2%					
Cumul. - 48.7%	I riton 1 M	Cumul.	-	42.8%	33.2%					
Cumul. -		Indiv.	41.9%	55.3%						
Adsorb-It™ Indiv. Cumul. 86.8% 49.8% 53.6% 53.8% -	WQS	Cumul.	-	48.7%						
Adsorb-It™ Indiv. 86.8% 49.8% 53.6% 53.8% - <		(k) Longe	vity Tests	with Sa	ndy Loar	n Soil			
DrainPac™ Cumul.			L1	L2	L3	L4	L5	L6	L7	L8
DrainPac™ Indiv. 60.3% 45.5% - - - - - - - - -	Adearh ItTM	Indiv.	86.8%	49.8%	53.6%	53.8%	-	-	-	-
DrainPac™ Cumul. - 53.0% - <t< td=""><td>Ausorb-It ····</td><td>Cumul.</td><td>-</td><td>68.4%</td><td>63.5%</td><td>61.6%</td><td>-</td><td>-</td><td>-</td><td>-</td></t<>	Ausorb-It ····	Cumul.	-	68.4%	63.5%	61.6%	-	-	-	-
FlexStorm®	DrainBaoTM	Indiv.	60.3%	45.5%	-	-	-	-	-	-
Cumul. -	Diamir ac ····	Cumul.	-	53.0%	-	-	-	-	-	-
Flo-Gard Plus® Indiv. 18.0% - - - - - - - - -	Elay Ctarm®	Indiv.	64.8%	49.7%	-	-	-	-	-	-
Flo-Gard Plus® Cumul. - <	riexStoffile	Cumul.	-	57.0%	-	-	-	-	-	-
Gullywasher®	Fla Card Diva	Indiv.	18.0%	-	-	-	-	-	-	-
Gullywasher® Cumul. - 46.9% -	Fio-Gard Plus®	Cumul.	-	-	-	-	-	-	-	-
Storm Indiv. 41.6% 36.0% - - - - - - - - -	0	Indiv.	53.1%	39.8%	-	-	-	-	-	-
Storm Indiv. 41.6% 36.0% -	Gullywasner©	Cumul.	-	46.9%	-	-	-	-	-	-
Sentinel® Cumul. - 38.8% -	Storm	Indiv.				-	-	-	-	-
Triton TM Indiv. 66.7% 48.8% - - - - - - - - -			-		-	-	-	-	-	-
Cumul. -			66.7%		-	-	_	-	-	-
WOS Indiv. 62.7% 55.7%	Triton™		-		_	_	_	_	_	-
WOS			62.7%		-					
Cuiliui. - 59.2% - - - - - -	WQS	Cumul.	-	59.2%	_	_	_	_	_	-

September 2018

Figure 5-9 plots cumulative retention percentages for each CBI throughout their respective longevity testing tenure. It can be seen that, on average, CBIs were able to endure more longevity tests when using the OK110 silica sand than when using the sandy loam soil, despite the fact that the OK110 silica sand was introduced at higher concentrations. This would suggest that CBIs subjected to sandy soils might require less maintenance in the field since performance capabilities were sustained longer than with loamy soils. This is most likely due to the higher clay content in the sandy loam soil causing the filter material to become blinded, hindering flow-through ability and performance by clogging the pore passages of the CBI media. For most CBIs, sediment retention percentage was also higher through the first few tests with OK110 silica sand than with sandy loam soil, indicating that the larger sized sand particles in the OK110 silica sand were easier to capture than the smaller silt and clay particles in the sandy loam soil.




Figure 5-9: Longevity Testing Summary of Cumulative Retention Data

The lab testing conducted provides an in-depth analysis of how the selected CBIs will perform in terms of both sediment removal and need for maintenance over time. The results provided in this section, paired with the data collected during the field testing phase of the project, can be combined to make final recommendations on the performance on each of the products.

6 GENERAL LABORATORY CONCLUSIONS

Lab Testing Methodology

- The overall design of the lab testing was conducted in accordance with the ODOT L&Dv2 flow rate and volume requirements.
- During performance evaluation tests, CBIs were tested at three different influent flow rates of 0.06, 0.12, and 0.18 ft³/s for 70 minutes, representative of drainage areas of 0.1, 0.2, and 0.3 acres.
- CBIs were also tested using two different soil types, an OK110 silica sand gradation introduced at a target concentration of 0.028 lb/ft³ (450 mg/L), and a sandy loam introduced at a target concentration of 0.012 lb/ft³ (185 mg/L).
- Sediment retention within the CBIs was measured to determine each CBIs performance.
- Longevity testing consisted of multiple consecutive tests on a single installed CBI and were conducted using each soil type at the low flow rate. Sediment retention percentage was calculated for each individual test, as well as cumulatively across all longevity tests.
- The longevity testing cycle continued until it was determined that the CBI was no longer capable of reaching the 80% sediment retention percentage during an individual test event or until the CBI failed structurally.
- Originally, CBIs were tested with the OK110 silica sand under sheet flow conditions.
 Most CBIs exhibited a leak between the CBI frame and the catch basin frame. So, flow introduction methods were adapted to directly discharge the sediment-laden influent into the catch basin to minimize flow bypass potential. CBIs were then tested with both soil types under the direct discharge testing method.

Lab Performance Evaluation Testing Results

- Most products failed to meet the 80% sediment retention criterion. However, the Adsorb It™ did capture above 80% sediment for both soil types and at multiple flow rates. The
 DrainPac™ reached 80% retention when tested with OK110 sand at the low flow rate
 under direct discharge conditions, but did not reach the target for other tests.
- The Adsorb-It[™] retained sediment at a statistically significant higher rate than any of the other CBI products, while the Flo-Gard Plus® retained sediment at a statistically significant lower rate than any of the other CBI products.
- CBIs exhibited a statistically significant decrease in sediment retention as flow rates increased, suggesting that CBIs are more effective in smaller drainage areas, which tend to contribute lower flows. Higher flow rates also led to more overflow conditions of the CBIs, thus leading to bypassing treatment.
- The direct discharge test method showed a statistically significant increase in sediment retention over the sheet flow method. This supports the observation that most of the CBIs did not create a water tight seal between the CBI frame and the catch basin frame. During testing, runoff leaked through this space and was not filtered (or treated) through the CBI.
- While the data do show that there was a small decrease in sediment retention between tests with sandy loam compared to tests with the OK110 silica sand, there was not a statistically significant difference.

Gresham, Smith & Partners – Columbus GS&P Project: 42299.00 ODOT PID 103684

September 2018

Analysis of performance evaluation tests concluded that, for most products, long periods
of overflow were likely to result in reduced retention efficiencies of CBIs.

Longevity Testing Results

- Six of the eight CBIs did not perform well enough during the first and second longevity tests to justify further longevity testing, suggesting that these products are incapable of providing the sediment retention needed to meet standard requirements.
- Sediment retention performance degraded with multiple simulated storm events. The
 cumulative sediment retention was less than 80% by the fourth test for the Adsorb-It™,
 by the third test for the DrainPac™, and by the second test for the FlexStorm®.
- Most products performed better during longevity testing with OK110 silica sand than with sandy loam soil. It is expected that the higher clay content in the sandy loam caused filter media to blind after repeated tests.

7 CONCLUSION

The goal of this research was to test the performance and maintenance requirements of a variety of CBIs available on the market in order to assess the viability of CBIs as acceptable alternative BMPs which ODOT could incorporate into the L&Dv2 BMP toolbox. To meet the research criteria, each CBI was required to achieve 80% sediment retention and be able to be installed in a standard ODOT CB-3A. None of the CBIs tested met both conditions.

Eight CBI products were evaluated in lab and field settings to accomplish this research goal. The field testing assessed the installation, maintenance, and removal needs of the CBIs during the 12-month monitoring period. The laboratory testing measured the CBIs sediment retention for two soil types (i.e., silica sand and sandy loam).

The field testing installed the CBIs in existing ODOT CB-3As at two locations. Fifteen CBI products were installed in the field at two site locations. One CBI product could not be installed at both locations, it was only installed at Site 1. The CBIs were assessed on installation, maintenance, and removal over a one year duration.

Of the eight CBIs evaluated, only the Triton™ could be installed in the CB-3A without requiring modifications to the curb inlet of the standard catch basin. All stormwater that entered into the standard catch basin could be treated by the Triton™. All other CBIs require installation within the grate of the catch basin, allowing any water captured by the curb "throat" opening to bypass the CBI. The catch basins required a throat block to divert the stormwater into the grate and allow it to be collected entirely. Intentionally blocking the curb throat opening was allowed by ODOT for this study only, but would not otherwise be considered an acceptable practice. All of the units required maintenance over the duration of the study with the first occurring within one to three months of installation. Five CBI units (two WQS, two Flo-Gard Plus®, and one DrainPac™) remained installed for the entire 12-month study. Nine of the 15 units were removed within the first seven months.

Laboratory testing exposed the CBI products to influent flow rates and durations to properly simulate field-like conditions during large-scale lab testing. Under these conditions, the CBIs performance in capturing 80% of the sediment introduced was analyzed. Both sandy loam and OK110 soil types were evaluated in the testing.

For the sediment retention criteria, the DrainPac[™] and Adsorb-It[™] both met 80% sediment retention at one or more flow variations within the lab testing. However, the remaining units fell below this threshold. During longevity testing, sediment retention rates decreased with repeated back-to-back simulated storms, falling below 80% within as many as four tests and as few as two tests.

The lab and field testing allowed for a comparable basis between each CBI, as well as an individual evaluation of each unit's performance. Key factors in evaluating performance in the field were the installation process, maintenance needs, and duration in the field before failure. Lab testing was evaluated on the unit's ability to meet the 80% sediment retention requirement for the two soil types. Table 7-1 below summarizes the results from the field and lab testing to allow for a complete summary of each CBI's performance.

Table 7-1 CBI Overall Results Summary

Product Name	Installed in CB Without Modification	Duration in Field Before Maintenance (Months)	Duration in Field Before Failure (Months)	80% Sediment Retention OK110 Silica Sand	80% Sediment Retention Sandy Loam Soil
Adsorb-It™	No	2	6	Yes ¹	Yes ²
DrainPac™	No	5	12	Yes ²	No
FlexStorm®	No	2	7	No	No
Flo-Gard Plus®	No	5	12	No	No
Gullywasher©	No	1.5	6	No	No
Storm Sentinel	No	1.5	6	No	No
Triton™	Yes	2	8.5	No	No
WQS	No	5	12	No	No

^{80%} sediment retention met for direct discharge, low flow rate (0.06 ft³/s) and medium flow rate (0.12 ft³/s) only. 80% sediment retention met for direct discharge, low flow rate (0.06 ft³/s) only.

Although the research selection criteria were met individually by some of the CBIs evaluated, none of the CBIs met both of the requirements. The two CBIs that met the sediment retention targets for any of the flow rates (i.e., Adsorb-ItTM and DrainPacTM) showed that within as many as four simulated storm events, the CBIs fell below the 80% threshold. This relatively quick drop in performance suggest the units would require frequent maintenance or replacement to continue meeting the sediment retention requirement. The field testing supported these longevity testing results, requiring frequent maintenance— the Adsorb-ItTM in as little as two months and the DrainPacTM an average of quarterly—based on the CBIs showing clogging with standing water. As demonstrated in the longevity testing, actual maintenance is likely needed even more frequently than conducted in the field testing to keep CBIs performing at or above 80% sediment retention (i.e., every two to four precipitation events). With the potentially large number of CBIs that would be required to address post-construction stormwater BMPs, this represents a significant maintenance burden from a practical standpoint.

Seven of the eight CBIs required the curb inlet of the standard catch basin CB-3A to be blocked. This modification does not align with ODOT's drainage design standards due to the significant reduction in flow capacity and increased risk of roadway flooding.

Based on the criteria established for this study, none of the units tested appear to be a viable option as a post-construction stormwater BMP within ODOT's L&Dv2 manual.

Catch Basin Inserts for Ohio Roadways

Appendix A Literature Review

APPENDIX A

Title:	On the Efficiency of Catch Basin Inserts for Stormwater Runoff Treatment
Publisher/Sponsor:	11th International Conference on Urban Drainage
Author(s):	Berretta, C., Gnecco, I., Molini, A., Palla, A., Lanza, L. G., and La Barbera, P.
Publication Date:	2008
Content and Focus:	Studied two industrial sites with CBIs. Using the data collected, they extrapolated future performance to determine how long these practices will be adequately functional. At the time of the publication, the study was still ongoing and little data was presented on reductions and performance longevity.
Url:	https://www.researchgate.net/publication/228506754 On the efficiency of catch basin inserts for storm water runoff treatment

Title:	An Evaluation of Storm Drainage Inlet Devices for Stormwater Quality Treatment
Publisher/Sponsor:	Water Environment Federation Technical Exposition and Conference
Author(s):	Field, R. and Pitt, R.
Publication Date:	1998
Content and Focus:	Evaluated two CBIs and one conventional catch basin inlet with a sump. Their findings showed some significant improvements in water quality using the conventional sump, but limited water quality improvements from the CBIs
	The median removal rates were about 30% for suspended solids, about 40% for turbidity, about 15% for color, and about 20% for total solids. No other pollutants were found to be significantly reduced. However, the coarse screened inlet device was found to significantly reduce the discharges of trash and other large debris. Unfortunately, flows passing through trapped material caught on the screen had increased concentrations of suspended solids and volatile solids, probably due to washing of decomposing large organic material through the screen.
Url:	https://cfpub.epa.gov/si/si_public_record_report.cfm?dirEntryId=100340

Title:	Catch Basins and Inserts for the Control of Gross Solids and Conventional Stormwater Pollutants
Publisher/Sponsor:	Critical Transitions in Water and Environmental Resource Management, American Society of Civil Engineers
Author(s):	Field, R. and Pitt, R.
Publication Date:	2004
Content and Focus:	This presentation summarizes the results from past and recent studies of catch basin inlet devices, and recommend important features to optimize their performance. Case studies are also presented, summarizing two EPA-funded projects that examined catch basins and insert performance. While many types of inlet devices may capture some stormwater debris, care must be taken in their design. Catch basins with sumps may remove up to about 30% of suspended loads that enter the inlet, but much of this material is relatively coarse and in many cases would not have moved to the outfall.
Url:	http://ascelibrary.org/doi/abs/10.1061/40737%282004%2957

Title:	Catch Basins and Inserts for the Control of Gross Solids and Conventional Stormwater Pollutants
Publisher/Sponsor:	Critical Transitions in Water and Environmental Resource Management, American Society of Civil Engineers
Author(s):	Field, R. and Pitt, R.
Publication Date:	2004
Content and Focus:	Reported 30% removal of suspended loads; however, they noted much of these loads were coarser material that likely would accumulate in the sewer system and actually reach the outfalls. They provided recommendations on desirable characteristics for CBIs, including: • Does not cause flooding when it clogs with debris;
	 Does not force stormwater through the captured material;
	 Does not have adverse hydraulic head loss properties;
	Maximizes pollutant reductions; and
	Requires inexpensive and infrequent maintenance.
Url:	http://ascelibrary.org/doi/abs/10.1061/40737(2004)57

Title:	Mass Loading of First Flush Pollutants with Treatment Strategy Simulations
Publisher/Sponsor:	TRR – Journal of the Transportation Research Board
Author(s):	Kayhanian, M. and Stenstrom, M. K.
Publication Date:	2005
Content and Focus:	Evaluated theoretical pollutant load reductions through simulations of CBI performance. The research results showed that treating the initial (first flush) pollutant loads was more beneficial than treating 20% of the entire runoff form the precipitation event.
Url:	http://trrjournalonline.trb.org/doi/10.3141/1904-14

Title:	Field Study of Catch Basin Inserts for the Removal of Pollutants from Urban Runoff
Publisher/Sponsor:	Water Resources Management (WATER RESOUR MANAG)
Author(s):	Kostarelos, K., Khan, E., Callipo, N., Velasquez, J., and Graves, D.
Publication Date:	2010
Content and Focus:	The study evaluated six CBIs in field but produced little quantifiable data. It included discussion of types of captured pollutants and maintenance activities
Url:	https://www.researchgate.net/publication/227153221 Field Study of Catch Basin Inserts for the Removal of Pollutants from Urban Runof f

Title:	Stormwater Management Practices (Closed Drainage) Study C-01-74					
Publisher/Sponsor:	New York State DOT					
Author(s):	Kostarelos, K. and Khan, E.					
Publication Date:	December 2007					
Content and Focus:	The study was to evaluate pollutant load reductions of stormwater runoff using catch basin inserts. NYDOT also recognized the opportunity to treat runoff without requiring land by using these inserts. However, NYDOT was not just concerned with TSS, but also fecal coliform bacteria, total phosphorus, total nitrogen, total petroleum hydrocarbons and biochemical oxygen demand. Of the six catch basin inserts evaluated, only the <i>Stream Guard Catch Basin Insert for Oil and Grease</i> was determined to remove at least 80% sediment.					
Url:	https://www.dot.ny.gov/divisions/engineering/technical-services/trans-r-and-d-repository/C-01-74%20Stormwater%20Management%20Practices%20(Closed%20Drainage.pdf					

Title:	Performance of a Catch Basin Filter and Leachate From Biocidal Media for Stormwater Treatment
Publisher/Sponsor:	California Polytechnic State University-San Luis Obispo
Author(s):	MacLure, R.
Publication Date:	2009
Content and Focus:	This thesis covers the testing of a Drainpac™ filter for its sediment, oil and grease, and coliform bacteria removal efficiency in conjunction with bench-scale testing of biocidal polymer beads.
Url:	http://digitalcommons.calpoly.edu/theses/47/

Title:	An Evaluation of the Urban Stormwater Pollutant Removal Efficiency of Catch Basin Inserts			
Publisher/Sponsor:	Water Environmental Research			
Author(s):	Morgan, R.A., Edwards, F.G., Brye, K.R., and Burian, S.J.			
Publication Date:	2005			
Content and Focus:	Evaluated four different CBIs for TSS and other pollutant removals. These evaluations were performed using both lab and field testing. The lab testing used captures from local street sweeping operations as a representative pollutant sample. The test results showed average TSS removal range from 10 to 42%.			
Url:	https://www.jstor.org/stable/25045905?seq=1#page_scan_tab_contents			

Title	Pollutant Removal Capacity of Stormwater Catch Basin Inserts					
Publisher/Sponsor:	World Water and Environmental Resources Congress					
Author(s):	Remly, R., Morgan, R., Edwards, F., Brye, K.R. and Burain, S.					
Publication Date:	2005					
Content and Focus:	basin inserts can provide a retrofit alternative as a method to meet the new National Pollution Discharge Elimination System Phase II stormwater pollution prevention regulations. Six inserts manufactured by five manufacturers were evaluated for removal of suspended solids, petroleum hydrocarbons, and zinc using a pilot scale catch basin and a simulated stormwater.					
Url:	http://ascelibrary.org/doi/pdf/10.1061/40792%28173%29217					

Title:	Environmental Technology Verification Report of the Low Cost Stormwater BMP Study				
Publisher/Sponsor:	Civil Engineering Research Foundation (CREF) - University of Arkansas				
Author(s):	Staff, C. and Jiang, L.				
Publication Date:	2003				
Content and Focus:	This verification report describes the nature and scope of an environmental evaluation of catch basin inserts manufactured by four different companies: AbTech Industries, GeoTechnical Marine Corp., AquaShield, Inc., PacTec, Inc. The inserts are manufactured to be retrofitted into existing catch basins in order to remove sediment, hydrocarbons, metals, nutrients and debris from stormwater runoff.				
Url:	http://faculty.cveg.uark.edu/edwards/papers%20etc/Low%20Cost%20B MP%20Final.pdf				

Title:	Evaluation of the Performance of Four Catch Basin Inserts in Delaware Urban Applications				
Publisher/Sponsor:	Delaware DOT				
Author(s):	Walch, M., Cole, R. and Polasko, W Walters, D. and Frost, W. DiNicola, P. and Gneo, R.				
Publication Date:	2004				
Content and Focus:	The evaluation included comparing the performance of four CBIs with respect to their ability to remove sediment and hydrocarbons as well as maintenance requirements. The units were monitored for 3 years to capture seasonal and various rainfall conditions.				
	The study concluded: Catch basin inserts are attractive retrofits because of the relative ease and low cost of installation. Ultimately, however, their cost effectiveness is determined by the frequency with which they must be maintained. Our study and others have demonstrated that for many applications a very high frequency of cleaning is necessary to keep the inserts from clogging and bypassing stormwater flows, as well as resuspending captured material. Inserts may not be practical for large drainage areas or for areas with high levels of leaves or debris that can plug them.				
Url:	http://deldot.gov/stormwater/pdfs/StormCon04 Walch.pdf				

Title:	ASTM D5141 Standard Test Method for Determining Filtering Efficiency and Flow Rate of the Filtration Component of a Sediment Retention Device (SRD)
Publisher/Sponsor:	ASTM International
Author(s):	Individual authors not listed
Publication Date:	2018
Content and Focus:	This test method is used to determine the filtering efficiency and flow rate of the filtration component of a sediment retention device, such as a silt fence, a silt barrier, or a silt curtain, for specific soil tested.
Url:	https://compass.astm.org/CUSTOMERS/search/search.html?query=D51 41&resStart=0&resLength=10&quicksearch=true&

Title:	ASTM D7351 Standard Test Method for Determination of Sediment Retention Device (SRD)				
Publisher/Sponsor:	ASTM International				
Author(s):	Individual authors not listed				
Publication Date:	2013				
Content and Focus:	This test method quantifies the ability of a sediment retention device (SRD) to retain eroded sediments caused by sheet flowing water under full-scale conditions. This test method may also assist in identifying physical attributes of SRDs that contribute to their erosion control performance.				
Url:	https://compass.astm.org/CUSTOMERS/search/search.html?query=D73 51&dltype=all&quicksearch=true				

Title:	NJCAT Technology Verification: Aqua-Swirl Concentrator and Aqua- Filter Stormwater Treatment Systems			
Publisher/Sponsor:	Tennessee Tech University/AIRL			
Author(s):	Individual authors not listed			
Publication Date:	2005			
Content and Focus:	This report covers the NJCAT verification testing of Aqua-Swirl Concentrator.			
Url:	http://www.state.nj.us/dep/dsr/bscit/AquaShield%20 Verification- Dec2005.pdf			

Title:	Treatment BMP Technology Report
Publisher/Sponsor:	Caltrans
Author(s):	Individual authors not listed
Publication Date:	April 2008 and 2010
Content and Focus:	This report consolidates information about technologies in a standardized manner in a fact sheet format. This report also provides a comprehensive list of potential manufactures for possible consideration. Factsheets provide design, construction and cost information
Url:	http://www.dot.ca.gov/hq/env/stormwater/pdf/CTSW-RT-09-239-06.pdf

Catch Basin Inserts for Ohio Roadways

Appendix B CBI Field Testing Inspection, Maintenance and Removal Forms

101 Storm Sentinel®

Installation form						Weather Information			
Date of	3/30 Location				Weather at time of this inspection?				
Installation		\square Site 2			☐ Clear	☐ Rain	\square Sleet	☐ Snowing	
		101				☑ Other:	cloudy		_
Inspector	Kathryn Gruver								
Name(s)	Ariel Croasmun								
Local Depressi	Over 1"								
			Installation Time						
CBI Name and Vendor			Start	End		Number of personnel			nel
Storm Sentinel			10:34					2	
			10:39	10:40		Tł	nroat bloc	ks install o	on 3/29
Observations									

Describe contents of catch basin

CB has a sump in bottom. Standing water in bottom



Facing Curb





Facing Roadway

Describe condition of catch basin Old concrete curbing in need of repair.









Downstream Curb

Facing Left

Upstream Curb

Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299.00



Depression

Special equipment required for installation

no

Any deviation from manufacturer's installation procedure

no

Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299.00



	Maintena	nce Form		Weather Information				
Date of	8/23/17	Location		Weather at time of this inspection?				
Maintenance		\boxtimes Site 1 \square Si	te 2	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing				
		101	☐ Other:Sunny during maintenance					
				Temperature:				
Inspector Name(s)	Kathryn Gruv	er						
CDIN	, ,	Γ'		N1				
CBI Name and	Start	Fime End		Number of personnel				
Vendor Storm Sentinel		10:13	2					
Storm Sentinei	10:09	10:13	2					
Observations	- 1	-	Photos					
Describe contents No standing wat Describe condit The block is wo impact flow	tion of throat k	olock						
Describe maint	enance activity	(clean, replace	filter,)					
			d from insert. Les	ss than 1 gallon of material.				
Equipment req	uired for main	tenance						
Any deviation f	from manufact	urer's recomm	endation					



	Maintena	nce Form		Weather Information			
Date of	6/15/17	Location		Weather at time of this inspection?			
Maintenance		\boxtimes Site 1 \square Si	te 2	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing			
		101		☐ Other: rained in the morning. Sunny during			
				maintenance			
				Temperature:			
Inspector Name(s)	Kathryn Gruv	er					
CBI Name an		Гіте		Number of personnel			
Vendor	Start	End					
Storm Sentinel			3				
Observations			Photos				
Describe contents basin insert: Clogged, standing blocking opening Describe conding The block is wo	ng water. Debri	s partially					
Describe maint	tenance activity	(clean, replace	filter,)				
CBI removed fr	om catch basin.	Water drained.	Unit taken to Al	len County Garage for back flushing.			
Equipment required for maintenance Truck wash hose at county garage							
Any deviation : Manufacturer re			endation . Not backflushin	g			

	Remo	val for	m	Weather Information					
Date of	10/19/17	Locat	ion	Weather at time of this inspection?					
Removal		⊠ Site	e 1 □ Site 2	⊠ Clear □ Rain □ Sleet □ Snowing					
		101		☐ Other:					
				Temperature:					
Inspector	Kathryn Gr	uver and	d Ariel Croasman	•					
Name(s)	-								
CBI Name and	Removal	Time							
Vendor	Start	End		Number of personnel					
Gully Washer	9:58	9:59	2	-					
01 /1			DI (
Observations			Photos						
Describe conte	nts of catch b	asin							
insert	. CDI								
Very little debri									
The insert conta during September		water							
during September	er inspection								
			A The						
Describe conte	nts and condi	tion	Clean, no debris in CB						
of catch basin			Clean, no deolis in CB						
Special Equipn	ant Doguina	d for D	omoval						
No special equipment, removed by one person									



104 DrainPac™

Installation form							Weather Information			
Date of	3/30	Location				Weather at time of this inspection?				
Installation		⊠ Site 1	☐ Site 2				☐ Rain	\square Sleet	\square Snowing	
		104				☐ Other:				
Inspector Name(s)		Kathryn Gruver Ariel Croasmun								
Local Depressi	es)	Over 1'	,							
CDI Na		Ti	lation me			Nb o	o f o o	l		
CBI Name and Vendor			Start	End			Number	of personn	iei	
Drainpac			10:24 10:30	10:31		T	hroat blocl	2 ks install o	n 3/29	

Observations

Describe contents of catch basin

CB has a sump in bottom. Standing water in bottom





Side Right

Facing Curb



Describe condition of catch basin



Throat



Facing Left

Describe gutter condition and contents



Gutter around CB in poor condition Downstream Curb



Upstream Curb



Depression

Special equipment required for installation

no

Any deviation from manufacturer's installation procedure

No

Other: this was the only location the Drain Pac could be installed. Attempted to install in (101, 104, 105, 109, 110, 111, 205, 206, 209, and 210)



N	Taintenance	Form	Weather Information						
Date of	8/23/	Location	Weather at time of this inspection?						
Maintena nce	a 17	⊠ Site 1 □	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing						
nce		Site 2 104	☐ Other:Sunny during maintenance Temperature:						
Inspector	r Kathry	n Gruver	Temperature.						
Name(s)	i itaan y	ii Giuvei							
CBI	7	Гіте	Number of personnel						
Name									
and Vendor	Start	End							
Drain	10:01	End 10:07	2						
Pac	10.01	10.07							
Observat			Photos						
		d condition							
	basin insert	:							
	ing water.	veen the wire							
	outer fabric								
	n't be remov								
shop vac			A Company of the Comp						
Describe	condition o	f throat block							
The block	k is working.								
			AND A STATE OF THE						
Describe	maintenan	ce activity (clea	n, replace filter,)						
CBI remo	oved from ca	tch basin. 1.5 ga	allons of debris removed from insert.						
			ned, the debris removed from the CBI is consistent with the patching material						
Equipme Shop vac	-	for maintenan	ce:						
Shop vac									
Any devi	ation from	manufacturer's	s recommendation						





M	Iaintenance	Form	Weather Information						
Date of	10/19	Location	Weather at time of this inspection?						
Maintena	ı /17	\boxtimes Site 1 \square	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing						
nce		Site 2	☐ Other:Sunny during maintenance						
	77.1	104	Temperature:						
Inspector Name(s)	Kathry	n Gruver and A	riel Croasman						
CBI]	ime	Number of personnel						
Name									
and Vendor	644	E J							
Venuor Drain	Start 10:47	End 10:54	2 maintananaa tima yaa maagurad anly at tha garaga. It daag not inalyda tima						
Pac	10:47	10:54	2 – maintenance time was measured only at the garage. It does not include time						
1 ac			to remove unit and travel to maintenance area						
Observat			Photos						
		d condition							
	oasin insert	:							
No standi									
		veen the wire							
	outer fabric n't be remov								
shop vac	i t de remov	ed with the							
shop vac									
			All the second s						
			A CONTRACTOR OF THE STATE OF TH						
Describe	condition o	f unit							
		veen the wire	TX III						
	outer fabric								
	i't be remov	ed with the							
shop vac									

Describe maintenance activity (clean, replace filter,..)

Shop vac and back flushed at garage until positive flow was achieved.

CBI removed from catch basin. Less than 1 gallon of debris removed from insert.

Equipment required for maintenance:

Shop vac and hose from truck wash.

Any deviation from manufacturer's recommendation

Back flushing is not a recommended maintenance activity. Unit was clogged during September inspection. The other manufacturers allow back flushing to extend the life of the unit for consistency within the study all clogged units will be back flushed once.











	Remo	oval for	m	Weather Information
Date of	3/9/18	Locat	ion	Weather at time of this inspection?
Removal		⊠ Site	e 1 □ Site 2	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing
		104		☐ Other:
				Temperature:
Inspector	Kathryn Gr	uver and	l Ariel Croasman	
Name(s)				
CBI Name and	Removal	Time		
Vendor	Start	End		Number of personnel
DrainPac	8:54	8:59	2	•
Observations			Photos	
Describe contentions	nts of catch b	asın		
			A STATE OF THE STA	
Describe conte	nts and cond	ition	A little less than one gallo	on of debris removed.
of catch basin		-		d detached from the basket. The fabric mesh was loose
			but not broken.	
Special Equipn	nent Require	d for R	emoval	
No special equip				
- 10 Special equip	,, 101110 v		- r	

Reason for removal End of study







105 FlexStorm®

Installation form							Weather Information			
Date of	3/30	Location				Weather at time of this inspection?				
Installation		⊠ Site 1	\square Site 2				☐ Rain	\square Sleet	\square Snowing	
		105				\square Other:				
Inspector	Kathryn Gruv	er								
Name(s)	Ariel Croasmun									
Local Depressi	es)	Over 2'	,							
			lation me							
CBI Na	Start	End			Number	of personr	nel			
FlexStorm			9:44			302				
	10:20	10:21		Tl	hroat block	ks install o	n 3/29			

Observations

Describe contents of catch basin

CB has a sump in bottom. Standing water in bottom



Facing Curb



Side Right



Describe condition of catch basin

Good but old



Throat



Facing Left

Describe gutter condition and contents



Gutter is in poor condition with patching Downstream Curb



Upstream Curb



Depression

Special equipment required for installation

Yes, Saw, file, circular saw

Any deviation from manufacturer's installation procedure

Needed to trim frame to install. Trimming frame not expected to impact performance in study.

Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299.00



	Maintenance	Form	Weather Information					
Date of	8/23/17	Location	Weather at time of this inspection?					
Maintena	a	\boxtimes Site 1 \square	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing					
nce		Site 2	☐ Other:Sunny during maintenance					
		105	Temperature:					
Inspector	r Kathryn G	ruver	•					
Name(s)								
CBI	T	ime	Number of personnel					
Name								
and	G	ъ.						
Vendor	Start	End						
Flex	9:49	9:59	2					
Storm								
Observat	tions		Photos					
Describe	contents and c	ondition of						
catch bas	sin insert:							
No standi	ng water.							
	_							
Describe	condition of th	roat block						
The block	k is working.		(NOS:					
Describe	maintenance a	ctivity (clean, rep	lace filter,)					
CBI not r	emoved from ca	itch basin. Used sl	nop vac and brushes to remove debris. 1 gallon of debris removed from					
insert. Int	ernal overflows	cleaned						
Equinme	nt required for	· maintenance:						
Shop vac								
-								
Any devi	ation from ma	nufacturer's reco	mmendation					


Catch Basin Inserts for Ohio Roadways Maintenance Form PID 103684 GS&P # 42299.00





	Maintena	ince Form		Weather Information		
Date of	6/15/17	Location		Weather at time of this inspection?		
Maintenance		⊠ Site 1 □ Si	te 2	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing		
		105		☐ Other: rained in the morning. Sunny during		
				maintenance		
				Temperature:		
Inspector Name(s)	Kathryn Gru	ver				
CBI Name an	**	Time		Number of personnel		
Vendor	Start	End	2			
Flexstorm			3			
			DI (
Observations			Photos			
Describe contents and condition of catch basin insert: Clogged, standing water. Debris partially blocking opening. Describe condition of throat block The block is working. Did not take a photo						
Describe maint	tenance activit	y (clean, replace	filter,)			
CBI removed fr	om catch basin	Water drained.	Unit taken to Al	len County Garage for back flushing.		
Equipment required for maintenance Truck wash hose at county garage						
		turer's recomm k flushing when	endation bag is ½ full of c	lebris.		

		Re	emoval for	m	Weather Information					
Date of	10	/19/17	Location		Weather at time of this inspection?					
Removal			⊠ Site 1	☐ Site 2	⊠ Clear □ Rain □ Sleet □ Snowing					
			105		☐ Other:					
					Temperature:					
Inspector Name(s)	K	athryn G	ruver and A	Ariel Croasman						
CBI Name an	h	Remov	val Time							
Vendor	·u	Start	End	Number of personnel						
Gully Washer	r	9:47	9:48	2						
, and the second										
Observations				Photos						
Describe cont		C 4 .	h hasin	Photos						
insert	tent	s of cate	n dasin							
Very little deb	ris i	in CBI		· lie						
The insert con			ing water							
during Septem	ıber	inspecti	on							
				1						
				N. W.						
Describe cont		s and co	ndition		And the second s					
of catch basir		CD		457	A STATE OF THE STA					
Clean, no debi	ris 11	n CB								
CB has a sum	n									
	r									
				1	And the Contract of the second of the second					
					A CONTRACTOR OF THE PROPERTY O					
Special Equip	me	nt Requ	ired for R	emoval						
			11 .	1						
No special equ	upn	nent, rem	noved by tw	vo people						



109 Gullywasher[©]

	Installat	ion form				Weather Information			
Date of	3/30	Location	1		,	Weather at time of this inspection?			
Installation		⊠ Site 1	☐ Site 2			\square Clear	\square Rain	\square Sleet	☐ Snowing
		109				☑ Other: light mist			
Inspector	Kathryn Gruver								
Name(s)	Ariel Croasmun								
Local Depressi	on Depth (inch	ies)							
			llation me						
CBI Na	Start	End			Number	of personr	iel		
Gullywasher			9:31			2			
	9:36	9:39		Th	roat blocl	ks install o	n 3/29		

Observations

Describe contents of catch basin

CB has a sump with standing water.



Facing Curb



Side Right



Facing Roadway

Describe condition of catch basin

Good condition



Throat



Facing Left

Describe gutter condition and contents





Upstream Curb



Depression

Special equipment required for installation

no

Any deviation from manufacturer's installation procedure

no

Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299.00



Maintenance Form			Weather Information
Date of	8/23/17	Location	Weather at time of this inspection?
Maintena		⊠ Site 1 □	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing
nce		Site 2	☐ Other:Sunny during maintenance
-	W 1 0	109	Temperature:
Inspector	Kathryn G	ruver	
Name(s)			
CBI Name		Time	Number of personnel
and	_		
Vendor	Start	End	
Gully Washer	9:41	9:46	2
w asner			
Observations			Photos
Describe contents and condition of			
catch basin insert:			
No standing water.			
Small rips forming in bag at handles			
Describer and Private College Addition			
Describe condition of throat block			
The block is working.			
The block is working.			The second secon
Describe maintenance activity (clean, replace filter,)			
CDI removed from actab basin. I ass then I callen of debric removed from insert. Internal eventlesses also not			
CBI removed from catch basin. Less than 1 gallon of debris removed from insert. Internal overflows cleaned.			
Equipment required for maintenance:			
Removed CBI and poured contents into collection bucket			
Any deviation from manufacturer's recommendation			
no			



	Maintena	nce Fo	rm		Weather Information				
Date of	6/15/17	Locat	tion		Weather at time of this inspection?				
Maintenance		\boxtimes Site 1 \square Sit		te 2	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing				
		109			☐ Other:				
	77 1 0				Temperature:				
Inspector Name(s)	Kathryn Gruv	/er							
CBI Name an		Time		Number of personnel					
Vendor	Star	t	End						
Gullywasher				3					
Observations				Photos					
Describe contents and condition of catch basin insert: Clogged, standing water. Debris partially blocking opening.									
Describe condi	tion of throat l	olock							
The block is working. Did not take a photo									
Describe maint	enance activit	y (clean	, replace	filter,)					
CBI removed fr	om catch basin.	Water	drained.	Unit taken to All	llen County Garage for back flushing.				
Equipment required for maintenance Truck wash hose at county garage									
Any deviation	from manufact	urer's	recomm	endation		_			
	Any deviation from manufacturer's recommendation Manufacturer recommends back flushing every 3-4 weeks. Unit was installed 3/30/17								

		Removal for	·m	Weather Information
Date of	10/19/1	7 Location	1	Weather at time of this inspection?
Removal			☐ Site 2	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing
		109		☐ Other:
				Temperature:
Inspector Name(s)	Kathry	n Gruver and	Ariel Croasman	
CBI Name ar	nd Rei	moval Time		
Vendor	Sta	rt End		Number of personnel
Gully Washer	r 9:33	9:35	2	
Observations			Photos	
Describe cont		atch hasin	1 notos	
insert	ciits oi c	aten basin		
Very little deb	ris in CB	I		
The insert con			7	The same of the sa
during Septen	nber inspe	ection		
			an A State of the	
			100/100	
Describe cont	tents and	condition	Oran - and the state of the sta	
of catch basin		condition	** (表示)	
Clean, no deb	ris in CB			A CONTRACTOR OF THE CONTRACTOR
Charles Essi	mar4 D	animad far D	amazal	
Special Equip	ment Ro	equired for R	emovai	
No special equ	uipment,	removed by o	ne person	
1 -1	,	<i>y</i> -	•	

Reason for removal Clogged unit not functional





110 Flo-Gard Plus®

Installation form						Weather Information			
Date of	3/30	Location	Location				Weather at time of this inspection?		
Installation		⊠ Site 1	☐ Site 2	!		\square Clear	⊠ Rain	\square Sleet	☐ Snowing
		110	110			\square Other:			
Inspector Name(s)	Kathryn Gruv Ariel Croasmu	athryn Gruver iel Croasmun							
Local Depression Depth (inches)			Over 1'	,					
			Ti	llation me			Nb o	- £	l
0	me and Vendo	<u>r</u>	Start	End			Number	of personn	iei
Flo-Gard Plus			9:05 9:12	9:13		Tl	hroat block	2 ks install o	n 3/29

Observations

Describe contents of catch basin

CB has a sump, standing water in bottom.



Facing Curb



Side Right



Facing Roadway

Describe condition of catch basin

Old but good condition





Facing Left

Throat Describe gutter condition and contents



Downstream Curb



Upstream Curb



Depression

Special equipment required for installation

no

Any deviation from manufacturer's installation procedure

no

Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299.00



M	aintenance	Form	Weather Information
Date of	8/23/17	Location	Weather at time of this inspection?
Maintena		\boxtimes Site 1 \square	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing
nce		Site 2	☐ Other:Sunny during maintenance
		110	Temperature:
Inspector	Kathryn G	ruver	
Name(s)			
CBI Name		Time	Number of personnel
and			
Vendor	Start	End	
Flo Gard	9:19	9:27	2
Observation	S		Photos
Describe cor		ondition of	The same of the sa
catch basin i			
No standing			
CBI looked f		, 1 gallon	
removed			
Media bags b	roken		
Describe cor	ndition of th	roat block	
The block is	working.		
Describe ma	intenance a	ctivity (clean, rep	place filter,)
CBI removed	d from catch	basin. Less than 1	gallon of debris removed from insert. Internal overflows cleaned.
Equipment 1	required for	· maintenance:	
Shop vac			
Any deviation	n from mai	nufacturer's reco	ammendation
ring ucviation	, 11 ()111 11141		MINION MARKATA
no			



Maintenance Form		Form	Weather Information				
Date of Maintenance		Location ⊠ Site 1 □ Site 2 110	Weather at time of this inspection? □ Clear □ Rain □ Sleet □ Snowing □ Other:Sunny during maintenance Temperature:				
Inspector Name(s)	Kathry	n Gruver and A	riel Croasman				
CBI	1	Time	Number of personnel				
Name and Vendor	Start	End					
Drain Pac	10:45	10:47	2 – maintenance time was measured only at the garage. It does not include time to remove unit and travel to maintenance area				
			Photos				
Describe contents and condition of catch basin insert: No standing water. Mouse nest in bag Some of netting chewed		ed	Photos				
			n, replace filter,) until positive flow was achieved.				
			than 1 gallon of debris removed from insert.				
Equipment required for maintenance: Shop vac and hose from truck wash.							
Any devi	ation from	manufacturer's	s recommendation				
manufact	Any deviation from manufacturer's recommendation Back flushing is not a recommended maintenance activity. Unit was clogged during September inspection. The other manufacturers allow back flushing to extend the life of the unit for consistency within the study all clogged units will be back flushed once.						

Catch Basin Inserts for Ohio Roadways Maintenance Form PID 103684 GS&P # 42299.00





Catch Basin Inserts for Ohio Roadways Removal Form PID 103684 GS&P # 42299 00

GS&P # 42299.00							
	Remo	oval for	m	Weather Information			
Date of Removal	3/9/18	Locat ⊠ Site 110	ion e 1 □ Site 2	Weather at time of this inspection? ⊠ Clear □ Rain □ Sleet □ Snowing □ Other: Temperature:			
Inspector Name(s)	Kathryn Gr	uver and	l Ariel Croasman	Temperature.			
CBI Name and							
Vendor	Start	End	2	Number of personnel			
FloGard Plus	8:34	8:47	2				
Observations		•	Photos				
Describe contents of catch basin insert A little less than one gallon of debris removed. Outer mesh was damaged. Rodent nest was built in the outside mesh				9789-056-888 DOMERTON OF THE PROPERTY OF THE P			
	nts and cond	ition					
Describe contents and condition of catch basin Catch basin has a sump, very little debris Special Equipment Required for Re			emoval				
No special equip	oment, remov	ed by or	ne person				





111 WOS Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299 00

GS&P # 42	2299.00									
	Installat	ion form			Weather Information					
Date of	3/30	Location	1		W	Veather a	t time of t	his inspect	tion?	
Installation		⊠ Site 1	☐ Site 2			Clear	⊠ Rain	☐ Sleet	\square Snowing	
		111	111			Other:				
Inspector	Kathryn Gruv	er								
Name(s)	Ariel Croasmi	un								
Local Depression Depth (inches) Over 2"				,						
				lation me						
CBI Na	me and Vendo	r	Start	End			Number	of person	nel	
Water Q	Quality Solutio	ns	8:51					2		
WQS			9:01	9:02		Tł	roat bloc	ks install	on 3/29	
Observations				L L						
Describe conte	nts of catch ba	sin					S	ide Right		
	TD 1	41 4								

CB has sump with standing water



Facing Curb





Describe condition of catch basin

Old, but good condition



Facing Left



Throat

Describe gutter condition and contents



Downstream Curb



Upstream Curb



Depression

Special equipment required for installation

no

Any deviation from manufacturer's installation procedure

Needed to adjust the handles to not impact the grate. The bolts on the handles were adjusted to let them sit lower into the CBI.



M	laintenance	Form	Weather Information					
Date of	8/23/17	Location	Weather at time of this inspection?					
Maintena nce		⊠ Site 1 □	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing					
lice		Site 2 111	☐ Other:Sunny during maintenance Temperature:					
Inspector	Kathryn G		Temperature.					
Name(s)	,							
CBI Name		Time	Number of personnel					
and Vendor	Start	End						
WQS	9:01	9:16	2					
Observation	ıs		Photos					
Describe contents and condition of catch basin insert: No standing water. Each layer of filter material was removed and cleaned Describe condition of throat block The block is working.								
Describe ma	nintenance a	ctivity (clean, rep	place filter,)					
of debris rem	noved from i	nsert.	of filter material removed. Metal screens were rinsed with water. 1 gallon					
Equipment	required for	maintenance:						
Shop vac								
_								
Any deviation	on from ma	nufacturer's reco	mmendation					
Manufacturer does not have recommended maintenance								

Catch Basin Inserts for Ohio Roadways Maintenance Form PID 103684 GS&P # 42299.00



Maintenance Form		Form	Weather Information			
Date of Maintena nce	10/19 /17	Location ⊠ Site 1 □ Site 2	Weather at time of this inspection? ☐ Clear ☐ Rain ☐ Sleet ☐ Snowing ☐ Other:Sunny during maintenance			
		111	Temperature:			
Inspector Name(s)	Kathry	yn Gruver and A	riel Croasman			
CBI		Гіте	Number of personnel			
Name and						
Vendor	Start	End				
Drain Pac	9:04	9:17	2			
Observat			Photos			
of catch I No standi	Dasin insert ng water.		n, replace filter,)			
Removed	all layers o	f filter media and	d used shop vac to clean. than 1 gallon of debris removed from insert.			
Equipme Shop vac	Equipment required for maintenance: Shop vac					
Manufact	Any deviation from manufacturer's recommendation Manufacture does not required in field cleaning. The product is to be removed and replaced with a fresh unit. The unit is then cleaned for later reuse.					

Catch Basin Inserts for Ohio Roadways Maintenance Form PID 103684 GS&P # 42299.00



Catch Basin Inserts for Ohio Roadways Maintenance Form PID 103684 GS&P # 42299.00











U3&F # 42299.00							
		oval for		Weather Information			
Date of	3/9/18	Locat		Weather at time of this inspection?			
Removal			e 1 □ Site 2	⊠ Clear □ Rain □ Sleet □ Snowing			
		111		☐ Other:			
				Temperature:			
Inspector	Kathryn Gr	uver and	d Ariel Croasman				
Name(s)							
CBI Name and	Removal	Time					
Vendor	Start	End		Number of personnel			
WQS	8:14	8:32	2				
Observations			Photos				
Describe conte	nts of catch b	asin					
insert							
A 1504 4 4	11	c					
A little less than		t					
debris removed.		d 4					
Outer mesh was nest was built in	the outside n	nach nach					
nest was built in	the outside in	10311					
Describe conte	nts and condi	ition					
of catch basin			CONTRACTOR OF THE PARTY OF THE				
Catch basin has	sump, very li	ttle	- Comment				
debris							
			Lynn Th				
				A STATE OF THE STA			
			The state of the s				
			THE RESERVED TO SERVED				
			THE PERSON NAMED IN				
Charles E	ant Dag	d for D	omoval				
Special Equipm No special equipment	ient Kequire	u ior Ko	emovai ne person				
ino speciai equij	ment, remov	cu by or	ic herson				





113 Triton™

PID 10368 GS&P # 42	4				
GBCC1 // 12		tion form		Weather Information	
Date of Installation	5/11	Location ⊠ Site 1 113			Weather at time of this inspection? ☐ Clear ☐ Rain ☐ Sleet ☐ Snowing ☐ Other: misty
Inspector Name(s)	Kathryn Gruv Ariel Croasmu				
Local Depression	on Depth (inch	ies)	n/a, CB	I does no	ot impact grate
			Instal Ti		
CBI Na	me and Vendo	r	Start	End	Number of personnel
	Triton		9:22	10:45	2 CBI installed inside catch basin
Observations					
Describe conte	nts of catch bas	sin			
Standing water is		g Curb			Side Right





Facing Roadway

Describe condition of catch basin
Poor condition, concrete around throat is missing. Not expected to impact the flow or performance of unit



Throat



Facing Left

Describe gutter condition and contents



Downstream Curb




Upstream Curb

Depression

Special equipment required for installation

Circular saw, hammer, drill, screw driver

Any deviation from manufacturer's installation procedure



M	laintenance	Form	Weather Information
Date of Maintena nce	8/23/17	Location ⊠ Site 1 □ Site 2 113	Weather at time of this inspection? ⊠ Clear □ Rain □ Sleet □ Snowing □ Other:Sunny during maintenance Temperature:
Inspector Name(s)	Kathryn G	ruver	
CBI Name		Time	Number of personnel
and Vendor	Start	End	
Triton	8:30	8:45	2
Observation			Photos
Describe contents and condition of catch basin insert: No standing water. Each layer of filter material was removed and cleaned Describe condition of throat block			
No throat block Picture taken from throat opening			
		ctivity (clean, rep debris. Debris rer	noved from overflows 1 gallon of debris removed
E anima v		. mainta	
Shop vac and	-	· maintenance:	
Any deviation	on from ma	nufacturer's reco	ommendation
no			



Maintenance Form			Weather Information							
Date of	10/19	Location	Weather at time of this inspection?							
Mainten	a /17	\boxtimes Site 1 \square	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing							
nce		Site 2	☐ Other:Sunny during maintenance							
_		113	Temperature:							
Inspector Name(s)	r Kathry	yn Gruver and A	riel Croasman							
CBI	,	Гіте	Number of personnel							
Name			Tvaliber of personner							
and										
Vendor	Start	End								
Drain	8:48	9:01	2							
Pac										
Observat		ı	Photos							
		nd condition								
	basin insert	•	and the same of th							
	ris on tray									
Some star	nding water									
			Ja Charles Andrews (April 1997)							
Describe	maintenan	ce activity (clea	ın, replace filter,)							
used shop	vac to clea	n contents and r	emoved debris from overflow.							
2 gallons	of debris an	nd water remove	d. Without the water, 1 gallon of debris							
- O 2- 2-2-2 And Have Lemo ten Handar and Have, L Balloli of deolib										

Equipment required for maintenance: Shop vac

Any deviation from manufacturer's recommendation



Catch Basin Inserts for Ohio Roadways Maintenance Form PID 103684 GS&P # 42299.00



		Re	emoval for	m	Weather Information				
Date of	12/	14/17	Location		Weather at time of this inspection?				
Removal		⊠ Site 1 [☐ Site 2	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing				
			113		☐ Other:				
Inspector	Vo	thrun Gr	uver and A	riel Croasman	Temperature: 15				
Name(s)	Na	ull yll Gi	uvei aliu A	Tier Croasman					
CBI Name a	ınd		val Time						
Vendor Triton		Start 9:05	End 9:53	Number of personnel 2					
Triton		9.03	9.33	2					
Observation	ıs			Photos					
Describe con insert Very little de Standing war	ebris ter	in CBI,							
Special Equ Very time co	in nd wa ipme nsun	ent Requ	ired for R emove. Req	emoval quired 2 people.					



114 Adsorb-It™

GDCI II II	2277.00						
	Installat	ion form			Weather Information		
Date of	6/15 Location				Weather at time of this inspection?		
Installation	\boxtimes Site 1 \square Site 2				☐ Clear ☐ Rain ☐ Sleet ☐ Snowing		
	114				☑ Other: misty		
Inspector	Kathryn Gruv				2 Other. Inisty		
Nome(g)	Mark McCabe						
Name(s)	Mark McCabe	5					
Local Depressi	on Depth (inch	es)					
			Instal	lation			
			Ti	me			
CBI Na	me and Vendo	r	Start	End	Number of personnel		
	Adsorb-it		1:18		2		
1	iusorb it		1:40	1:43	2		
			1.40	1.43			
Observations							
Describe conte	nts of catch ba	sin					
2 0 0 0 1 0 0 0 1 0 0		y 					
	Standing w	ater in sum	n				
Standing water in sump					Side Right		
	Facin	g Curb					

Facing Roadway

Describe condition of catch basin
Poor condition, concrete around throat is missing. Not expected to impact the flow or performance of unit





Facing Left

Throat

Describe gutter condition and contents Downstream Curb



Upstream Curb

Depression

Special equipment required for installation

Circular saw, hammer, drill, screw driver

Any deviation from manufacturer's installation procedure No



Maintenance Form			Weather Information				
Date of Maintena	8/23/17	Location	Weather at time of this inspection?				
nce		⊠ Site 1 □ Site 2	☑ Clear☐ Rain☐ Sleet☐ Snowing☐ Other:Sunny during maintenance				
		114	Temperature:				
Inspector	Kathryn G		Temperature.				
Name(s)							
CBI Name		Time	Number of personnel				
and Vendor	Start	End					
Adsorb-it	8:48	8:56	2				
Observation	1S	l	Photos				
Describe contents and condition of catch basin insert: No standing water, however the bag material was slightly damp.							
Describe condition of throat block The block is working.							
Describe ma	intenance a	ctivity (clean, rep	place filter,)				
Shop vac to	remove colle	ected debris.					
Equipment	required for	maintenance:					
Shop vac	Shop vac						
Any deviation	on from ma	nufacturer's reco	ommendation				
Manufacturer does not have recommended maintenance							

Maintenance Form			Weather Information
Date of Maintenance	10/19 /17	Location ⊠ Site 1 □ Site 2	Weather at time of this inspection? ☐ Clear ☐ Rain ☐ Sleet ☐ Snowing ☐ Other:Sunny during maintenance
Inspector	r Kathry	114 n Gruver and A	Temperature:
Name(s)	Kauny	ii Gruver and A	Het Croasilian
CBI	Γ	ime	Number of personnel
Name and			
Vendor	Start	End	
Drain	10:33	10:45	2 – maintenance time was measured only at the garage. It does not include time
Pac			to remove unit and travel to maintenance area
Observat			Photos
of catch l No standi	basin insert: ng water at t n/maintenanc	the time of the	
Shop vac	and back flu	ished at garage	an, replace filter,) until positive flow was achieved.
Less than	I gallon of o	debris removed	from insert.

Equipment required for maintenance: Shop vac and hose from truck wash.

Any deviation from manufacturer's recommendation

Back flushing is not a recommended maintenance activity. Unit was clogged during September inspection. The other manufacturers allow back flushing to extend the life of the unit for consistency within the study all clogged units will be back flushed once.





		Re	emoval for	m	Weather Information
Date of	12/	14/17	Location		Weather at time of this inspection?
Removal			\boxtimes Site 1	☐ Site 2	\boxtimes Clear \square Rain \square Sleet \square Snowing
			114		☐ Other:
T .	17	4 0	1.4	. 1.0	Temperature: 15
Inspector Name(s)	Ka	thryn Gr	uver and A	riel Croasman	
CBI Name a	nd		val Time		
Vendor		Start	End		Number of personnel
Absorb-it		8:59	9:03	2	
Observation	S			Photos	
Describe cor	itent	s of catc	h basin		
insert					THE ROOM STREET, ASS.
Very little de	bris	in CBI			
Snow, grit an	d wa	iter			The state of the s
Describe cor	ntent	s and co	ndition		
of catch basi		s and co	narnon		
Grit and debris in catch basin.					

Special Equipment Required for Removal No special equipment, removed by one person

Reason for removal

Clogged unit not functional



205 Adsorb-It™

		Weather Information							
Date of	6/15 Location				Weather at time of this inspection?				
Installation		⊠ Site 1	\square Site 2			⊠ Clear	☐ Rain	\square Sleet	☐ Snowing
		205	5			\square Other:			
Inspector	Kathryn Gruv	er							
Name(s)	Mark McCabe								
Local Depressi	es)								
				lation					
			me						
CBI Na	Start	End			Number	of personn	iel		
Adsorb-it			10:24					2	
			10:43	10:44					

Observations

Describe contents of catch basin



Facing Curb



Side Right



Facing Roadway

Describe condition of catch basin
Poor condition, concrete around throat is missing. Not expected to impact the flow or performance of unit



Throat



Facing Left

Describe gutter condition and contents



Upstream Curb

Depression

Special equipment required for installation

Circular saw, hammer, drill, screw driver

Any deviation from manufacturer's installation procedure

Yes, basket shape of basket was modified to within the catch basin













aintenance	Form	Weather Information					
8/23/17	Location	Weather at time of this inspection?					
	\square Site 1 \boxtimes	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing					
	Site 2	☐ Other:Sunny during maintenance					
	205	Temperature:					
Kathryn G	ruver						
	Time	Number of personnel					
		•					
Start	End						
12:00	12:10	2					
S		Photos					
	ondition of	13 AMO AMO					
	low clogged						
discolored		and the second					
idition of th	roat block						
		He State of Manual Control of the Co					
working.							
intenance a	ctivity (clean ren	lace filter)					
	cervity (cicum, rep	11001,)					
emove colle	cted debris. Remo	eved 3.5 gallons of debris. Clean debris from overflows.					
required for	· maintenance:						
Shop vac and brush							
n from mai	nufacturer's reco	mmendation					
, i i viii iiidi							
	Start 12:00 Start 12:00 s ntents and consert: water. Overfordiscolored discolored intenance and consert and consert and consert. water overfordiscolored intenance and consert and conse	Site 1 Site 2 205 Kathryn Gruver					



Maintenance Form			Weather Information					
Date of	10/19	Location	Weather at time of this inspection?					
Maintena	a /17	\square Site 1 \boxtimes	⊠ Clear □ Rain □ Sleet □ Snowing					
nce		Site 2	☐ Other: Sunny during maintenance					
		205	Temperature:					
Inspector	r Kathry	n Gruver and A	riel Croasman					
Name(s)								
CBI	7	Гіте	Number of personnel					
Name								
and								
Vendor	Start	End						
Drain	12:43	12:47	2 – maintenance time was measured only at the garage. It does not include time					
Pac			to remove unit and travel to maintenance area					
Observat	tions	.	Photos					
Describe	contents an	d condition						
	basin insert		and the same of the					
No standi	ing water at	the time of the	The second secon					
	n/maintenan	ce						
Minor del	bris							
			00000000					
			The second secon					
Describe	maintenan	ce activity (clea	n, replace filter,)					
			until positive flow was achieved.					
1 gallon of debris removed from inser			rt.					
E	4	6						
		for maintenan om truck wash.	ice:					
Shop vac	and nose no	m uuck wasil.						

Any deviation from manufacturer's recommendation

Back flushing is not a recommended maintenance activity. Unit was clogged during September inspection. The other manufacturers allow back flushing to extend the life of the unit for consistency within the study all clogged units will be back flushed once.



Catch Basin Inserts for Ohio Roadways Maintenance Form PID 103684 GS&P # 42299.00







		Re	emoval for	m	Weather Information
Date of	12/	14/17	Location		Weather at time of this inspection?
Removal				⊠ Site 2	⊠ Clear □ Rain □ Sleet □ Snowing
205					☐ Other: Temperature: 15
Inspector	Ka	thrvn Gr	uver and A	riel Croasman	Temperature. 13
Name(s)					
CBI Name a	nd		val Time		
Vendor Absorb-it		Start 11:04	End 11:11	2	Number of personnel
Absorb-it		11.04	11.11	2	
Observation	S			Photos	
Describe contents of catch basin insert Very little debris in CBI Describe contents and condition					
of catch basis	in ad wa	nt Requ	ired for Ro		
No special ed	quipn	nent, rem	noved by or	ne person	



207 Triton™

US&F # 42299.00								
		ion form		Weather Information				
Date of	5/11	Location			Weather at time of this inspection?			
Installation		☐ Site 1	⊠ Site 2		☐ Clear ☐ Rain ☐ Sleet ☐ Snowing			
207					☑ Other: cloudy			
Inspector Name(s)	Kathryn Gruv Ariel Croasmu							
Local Depressi	on Depth (inch	es)	n/a, CB	I does not	t impact grate			
				lation me				
CBI Na	me and Vendo	r	Start	End	Number of personnel			
	Triton				2			
			11:22	1:07	CBI installed inside catch basin			
Observations				<u> </u>				
Describe conte	nts of catch bas	sin						
CB clean no del	oris							
	Facin	g Curb		Side Right				
Facing Roadway								

Describe condition of catch basin

Very good condition



Throat



Facing Left

Describe gutter condition and contents



Downstream Curb



Upstream Curb

Depression

Special equipment required for installation

Circular saw, hammer, drill, screw driver

Any deviation from manufacturer's installation procedure

Top hat location had to be moved closer to the front of the base to allow the unit to be installed within the catch basin. New holes were drilled and the vacated screw holes were filled with spray foam.





Maintenance Form			Weather Information					
Date of	8/23/17	Location	Weather at time of this inspection?					
Maintena		\square Site 1 \boxtimes	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing					
nce		Site 2	☐ Other:Sunny during maintenance					
		207	Temperature:					
Inspector	Kathryn G	ruver						
Name(s)								
CBI Name		Time	Number of personnel					
and								
Vendor	Start	End						
Triton	11:43	11:57	2					
Observation	S		Photos					
Describe cor		ondition of						
catch basin i								
No standing		low clogged						
with debris.								
CBI media is	discolored							
Describe con	dition of th	roat block						
No throat blo	ck							
			Control of the Contro					
			L.					
Describe ma	intenance a	ctivity (clean, rep	lace filter,)					
GI.	11	. 111 ' D						
Shop vac to r	emove colle	cted debris. Remo	oved almost 3 gallons of debris.					
Equipment i	required for	maintenance:						
Shop vac and	l hanah							
Shop vac and	i bi usii							
Any deviation	n from mai	nufacturer's reco	mmendation					
no								



G5&1 11 12277.00			
Maintenance Form			Weather Information
Date of	10/19	Location	Weather at time of this inspection?
Maintena		\square Site 1 \boxtimes	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing
nce	1 /1/		
nce		Site 2	☐ Other:Sunny during maintenance
		207	Temperature:
Inspector Kathryn Gruver and A		n Gruver and A	riel Croasman
Name(s)	Name(s)		
CDI			
CBI		<u> Fime</u>	Number of personnel
Name			
and			
Vendor	Start	End	
Drain	12:14	12:21	2
Pac			
Observations			Photos
Describe contents and condition			
of catch basin insert:			
A few inches of debris on tray			A STATE OF THE STA
A lew menes of deuris on day			

Describe maintenance activity (clean, replace filter,..) used shop vac to clean contents and removed debris from overflow.

2 gallons of debris removed.

Equipment required for maintenance:

Shop vac

Any deviation from manufacturer's recommendation none



	Re	moval for	m	Weather Information			
Date of	3/9/18	Location	n	Weather at time of this inspection?			
Removal		☐ Site 1	\boxtimes Site 2	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing			
		207		☐ Other:			
				Temperature:			
Inspector	Kathryn (Gruver and	d Ariel Croasman				
Name(s)							
CBI Name and	Remov	al Time					
Vendor	Start	End		Number of personnel			
Triton	9:49	10:51	2				
Observations			Photos				
Describe conte	nts of catch	hasin	1 Hotos	The state of the s			
insert	iits of Catci	i Dasiii					
15 gallons of de	bris remove	ed.					
To guirons of ac	0110 1 01110 / 1						
			A Secretaria	attern management in thirt day in the state of the state			
			day and the				
Describe conte	nts and cor	dition					
of catch basin							
				The same			
			All fails at the				
			A SECOND CONTRACTOR OF THE SECOND CONTRACTOR O				
				The same of the sa			
Special Equipn	ant Dear-	rad for D	amoval				
Very time consu							
Wrench, screw	driver saw	nove. Req	junea 2 people.				
William, Sciew	arren, saw.						

Reason for removal

Unit observed with standing water during February inspection and end of study







15 gallons of debris removed, collected in several buckets





208 Flo-Gard Plus®

Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299 00

GS&P # 42299.00							
	Installat	ion form			Weather Information		
Date of	3/29 Location					Weather at time of this inspection?	
Installation		☐ Site 1 ⊠ Site 2				⊠ Clear □ Rain □ Sleet □ Snowing	
		208				☐ Other:	
Inspector	Kathryn Gruv	er					
Name(s)	Ariel Croasm	ın					
Local Depressi	on Depth (inch	ies)	1"				
			lation				
CRI No	me and Vendo	ır	Start	me End		Number of personnel	
CDINA	ime and vendo	1	2:05	Enu		2	
Flo	-Gard Plus		2:22	2:24		2	
Observations							
Describe conte	nts of catch ba	sin					
Debris from removing the grate in basin The state of the						Side Right	
Facing Curb Side Right Facing Roadway							

Describe condition of catch basin

Good condition



Throat



Facing Left

Describe gutter condition and contents



Downstream Curb



CBI Field Installation forms_208.docx



Depression

Special equipment required for installation

No special equipment needed Time to install includes construction of the throat blockage.

Any deviation from manufacturer's installation procedure

no

Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299.00



M	Maintenance Form		Weather Information
Date of	8/23/17	Location	Weather at time of this inspection?
Maintena	0,20,1,	\square Site 1 \boxtimes	⊠ Clear □ Rain □ Sleet □ Snowing
nce		Site 2	☐ Other:Sunny during maintenance
		208	Temperature:
Inspector	Kathryn C		Temperature.
Name(s)	1200111 5		
CBI Name		Time	Number of personnel
and			
Vendor	Start	End	
Flo-Gard	11:30	11:41	2
Observation	ıs		Photos
Describe con catch basin CBI very ful No standing	insert: l of debris. water.		Part of the second seco
Describe condition of throat block The block is working.			
Describe ma	intenance a	ctivity (clean, rep	place filter,)
			ll shovel and shop vac to remove collected debris. Removed 8 gallons of
Equipment	required for	maintenance:	
Small shovel	, shop vac a	nd brush	
Any deviation	on from ma	nufacturer's reco	ommendation
no			







Maintenance Form		e Form	Weather Information			
Date of Maintena nce		Location ☐ Site 1 ⊠ Site 2 208	Weather at time of this inspection? □ Clear □ Rain □ Sleet □ Snowing □ Other:Sunny during maintenance Temperature:			
Inspector Name(s)	Kathr	yn Gruver and A	riel Croasman			
CBI		Time	Number of personnel			
Name and Vendor	Start	End				
Drain	12:47	12:50	2 – maintenance time was measured only at the garage. It does not include time			
Pac			to remove unit and travel to maintenance area			
Observat	ions		Photos			
of catch I	pasin inser		m, replace filter,)			
Shop vac	and back fl	ushed at garage	until positive flow was achieved.			
CDI ICIIIO	veu mom c	awii basiii. 1 gali	on of acous temoved nom insert.			
		d for maintenan om truck wash.	ce:			

Any deviation from manufacturer's recommendation

Back flushing is not a recommended maintenance activity. Unit was clogged during September inspection. The other manufacturers allow back flushing to extend the life of the unit for consistency within the study all clogged units will be back flushed once.



	Re	moval for	m	Weather Information			
Date of	3/9/18	Location		Weather at time of this inspection?			
Removal			⊠ Site 2	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing			
		208		☐ Other:			
Inspector	V othryn (Gruver on	d Ariel Croasman	Temperature:			
Name(s)	Kaunyn	Jiuvei and	d Affet Croasillali				
CBI Name and Vendor	Remov Start	al Time End		Number of personnel			
FlowGard	9:36	9:48	2	1,4111001 01 personner			
Plus							
Observations	•		Photos				
Describe contents of catch basin insert 1 gallon of debris removed. Standing water during last inspection			ACTO COTO OF A PLANT OF THE PLA				
Describe conter of catch basin Special Equipm			emoval				
None	-						



Catch Basin Inserts for Ohio Roadways Removal Form PID 103684 GS&P # 42299.00



209 WOS

		Weather Information							
Date of	3/29	Location				Weather at time of this inspection?			
Installation		\square Site 1 \boxtimes Site 2					☐ Rain	\square Sleet	\square Snowing
		209				☐ Other:			
Inspector	Kathryn Gruver								
Name(s)	Ariel Croasmun								
Local Depression Depth (inches)			1/2"						
				llation me					
CBI Name and Vendor			Start	End			Number	of personn	nel
Water Quality Solutions			11:48						
WQS			12:07	12:08				2	

Observations

Describe contents of catch basin

Basin clean







Side Right



Facing Roadway

Describe condition of catch basin

Good condition



Throat



Facing Left

Describe gutter condition and contents



Downstream Curb



CBI Field Installation forms_209.docx



Depression

Special equipment required for installation

No

Time to install includes construction of the throat blockage.

Any deviation from manufacturer's installation procedure

Handles are higher than the basket, without modification the grate would sit on the handles. The handles were removed, bent slightly and reattached. The above modification is not expected to impact the performance of the unit.



	G561 11 12277.00						
	aintenance		Weather Information				
Date of	8/23/17	Location	Weather at time of this inspection?				
Maintena		\square Site 1 \boxtimes	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing				
nce		Site 2	☐ Other:Sunny during maintenance				
		209	Temperature:				
Inspector	Kathryn G	ruver	1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -				
Name(s)							
CBI Name		Time	Number of personnel				
and							
Vendor	Start	End					
WQS	11:14	11:24	2				
Observation	S		Photos				
Describe con catch basin in Top layer of debris. No standing to Describe con	insert: CBI covered water.	with 3" of					
The block is	working.						
Describe ma	intenance a	ctivity (clean, rep	lace filter,)				
of debris rem	noved from i	nsert.	of filter material removed. Metal screens were rinsed with water. 3 gallon				
Equipment 1	required for	maintenance:					
Small shovel, shop vac and brush							
Any deviation	on from mai	nufacturer's reco	mmendation				
Manufacturer does not have recommended maintenance							





Maintenance Form		Form	Weather Information				
Date of	12/14	Location	Weather at time of this inspection?				
Maintena	a /17	\square Site 1 \boxtimes	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing				
nce		Site 2	☐ Other: Sunny during maintenance				
		209	Temperature:				
Inspector	r Kathry	n Gruver and A	riel Croasman				
Name(s)							
CBI	7	Гіте	Number of personnel				
Name			•				
and							
Vendor	Start	End					
WQS	10:43	10:53	2				
Observat	tions		Photos				
		. d diti	Photos				
	contents an basin insert:	d condition					
Snow cov		•					
	top filter la	vor					
Deoris on	top mier ia	yeı					
All filter	lavers remov	ved and debris					
cleaned	ia y cro renne i	ou una acomo					
			in, replace filter,)				
Removed	all layers of	t filter media an	d used shop vac to clean.				
CDI	1 C	4 - 1 - 1 1 11	Long Count delade managed Counting and				
CBI remo	oved from ca	ten basın. 4 gall	lon of wet debris removed from insert.				
Fanisses	nt required	for maintance					
Shop vac	nt required	for maintenan	ice:				
Shop vac							

Any deviation from manufacturer's recommendation

Manufacture does not required in field cleaning. The product is to be removed and replaced with a fresh unit. The unit is then cleaned for later reuse.

Maintenance Form		Form	Weather Information					
Date of	10/19	Location	Weather at time of this inspection?					
Maintena	/17	\square Site 1 \boxtimes	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing					
nce		Site 2	☐ Other: Sunny during maintenance					
		209	Temperature:					
Inspector	· Kathry	n Gruver and A	riel Croasman					
Name(s)								
CBI	ŗ	Гіте	Number of personnel					
Name								
and								
Vendor	Start	End						
WQS	11:56	12:08	2					
Observat	ions		Photos					
Describe	contents a	nd condition						
	oasin insert							
No standi	ng water.							
	C							
			The same of the sa					
			4					
Describe	maintenan	ce activity (clea	n, replace filter,)					
Removed	all layers o	f filter media an	d used shop vac to clean.					
CDI	1.0	. 1 1	1 1 1 011 1 10 1					
CBI remo	ved from ca	itch basin. Less	than 1 gallon of debris removed from insert.					
Equipme	nt required	l for maintenan	ce:					
Shop vac	1 01							
1								

Any deviation from manufacturer's recommendation

Manufacture does not required in field cleaning. The product is to be removed and replaced with a fresh unit. The unit is then cleaned for later reuse.





	Re	moval for	·m	Weather Information
Date of	3/9/18	Locatio		Weather at time of this inspection?
Removal			1 ⊠ Site 2	⊠ Clear □ Rain □ Sleet □ Snowing
		209		☐ Other:
				Temperature:
Inspector	Kathryn (Gruver and	d Ariel Croasman	
Name(s)				
CBI Name and		al Time		
Vendor	Start	End		Number of personnel
WQS	9:25	9:33	2	
Observations		l	Photos	
Describe conte	nts of catch	n basin		
insert				
Standing water	during last			
inspection				
Unit frozen, cou	ıld not remo	NVA		
media layers to				The second second
debris collected				
			17 min 14 km	
			1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
Describe conte	nts and con	dition	A STATE OF THE STA	The state of the s
of catch basin				
			CONTRACTOR OF	
				A Charles of the Control of the Cont
				A FACTOR OF THE SECOND CO.
			Karab Calabara La	
			The state of the s	
Special Equipn	nent Reavi	red for R	emoval	The second secon
None	recyui	. cu ivi i		

Reason for removal: Standing water during last inspection



210 FlexStorm®

	Installat	ion form		Weather Information			
Date of	3/29	Location			Weather at time of this inspection?		
Installation		☐ Site 1	⊠ Site 2		☐ Clear ☐ Rain ☐ Sleet ☐ Snowing		
		210			☐ Other:		
Inspector	Kathryn Gruver				·		
Name(s)	Ariel Croasmun						
Local Depressi	on Depth (inch	es)	Over 1"				
			Instal	lation			
			Time				
CBI Na	me and Vendo	r	Start	End	Number of personnel		
F	lexStorm		11:00	11:48	2		
			12:10		Installation started at 11:00 and paused at 11:45 to		
			12:39	12:40	get a tool, the unit at 209 installed. Then restarted		
					install here at 12:10		
Observations							

Observations

Describe contents of catch basin

small amount of debris from removing grate



Facing Curb



Side Right



Facing Roadway

Describe condition of catch basin

good condition



Throat



Facing Left

Describe gutter condition and contents



Downstream Curb



Upstream Curb

Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299.00



Maintenance Form		Form	Weather Information
Date of	8/23/17	Location	Weather at time of this inspection?
Maintena	0/23/17	\square Site 1 \boxtimes	⊠ Clear □ Rain □ Sleet □ Snowing
nce		Site 2	☐ Other:Sunny during maintenance
		210	Temperature:
Inspector	Kathryn C		1 omportune.
Name(s)	11		
CBI Name		Time	Number of personnel
and			
Vendor	Start	End	
Flex Storm	11:03	11:11	2
Observation	ıs		Photos
Describe concatch basin No standing	insert: water.		FRONT
Describe condition of throat block The block is working.			
Describe ma	intenance a	ctivity (clean, rep	place filter,)
Debris (less	than 1 gallor	n) removed from (CBI with shop vac. Overflows cleaned.
Equipment	required fo	r maintenance:	
shop vac and	l brush		
Any deviation	on from ma	nufacturer's reco	ommendation
Manufacture	r does not ha	ave recommended	maintenance

Catch Basin Inserts for Ohio Roadways Maintenance Form PID 103684 GS&P # 42299.00



Catch Basin Inserts for Ohio Roadways Maintenance Form PID 103684 GS&P # 42299.00

	3.5	Е		XX 41 T 6 4	
D		ance Form		Weather Information	
Date of	6/15/17	Location		Weather at time of this inspection?	
Maintenance		☐ Site 1 ⊠ Si	ite 2	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing	
		210		☐ Other: rained in the morning. Sunny during	
				maintenance	
			Temperature:		
Inspector Kathryn Gruver Name(s)					
CBI Name an	d	Time		Number of personnel	
Vendor	Start	End		•	
Flexstorm	11:40	12:03	include time	time was measured only at the garage. It does not and travel to maintenance area	
Observations			Photos		
Describe conte basin insert: Clogged, standi blocking openin	ng water. Debr	is partially		BACK	
Describe maint	tenance activit	y (clean, replace	filter,)		
CBI removed fr	om catch basin	. Water drained.	. Unit taken to Al	len County Garage for back flushing.	
Equipment req	uired for mai	ntenance			
Truck wash hos					
		turer's recomm kk flushing when	endation bag is ½ full of c	lebris.	

Catch Basin Inserts for Ohio Roadways Removal Form PID 103684 GS&P # 42299.00

Removal for			emoval for	m	Weather Information
Date of Removal	10/1	9/17	Location ☐ Site 1		Weather at time of this inspection? ⊠ Clear □ Rain □ Sleet □ Snowing
			210		☐ Other: Temperature:
Inspector Name(s)	Kat	hryn Gr	uver		
CBI Name a	nd		val Time		
Vendor		Start	End		Number of personnel
Gully Wash		11:52	11:53	2	
Observation				Photos	
Describe con insert Very little de	ebris in	n CBI			APACK
Describe con of catch basi Clean, no del	in		ndition		
Special Equi No special ed	ipmei quipm	nt Requient, rem	ired for Ronoved by or	emoval ne person	

Catch Basin Inserts for Ohio Roadways Removal Form PID 103684 GS&P # 42299.00



211 Gullywasher[©] Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299 00

GS&P # 42299.00							
	Installat	ion form				Weather Information	
Date of Installation	3/29	Location ☐ Site 1 ⊠ Site 2 211			Weather at time of this inspection? ⊠ Clear □ Rain □ Sleet □ Snowing □ Other:		
Inspector Name(s)	Kathryn Gruv Ariel Croasmu	ın					
Local Depressi	on Depth (inch	es)	1/4"				
			Instal Ti	me			
CBI Na	me and Vendo	r	Start	End		Number of personnel	
	ullywasher		10:30 10:52	10:52		2 (one person could install it)	
Observations							
Describe conte	nts of catch bas	sin					
	Debris from r	emoving g	rate				
	Facin	g Curb				Side Right	
				Facing Ro		ray	

Describe condition of catch basin

Good condition



Throat



Facing Left

Describe gutter condition and contents



Downstream Curb



CBI Field Installation forms_211.docx

Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299.00



Depression

Special equipment required for installation

No

Any deviation from manufacturer's installation procedure

No

Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299.00



Catch Basin Inserts for Ohio Roadways Maintenance Form PID 103684 GS&P # 42299.00

	Maintena	ınce Form		Weather Information		
Date of	6/15/17	Location		Weather at time of this inspection?		
Maintenance		⊠ Site 1 □ Si	ite 2	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing		
		211		☐ Other: rained in the morning. Sunny during		
				maintenance		
			Temperature:			
Inspector Name(s)						
CBI Name an		Time		Number of personnel		
Vendor	Start	End				
Gullywasher	11:36	11:37	include time	time was measured only at the garage. It does not and travel to maintenance area		
Observations			Photos			
Describe contents and condition of catch basin insert: Clogged, standing water. Debris partially blocking opening. Describe condition of throat block The block is working. Did not take a photo						
Describe maint	tenance activit	y (clean, replace	filter,)			
CBI removed fr	om catch basin.	Water drained	. Unit taken to Al	len County Garage for back flushing.		
Equipment required for maintenance Truck wash hose at county garage						
Any deviation : Manufacturer re				was installed 3/30/17		

Catch Basin Inserts for Ohio Roadways Removal Form PID 103684 GS&P # 42299.00

Re	emoval for	m	Weather Information			
8/23/17	Location		Weather at time of this inspection?			
		⊠ Site 2	□ Clear □ Rain □ Sleet □ Snowing			
	211	☐ Other:				
		Temperature:				
Kathryn	Gruver					
		Number of personnel				
10:58	11:01	2				
		Photos				
n CBI s in CBI						
	Kathryn Remove Start 10:58 ts of catc CBI in CBI	8/23/17 Location ☐ Site 1 211 Kathryn Gruver Removal Time Start End 10:58 11:01 ts of catch basin a CBI in CBI	Site 1 Site 2 211			

Catch Basin Inserts for Ohio Roadways Removal Form PID 103684 GS&P # 42299.00

Describe contents and condition of catch basin

Clean, no debris in CB



Special Equipment Required for Removal

No special equipment, removed by one person

Reason for removal

Clogged unit not functional







213

Storm Sentinel®

Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299 00

GS&P # 42299.00						
	Installat	ion form			Weather Information	
Date of Installation	3/29	Location ☐ Site 1 ⊠ Site 2 213			Weather at time of this inspection? ⊠ Clear □ Rain □ Sleet □ Snowing □ Other:	
Inspector Kathryn Gruver Ariel Croasmun						
Local Depressi	on Depth (inch	es)	Over 1'	,		
			Ti			
	me and Vendo	r	Start	End	Number of personnel	
	rm Sentinel		10:05 10:27	10:28	2	
Observations						
Describe conte	nts of catch bas	sin				
Debris from removing grate						
	Facin	g Curb			Side Right	
Facing Roadway						

Describe condition of catch basin

Good





Throat

Describe gutter condition and contents





CBI Field Installation forms_213.docx



Depression

Special equipment required for installation

File, grinder, small circular saw.

Time to install includes construction of the throat blockage.

Any deviation from manufacturer's installation procedure

Needed to trim the corners of the CBI frame for the unit to fit within the catch basin grate. Trimming of the frame is not expected to impact the performance of the unit.

Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299.00



Depression

Special equipment required for installation

ทก

Any deviation from manufacturer's installation procedure

No

Catch Basin Inserts for Ohio Roadways Installation Form PID 103684 GS&P # 42299.00



Catch Basin Inserts for Ohio Roadways Maintenance Form PID 103684 GS&P # 42299.00

GDCI II 12						
	Maintena	ince Form		Weather Information		
Date of	6/15/17	Location		Weather at time of this inspection?		
Maintenance		☐ Site 1 ⊠ Si	ite 2	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing		
		213		☐ Other: rained in the morning. Sunny during		
		213		maintenance		
T	V - 11 C			Temperature:		
Inspector Name(s)	Kathryn Gruv	ver				
CBI Name an	d	Time		Number of personnel		
Vendor	Start	End		-		
Storm Sentinel	11:38	11:58	2-maintenance	time was measured only at the garage. It does not		
			include time			
			to remove unit	and travel to maintenance area		
Observations			Photos			
Describe contents and condition of catch basin insert: Clogged, standing water. Debris partially blocking opening. Describe condition of throat block The block is working. Did not take a photo						
Describe maint	tenance activit	v (clean, replace	filter)			
		, (, -				
CBI removed fr	om catch basin.	Water drained	. Unit taken to Al	len County Garage for back flushing.		
Equipment req	uired for mair	itenance				
Truck wash hos						
Any deviation	from manufact	turer's recomm	endation			
			. Not backflushin	g		
		1		-		
1						

Catch Basin Inserts for Ohio Roadways Removal Form PID 103684 GS&P # 42299.00

	R	emoval for	m	Weather Information			
Date of	8/23/17	Location		Weather at time of this inspection?			
Removal		☐ Site 1	⊠ Site 2	☐ Clear ☐ Rain ☐ Sleet ☐ Snowing			
		213		☐ Other:			
				Temperature:			
Inspector	Kathryn	Gruver					
Name(s)							
CBI Name and	Remo	val Time					
Vendor	Start	End		Number of personnel			
Storm Sentinel	10:52	10:56	2				
Observations			Photos				
Describe conte	nts of cate	h basin					
insert							
Standing water							
Very little debri	s in CBI						
Describe condi	tion of cat	tch basin	51				
insert				ZAT			
The insert is clo	gged.			N A STATE OF THE S			
Overflows clogg	ged with d	ebris					
				Start			
Describe conte	nts and co	ndition		AND THE WORK COMMISSION SHOULD SHOW COME SHOULD SHOULD SHOW COME SHOULD SHOW COME SHOULD SHOW COME SHOULD SHOW COME SHOULD SHOULD SHOW COME SHOW COME SHOULD SHOW COME SHOW COME SHOULD SHOW COME SHOW COME SHOULD SHOW COME SHOW COME SHOULD SHOULD SHOULD SHOW COME SHOULD SHOULD SHOULD SHOULD SHOULD SHOW COME SHOULD SHOULD SHOULD SHOULD SHOULD SHOULD SHOULD SHOULD			
of catch basin	· an		Le vi Verse				
Clean, no debris	in CB			The Walter of the Control of the Con			
Special Equipn	nent Requ	ired for R	emoval				
No special equip	nment ren	noved by or	ne nerson				
140 special equip	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	noveu by 01	ic person				

Reason for removal Clogged unit not functional

Catch Basin Inserts for Ohio Roadways

Appendix C Laboratory CBI Performance Evaluation Testing

APPENDIX C:

LABORATORY CBI PERFORMANCE EVALUATION TESTING

ADSORB-IT™ - STORMWATER BMP PRODUCTS

The Adsorb-It™ is a basket-type catch basin insert consisting of a heavy-duty PVC coated wire mesh steel basket supported by a rigid stainless steel frame. The basket is also lined with a filtration fabric material. The basket has bypass openings on the two sides of the device and is equipped with heavy-duty wire lifting cables that are supported under the frame for easy removal. The Adsorb-It™ products that were shipped to AU-ESCTF for large-scale laboratory testing were undersized and did not fit appropriately into the ODOT Type 3A catch basin. Therefore, a plywood frame was constructed to fit inside the lip of the catch basin frame. The plywood frame was supported by 2x4's and was sealed to the existing catch basin frame using a silicon caulking to prevent water from passing between the two frames. This modification can be seen in Figure C-1(a).


Photos of the Adsorb-It™ installed in the testing catch basin can be seen in Figure C-1.


Figure C-1: Pre-test installation for Adsorb-It™.





(a) location 1







(e) location 5


(f) location 6

Figure C-2(a-c) shows images of the Adsorb-It™ during testing with OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only. It was observed during the tests that a small amount of influent water was flowing into the catch basin and directly exiting through the bypass openings untreated, which could have had an effect on sediment removal efficiency.

Figure C-2: Adsorb-It™ during testing using various test methods and soil types.



0.06 cfs 0.12 cfs 0.18 cfs
(a) sheet flow testing with OK110 silica sand



0.06 cfs 0.12 cfs 0.18 cfs

(b) direct discharge testing with OK110 silica sand



0.06 cfs 0.12 cfs 0.18 cfs

(c) direct discharge testing with sandy loam soil

Table C-1(a-c) summarizes performance evaluation data for the Adsorb-It™ when introducing OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only. The 80% sediment removal target was exceeded at two of the three low flow tests, and also at the medium flow test when introducing OK110 silica sand under direct discharge conditions. However, performance did decrease as flow rate increased.

Table C-1: Summary of Performance Data for Adsorb-It™ for Various Test and Soil Types

(a) Sheet Flow Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	7.02 (-0.85%)	13.78 (-2.68%)	21.77 (2.50%)
Sediment Captured, lb	5.42	8.87	10.60
Sediment Retention, %	77.2	64.4	48.7
Time to Overflow, min	-	27	15

(b) Direct Discharge Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	7.40 (4.52%)	14.43 (1.91%)	22.49 (5.89%)
Sediment Captured, lb	7.12	11.90	14.46
Sediment Retention, %	96.2	82.5	64.3
Time to Overflow, min	-	32	18

(c) Direct Discharge Testing with Sandy Loam Soil

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	2.87 (-1.4%)	5.97 (2.6%)	8.68 (-0.6%)
Sediment Captured, lb	2.45	3.83	4.38
Sediment Retention, %	85.4	64.2	50.5
Time to Overflow, min	46	18	12

DRAINPAC™ - UNITED STORM WATER INC.

DrainPac™ consists of a metal basket lined with a filter fabric bag. A plastic netting attached to the metal frame also surrounds the fabric bag in order to provide structural support. The metal bag is equipped with large bypass openings on all four sides of the device. The DrainPac™ insert removes pollutants by both filtering the water through the mesh material and allowing particles to settle out while the influent accumulates in the bag prior to discharge. DrainPac™ insert variations include models for drop inlets, curb inlets, and round inlets, and can be made to specific sizes. The filter fabric material of the bag has been specified to have a maximum flow through rate of 0.31 cfs/ft², per manufacturer claims.

Photos of the DrainPac™ installed in the testing catch basin can be seen in Figure C-3.

Figure C-3: Pre-test installation for DrainPac™.



A common issue with the DrainPac™ was that many of the products were slightly damaged when shipped to AU-ESCT. When many of the products were removed from their respective shipping boxes, it was found that corners of the frame had been bent, as opposed to lying flat. These bent corners then create gaps between the CBI frame and the inlet frame which allow water to flow past the CBI untreated. Bent edges were attempted to be straightened before installation in order to mitigate the issue. Figure C-4 provides an example of two of the damaged CBIs. All damages are documented in the test reports included in Appendix C of this report.

Figure C-4: Bent edges of DrainPac™ frame.



(a) 0.06 ft³/s with OK110 under sheet flow



(b) 0.18 ft³/s with OK110 under sheet flow

Figure C-5(a-c) shows images of the DrainPac[™] during testing with OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only. It was observed during the tests that a small amount of influent water was flowing into the catch basin and directly exiting through the bypass openings untreated, which could have had an effect on sediment removal efficiency.

Figure C-5: DrainPac™ during testing using various test methods and soil types.







0.06 cfs

0.12 cfs

0.18 cfs

(a) sheet flow testing with OK110 silica sand







0.06 cfs

0.12 cfs

0.18 cfs

(b) direct discharge testing with OK110 silica sand







0.06 cfs

0.12 cfs

0.18 cfs

(c) direct discharge testing with sandy loam soil

Table C-2(a-c) summarizes performance evaluation data for the DrainPac™ when introducing OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only. The 80% sediment removal target was reached during the low flow test when introducing OK110 silica sand under direct discharge conditions. However, retention values were lower when introducing sandy loam and when using sheet flow conditions. This could possibly be accredited to the untreated flow bypassing the CBI due to the bent edges of the frame show in Figure C-4.

Table C-2: Summary of Performance Data for DrainPac™ for Various Test and Soil Types

(a) Sheet Flow Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	7.30 (3.11%)	14.67 (3.60%)	21.90 (3.11%)
Sediment Captured, lb	2.62	6.76	10.31
Sediment Retention, %	36.0	46.1	47.1
Time to Overflow, min	-	47	21

(b) Direct Discharge Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	7.27 (2.68%)	14.04 (-0.85%)	21.62 (1.79%)
Sediment Captured, lb	5.80	9.10	13.56
Sediment Retention, %	79.8	64.8	62.7
Time to Overflow, min	67	25	20

(c): Direct Discharge Testing with Sandy Loam Soil

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	2.98 (2.4%)	5.86 (0.7%)	8.48 (-2.86%)
Sediment Captured, lb	2.03	2.74	3.26
Sediment Retention, %	68.1	46.8	38.4
Time to Overflow, min	27	7	6

FLEXSTORM® - ADVANCED DRAINAGE SYSTEMS

The FlexStorm® has a stainless steel frame that can be custom configured to fit most drainage structures. The frame is equipped with supported handles for installation and removal. The frame also is constructed with large flow bypass openings on all four sides to allow water to bypass the CBI untreated in the event that the influent flow is too great for the CBI to treat effectively, herein referred to as untreated bypass. A clamping mechanism is used to secure replaceable filtration bags to the frame. Woven geotextile filtration bags are lined with carpet fiber material to treat water exiting the bag. The bag also has a more permeable fabric that sits between the filtration bag and the stainless steel frame that allows water to flow through at a higher rate than the filtration bag while still provided some treatment, herein referred to as treated bypass. The FlexStorm® has a manufacturer specified flow capacity of 0.45 ft³/s, but it is not specified whether or not this capacity is based off of clean or sediment laden influent. Photos of the FlexStorm® installed in the testing catch basin can be seen in Figure C-6

Figure C-6: Pre-test installation for FlexStorm®.




(e) location 5

(f) location 6

Figure C-7(a-c) shows images of the FlexStorm® during testing with OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only. The water level inside the CBI reached the treated overflow level for all tests. However, the untreated overflow was only reached at the 44 minute mark of the high flow test using sandy loam soil under direct discharge conditions.

Figure C-7: FlexStorm® during testing using various test methods and soils



cfs 0.12 cfs 0.18
(a) FlexStorm® during sheet flow testing with OK110 silica sand.



(b) FlexStorm® during direct discharge testing with OK110 silica sand



0.06 cfs 0.12 cfs 0.18 cfs

(c) FlexStorm® during direct discharge testing with sandy loam soil

Table C-3(a-c) summarizes performance evaluation data for the FlexStorm® when introducing OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only. Sediment retention percentage was best at the low flow rate when directly discharging influent with OK110 silica sand but was still below the 80% target rate. With the exception of the low flow test under sheet flow conditions, sediment retention values decreased as flow rate increased.

Table C-3: Summary of Performance Data for FlexStorm® for Various Test and Soil Types

(a) Sheet Flow Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	7.52 (6.21%)	14.89 (5.16%)	21.51 (1.27%)
Sediment Captured, lb	3.85	8.46	10.01
Sediment Retention, %	51.2	56.8	46.5
Time to Overflow, min	46	24	9

(b) Direct Discharge Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	7.29 (2.97%)	14.37 (1.48%)	22.70 (6.87%)
Sediment Captured, lb	5.20	7.21	8.25
Sediment Retention, %	71.3	50.2	36.3
Time to Overflow, min	33	10	7

(c) Direct Discharge Testing with Sandy Loam Soil

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	2.95 (1.4%)	5.33 (-8.4%)	9.33 (6.9%)
Sediment Captured, lb	1.93	3.11	4.10
Sediment Retention, %	65.4	58.3	43.9
Time to Overflow, min	35	20	11


FLO-GARD® PLUS - OLD CASTLE


The Flo-Gard® Plus has characteristics of both a bag-type and basket-type catch basin insert. A plastic, large-mesh basket structure supports a woven filter fabric liner that is attached to a stainless steel frame. The frame is equipped with bypass openings on all four sides. The bypass openings also have a roof structure above them, preventing flow and contaminants from bypassing the device when entering the device from above, ensuring the only time flow exits through the bypass is when the CBI has become overloaded.

Photos of the Flo-Gard® Plus installed in the testing catch basin can be seen in Figure C-8.


Figure C-8: Pre-test installation for Flo-Gard® Plus.












(e) location 5


(f) location 6

Figure C-9(a-c) shows images of the Flo-Gard® during testing with OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only. A reoccurring issue with the Flo-Gard® Plus was that there was never any impoundment of flow within the CBI. It appeared that the mesh opening size of the filter bag had a high flow through rate, inhibiting the CBI's ability to impound flow. The lack of impoundment greatly impaired the sediment removal efficiency of the product.


Figure C-9: Flo-Gard® during testing using various test methods and soil types.



(a) sheet flow testing with OK110 silica sand



(b) direct discharge testing with OK110 silica sand



(c) direct discharge testing with sandy loam soil

Table C-4(a-c) summarizes performance evaluation data for the Flo-Gard® when introducing OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only. Sediment retention values showed no potential for meeting the 80% target removal rate, which is most likely due to the high-flow through rate of the fabric.

Table C-4: Summary of Performance Data for Flo-Gard® for Various Test and Soil Types

(a) Sheet Flow Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	6.99 (-1.27%)	14.68 (3.67%)	23.36 (9.98%)
Sediment Captured, lb	0.51	0.15	0.16
Sediment Retention, %	7.3	1.0	0.7
Time to Overflow, min	-	-	-

(b) Direct Discharge Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	7.40 (4.52%)	12.2 (-13.84%)	20.08 (-5.46%)
Sediment Captured, lb	0.77	0.10	0.44
Sediment Retention, %	10.4	0.8	2.2
Time to Overflow, min	-	-	-

(c) Direct Discharge Testing with Sandy Loam Soil

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	2.91 (0.00%)	5.67 (-2.58%)	8.94 (2.41%)
Sediment Captured, lb	0.72	1.12	1.97
Sediment Retention, %	24.7	19.8	22.0
Time to Overflow, min	-	-	-

GULLYWASHER©

The Gullywasher© Commercial Duty Frame Mounted Insert consists of a nonwoven geotextile filter fabric mounted on a rectangular metal frame. The bag has sewn-in tabs that hold the frame into proper position, ensuring that the bag does not move around and become unsupported under heavy loading. The bag is also supported by nylon straps that wrap under the bottom of the bag and support loads when the bag is full. Nylon straps are also placed on the inside of the bag as removal handles. Finally, the bag is equipped with overflow openings on both the upstream and downstream side of the CBI.

Photos of the Gullywasher© installed in the testing catch basin can be seen in Figure C-10.


Figure C-10: Pre-test installation for Gullywasher©.



Gullywasher© CBIs were shipped to AU-ESCTF with extra fabric around the frame, and installation instructions directed the installer to cut the fabric to fit as needed. The Gullywasher© before and after modifications can be seen in Figure C-11.

Figure C-11: Gullywasher© modifications.









(b) Gullywasher© after modifications

It was observed during the low flow rate direct discharge test with OK110 silica sand that some influent water was flowing into the catch basin and directly exiting through the downstream bypass opening untreated, which could impact sediment removal performance. This was not an observed during other tests. Figure C-12(a-c) shows images of the Gullywasher© during testing with OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only.

Figure C-12: Gullywasher© during testing using various test methods and soil types.



(a) sheet flow testing with OK110 silica sand



(b) direct discharge testing with OK110 silica sand



(c) direct discharge testing with sandy loam soil

Leaks were observed during the two high flow tests with OK110 silica sand that could have impacted sediment removal efficiency. The leaks can be seen in Figure C-13.

Figure C-13: Leaks in Gullywasher© at high flow rate tests





(a) sheet flow with OK110 silica sand

(b) direct discharge with OK110 silica sand

Table C-5(a-c) summarizes performance evaluation data for the Gullywasher© when introducing OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only. During the testing with OK110 silica sand under sheet flow conditions, there was more sediment captured during the medium flow test than the high flow test, despite the fact that more sand was introduced during the high flow test. One possible explanation for this is that the leak shown in Figure C-13(a) impacted performance. Sediment retention decreased as flow rate increased for all test methods. The Gullywasher© was one of the few products that actually performed slightly better under sheet flow conditions than under direct discharge conditions. One possible explanation for this would be that overflow was reached quicker during direct discharge tests than with sheet flow tests, meaning that a larger volume of water was able to be treated under sheet flow than direct discharge before passing the CBI.

Table C-5: Summary of Performance Data for Gullywasher© for Various Test and Soil Types

(a) Sheet Flow Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	7.47 (5.51%)	14.45 (2.05%)	18.63 (-12.29%)
Sediment Captured, lb	5.66	8.49	7.64
Sediment Retention, %	75.8	58.8	41.0
Time to Overflow, min	42	11	6

(b) Direct Discharge with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	7.66 (8.19%)	14.68 (3.67%)	23.34 (9.89%)
Sediment Captured, lb	5.14	7.01	8.34
Sediment Retention, %	67.1	47.8	35.7
Time to Overflow, min	21	7	3


(c) Direct Discharge Testing with Sandy Loam Soil

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	2.92 (0.3%)	6.03 (3.6%)	8.84 (1.26%)
Sediment Captured, lb	1.51	2.30	2.95
Sediment Retention, %	51.7	38.1	33.4
Time to Overflow, min	16	6	5

STORM SENTINEL® - ENPAC GROUP

The Storm Sentinel® is a bag-type CBI made out of a nonwoven geotextile fabric that is supported by an adjustable steel wire frame. The bag contains three openings to allow influent to bypass the bag, preventing flow from backing onto the street in the event that the bag becomes overloaded or the fabric is clogged. The Storm Sentinel® is equipped with two nylon handles for easy maintenance and removal. Ranging in dimensions from 16 by 20 in. to 28 by 36 in. and weighing two pounds, the Storm Sentinel® has a load capacity of up to 125 lb, and can handle flow rates up to 1.11 ft³/s based upon manufacturer claims, which do not specify whether this capacity is based upon clean or sediment-laden flow.

Photos of the Storm Sentinel® installed in the testing catch basin can be seen in Figure C-14. Figure C-14: Pre-test installation of Storm Sentinel®.




It was observed during the high flow rate tests that the influent flow caused the filter bag to move around the adjustable frame, creating small gaps to open at the entrance to the CBI. The gaps, though small, could allow influent water to bypass the CBI completely and enter the catch basin untreated. The position of the bypass openings also allowed for some flow to directly exit through the openings untreated. These issues can be seen in Figure C-15.

Figure C-15: Openings in Storm Sentinel® allow untreated bypass.



Figure C-16(a-c) shows images of the Storm Sentinel® during testing with OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only.

Figure C-16: Storm Sentinel® during testing using various test methods and soil types.



(a) sheet flow testing with OK110 silica sand



0.06 cfs 0.12 cfs 0.18 cfs

(b) direct discharge testing with OK110 silica sand



0.12 cfs

(c) direct discharge testing with sandy loam soil

Table C-6(a-c) summarizes performance evaluation data for the Storm Sentinel® when introducing OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only. Sediment retention was best when introducing OK110 silica sand under direct discharge, low flow conditions, and sediment retention values decreased as flow rate increased.

Table C-6: Summary of Performance Data for Storm Sentinel® for Various Tests and Soil Types

(a) Sheet Flow Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	7.40 (4.52%)	13.94 (-1.55%)	21.88 (3.01%)
Sediment Captured, lb	4.38	5.72	4.75
Sediment Retention, %	59.2	41.0	21.7
Time to Overflow, min	27	10	3

(b) Direct Discharge Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	7.76 (9.60%)	14.66 (3.53%)	22.46 (5.74%)
Sediment Captured, lb	5.53	5.65	5.83
Sediment Retention, %	71.3	38.5	26.0
Time to Overflow, min	16	5	3

(c) Direct Discharge Testing with Sandy Loam Soil

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	3.05 (4.81%)	5.71 (-1.89%)	8.59 (-1.60%)
Sediment Captured, lb	1.27	1.72	1.74
Sediment Retention, %	41.6	30.1	20.3
Time to Overflow, min	28	6	4

TRITON™ - CONTECH ENGINEERED SOLUTIONS

The Triton™ is a cartridge-type catch basin insert. The Triton™ base fits down into the catch basin and is sealed against the catch basin frame, preventing water from exiting the catch basin without passing through the replaceable filter cartridge that is installed on top of the base. The filter cartridge consists of a fine mesh medium, enclosed by a stainless steel housing that prevents debris from damaging the filter media. The cartridge also has a bypass opening at the top to allow water to exit the catch basin untreated by the filter cartridge in the event that the cartridge is too clogged to allow water to pass through adequately. While all other CBI's under consideration hung from the lip of the catch basin frame, allowing water to flow into the CBI, the Triton™ is designed to be supported from below, and allow water to impound around the device. Therefore, an acrylic box was constructed to simulate the sides of the catch basin. A large hole was cut into the bottom of the box to allow water to exit once it passed through the filter media of the CBI. A Triton™ platform was installed into the bottom of the box and sealed appropriately using a foam caulking to ensure water did not leave the box without passing through the filter.

Photos of the Triton™ installed in the testing catch basin can be seen in Figure C-17.

Figure C-17: Pre-test installation for Triton™.




(e) location 5


(f) location 6

Figure C-18 shows images of the Triton™ during testing with OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only.


Figure C-18: Triton™ during testing using various test methods and soil types.



(a) sheet flow testing with OK110 silica sand



(b) direct discharge testing with OK110 silica sand



(c) direct discharge testing with sandy loam soil

Table C-7 summarizes performance evaluation data for the Triton™ when introducing OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only. The water level did not reach the bypass mechanisms for any of the tests. However, maximum impoundment depths are recorded in Table C-7. Sediment retention values did not meet the 80% target removal rate.

Table C-7: Summary of Performance Data for Triton™ for Various Test and Soil Types

(a) Sheet Flow Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	7.27 (2.68%)	13.49 (-4.73%)	19.90 (-6.31%)
Sediment Captured, lb	4.32	6.61	8.99
Sediment Retention, %	59.4	49.0	45.2
Time to Overflow, min	-	-	-
Max Impoundment, in.	9.5	14.0	15.25

(b) Direct Discharge Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	7.23 (2.12%)	13.01 (-8.12%)	21.03 (-0.99%)
Sediment Captured, lb	4.95	7.77	9.44
Sediment Retention, %	68.5	59.7	44.9
Time to Overflow, min	-	-	-
Max Impoundment, in.	13.75	15.0	15.5

(c) Direct Discharge Testing with Sandy Loam Soil

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	2.75 (-5.5%)	5.60 (-3.8%)	7.59 (-13.0%)
Sediment Captured, lb	1.11	2.15	2.76
Sediment Retention, %	40.4	38.4	36.4
Time to Overflow, min	-	-	-
Max Impoundment, in.	14.5	14.5	14.75

WATER QUALITY SOLUTIONS

The Water Quality Solutions (WQS) is a tray-type catch basin insert consisting of a hard-plastic outer shell with layers of filters stacked inside for a staged-treatment approach. The upper half of the CBI consists of four plastic mesh filters, each decreasing in mesh size deeper into the shell. The bottom half of the CBI consists of two fine mesh metal screens. The trays are arranged so that larger particles are captured near the top of the device, and finer particles are removed through the metal screens at the bottom of the device before treated flow exits the WQS through large holes in the bottom of the hard-plastic shell. Unlike other CBI's under consideration, the WQS has no bypass mechanism.

Photos of the WQS installed in the testing catch basin can be seen in Figure C-19.

Figure C-19: Pre-test installation for WQS.



(e) location 5

(f) location 6

Figure C-20 shows images of the WQS during testing with OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only. Pictures are not available for the low and high flow rate tests in Figure C-20(a) during the sheet flow testing with OK110 silica sand due to a corrupted file storage device. It was noticed during installation that the plastic lip that supports the WQS on the catch basin frame may not have been strong enough to support the heavy weight of the CBI, causing the lip to become distorted, and allowing some flow to get around the CBI untreated. This can be seen by water flowing down the outside of the filter in Figure C-20(b).

Figure C-20: WQS during testing using various test methods and soil types.

NO PICTURE AVAILABLE



NO PICTURE AVAILABLE

0.06 cfs

0.12 cfs

0.18 cfs

(a) sheet flow testing with OK110 silica sand







0.06 cfs

0.12 cfs

0.18 cfs

(b) direct discharge testing with OK110 silica sand







0.06 cfs

0.12 cfs

0.18 cfs

(c) direct discharge testing with sandy loam soil

Because the WQS has no bypass mechanism, during the medium flow test using sandy loam soil under direct discharge conditions, the water level impounded inside the CBI until it was just below the bottom of the grate. However, during the 0.18 cfs test, water flooded onto the platform by the 15 minute mark. By the 57 minute mark, water flooded the platform to the point of overtopping the 6" simulated curb. Images of the flooded platform can be seen in Figure C-21.

Figure C-21: Flooding during WQS high flow test using sandy loam soil under direct discharge conditions.







(a) from side

(b) from downstream

(c) from upstream

Table C-8(a-c) summarizes performance evaluation data for the WQS when introducing OK110 silica sand under sheet flow and direct discharge conditions and sandy loam soil under direct discharge conditions only. While sediment retention values did not meet the 80% target removal rate, it is worth noting that, on average, sediment retention values increased as flow rate increased. This was not common to the other CBIs that were evaluated. While it is impossible to monitor water levels inside the WQS during testing because of the many components inside, one possible explanation is that the low flow rate did not allow water to impound within the device, relying solely on the filter media to remove sediment. During higher flow tests, flow impounded during the tests, allowing particles to be removed via the filter media, and to fall out of suspension due to the impoundment.

Table C-8: Summary of Performance Data for WQS for Various Test and Soil Types

(a) Sheet Flow Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb (% error)	7.48 (5.65%)	14.68 (3.67%)	22.43 (5.60%)
Sediment Captured, lb	0.20	4.00	6.01
Sediment Retention, %	2.7	27.3	26.8
Time to Overflow, min	-	-	-

(b) Direct Discharge Testing with OK110 Silica Sand

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb	7.39 (4.38%)	14.47 (2.19%)	22.58 (6.31%)
Sediment Captured, lb	2.00	7.44	12.18
Sediment Retention, %	27.1	51.4	53.9
Time to Overflow, min	-	-	-

(c) Direct Discharge Testing with Sandy Loam Soil

Flow Rate, cfs	0.06	0.12	0.18
Sediment Introduced, lb	2.81 (-3.44%)	5.85 (0.52%)	8.56 (-1.95%)
Sediment Captured, lb	1.20	2.89	4.32
Sediment Retention, %	42.7	49.4	50.5
Time to Overflow, min	-	-	15

LONGEVITY TESTING

ADSORB-IT™

Four longevity tests of the Adsorb-It™ were conducted using each of the soil types. Overflow was not reached during the L1 test but was reached during the remaining three tests at 40, 4 and 1 minutes when using OK110 silica sand. Overflow occurred during all four tests with sandy loam soil at 60 minutes for the L1 test, 2 minutes for the L2 test, and less than on minute for both the L3 and L4 tests. The rapid difference in overflow times between L1 and L2 tests indicate that the soils severely blinded the filter media, inhibiting flow-through rate and causing the device to fill quickly in subsequent tests.

Table C-9 summarizes longevity data for the Adsorb-It™ when introducing OK110 silica sand and sandy loam. During the L1 test with OK110 silica sand, the Adsorb-It™ retained 95.6% of the introduced sediment, which was similar to the 96.1% sediment retention determined when evaluating the Adsorb-It™ under similar conditions during performance evaluation testing. The Adsorb-It™ was then tested again and retained 88.4% of the sediment introduced during the L2 test, bringing the cumulative retention to 92.0%. An L3 test was conducted with a sediment retention of 72.4% and a cumulative retention of 85.7% across the three tests. While the sediment retention performance for the L3 test was below the 80% rate, the cumulative retention was still well above, so it was determined that the Adsorb-It™ would be tested a fourth time, resulting in an individual retention of 55.7% and a cumulative retention of 78.9% falling below the required threshold, concluding longevity testing.

During the L1 test with sandy loam soil, the Adsorb-It™ retained 86.8% of the sediment introduced, which was similar to the sediment retention of 85.4% determined when using sandy loam soil at the low flow rate during performance evaluation testing. The Adsorb-It™ was then tested again and retained 49.8% of the sediment introduced during the L2 test, bringing the cumulative retention to 68.4%. An L3 test was conducted with a sediment retention of 53.6% and a cumulative retention of 63.5% across the three tests. During the testing of the L4 test, the Adsorb-It™ retained 53.8% of the sediment introduced for a cumulative retention of 61.6%, concluding longevity testing for the Adsorb-It™. It is worth noting that the performance across the L2, L3, and L4 tests were very similar, and had similar overflow times. The results indicate that while the Adsorb-It™ is capable of reaching the 80% sediment retention rate with the sandy loam soil, maintenance must occur frequently in order to continue performance.

Table C-9: Longevity Testing for Adsorb-It™

(a) Longevity Testing with OK110 Silica Sand							
	L1	L2	L3	L4			
Sediment Introduced, Ib	7.04	7.09	6.64	6.10			
(% error)	(-0.6%)	(0.1%)	(-6.2%)	(-13.8%)			
Sediment Captured, lb	6.73	6.27	4.81	3.40			
Sediment Retention, %	95.6	88.4	72.4	55.7			
Cumulative Retention, %	95.6	92.0	85.7	78.9			
Time to Overflow, min	-	40	4	1			
(b) Longe	vity Testing wit	h Sandy Loar	n Soil				
	L1	L2	L3	L4			
Sediment Introduced, lb	2.66	2.63	2.63	1.97			
(% error)	(-8.6%)	(-9.6%)	(-9.63%)	(-32.3%)			
Sediment Captured, lb	2.31	1.31	1.41	1.06			
Sediment Retention, %	86.8	49.8	53.6	53.8			
Cumulative Retention, %	86.8	68.4	63.5	61.6			
Time to Overflow, min	60	2	1	1			

Figure C-22 shows sediment bypassing increases, or is not being captured at the same rate, over time by the Adsorb-It™, indicating a decline in performance and a need for maintenance.




Figure C-22: Sediment retention percentage for Adsorb-It™ over longevity tests.

DRAINPACTM

Eight longevity tests were conducted on the DrainPac™ using OK110 silica sand. Overflow was not reached during the L1 test, but was reached during the remaining tests at 65, 7, 14, 13, 8, 3, and 11 minutes, respectively. Tests L3 through L8 had little variance between overflow times, indicating that there was little change in flow-through rate after the blinding conditions were reached. Two longevity tests were conducted using the sandy loam soil, with overflow at 33 and 4 minutes, respectively. Overflow was reached much quicker during sandy loam soil tests than with OK110 silica sand, indicating that the high clay content in the sandy loam soil played a role in blinding the material more than the high sand content of the OK110 silica sand.

Table C-10 summarizes longevity data for the DrainPac[™] when introducing OK110 silica sand and sandy loam. During the L1 test with OK110 silica sand, the DrainPac[™] retained 80.0% of the introduced sediment, which was similar to the 79.8% sediment retention determined when evaluating the Adsorb-It[™] under similar conditions during performance evaluation testing. The DrainPac[™] was then tested again and retained 81.7% of the sediment introduced during the L2 test, bringing the cumulative retention to 80.9%. An L3 test was conducted with a sediment retention of 68.4% and a cumulative retention of 76.7% across the three tests. Sediment retention fluctuated with each test, increasing in retention, decreasing in retention, and continuing. For this reason, longevity testing was expanded to eight tests in order to further observe the pattern and ensure that the DrainPac[™] would not reach the 80% target in another test. After the eighth test, it was determined that longevity testing could be concluded.

During the L1 test with sandy loam soil, the DrainPac[™] retained 60.3% of the sediment introduced, which was similar to the sediment retention of 68.1% determined when using sandy loam soil at the low flow rate during performance evaluation testing. The DrainPac[™] was then tested again and retained 45.5% of the sediment introduced during the L2 test, bringing the cumulative retention to 53.0%. At this point, it was determined that longevity testing could be concluded. From the longevity testing, the DrainPac[™] did not meet the requirement for retaining 80% of the introduced sediment under the sandy loam soil testing conditions.

Table C-10: Longevity Testing for DrainPac™

(a) Longevity Testing with OK110 Silica Sand								
	L1	L2	L3	L4	L5	L6	L7	L8
Sediment Introduced, lb	6.74	7.55	7.35	6.84	7.10	6.84	7.15	7.17
(% error)	(-4.8%)	(6.6%)	(3.8%)	(-3.4%)	(0.3%)	(-3.4%)	(1.0%)	(1.3%)
Sediment Captured, lb	5.39	6.17	5.03	5.34	2.88	4.82	4.34	4.61
Sediment Retention, %	80.0	81.7	68.4	78.1	40.6	70.5	60.7	64.3
Cumulative Retention, %	80.0	80.9	76.7	77.0	69.7	69.8	68.5	68.0
Time to Overflow, min		65	7	14	13	8	3	11
(b)	Longevity	/ Testing	with Sa	ndy Loan	n Soil	_		_
	L1	L2	L3	L4	L5	L6	L7	L8
Sediment Introduced, lb	3.05	2.97						
(% error)	(4.8%)	(2.1%)	-	-	-	-	-	-
Sediment Captured, lb	1.84	1.35	-	-	-	-	-	-
Sediment Retention, %	60.3	45.5	-	-	-	-	-	-
Cumulative Retention, %	45.5	53.0	-	-	-	-	-	-
Time to Overflow, min	33	4	-	-	-	-	-	-

Figure C-23 was included to further analyze the DrainPac™ over the longevity tests. Sediment capture rate decreases overtime while bypass increases, indicating a decline in performance and a need for maintenance. Further analysis of Figure C-23 also shows that, while sediment retention appeared volatile when considering the percentages individually for each test, it can be seen that sediment retention is actually fairly linear across all eight tests, with the exception of the one L5 tests, which could be considered an outlier.




Figure C-23: Sediment retention percentage for DrainPac™ over longevity tests.

Another observation during the eight longevity tests was the wear of the device after significant loading. A total of 56.74 lb of sediment was introduced with 38.58 lb of sediment captured over the eight longevity tests. A large portion of this sediment was stored between the metal basket frame and the filter fabric lining, putting excess loading on the bag which started causing the plastic netting to pull away from its anchor point. The damage can be seen in Figure C-24 from both the front and side views.



(a) front view (b) side view Figure C-24: Damage to DrainPac™ after eight longevity tests.

FLEXSTORM®

Four longevity tests with OK110 silica sand were conducted with the FlexStorm®. While the water level inside the FlexStorm® never reached the untreated bypass mechanism built into the FlexStorm® frame, treated bypass was reached during the four tests at 40, 29, 30, and 31 minutes, respectively. The FlexStorm® also underwent two longevity tests with sandy loam soil. Again, water level inside the FlexStorm® never reached the untreated bypass mechanism built into the FlexStorm® frame. However, treated bypass was reached during the two tests at 45 minutes and 1 minute, respectively. The FlexStorm® was affected differently by the two soil types, based upon the difference in overflow times. When using the OK110 silica sand, there was little change in overflow time, especially between the final three tests. However, with the sandy loam soil, overflow was reached much faster after the first test. This is likely due to the higher clay content in the sandy loam soil. The clay particles can cause the material to blind, or clog, which can reduce the flow-through rate of the material after the initial test.

Table C-11 summarizes longevity data for the FlexStorm® when introducing OK110 silica sand and sandy loam. Note, test names are abbreviated, whereas L1 is longevity test 1, L2 is longevity test 2 and so on. During the L1 test with OK110 silica sand, the FlexStorm® retained 88.3% of the introduced sediment, which was higher than the 71.3% sediment retention determined when evaluating the FlexStorm® under similar conditions during performance evaluation testing. The FlexStorm® was then tested again, with the 7.17 pounds of sediment collected from the L1 tests still contained within the product and retained 64.5% of the sediment introduced during the L2 test. However, while the 64.5% was below the desired 80% retention, the cumulative retention percentage between the two tests was still at 76.8%. Therefore, it was determined that an L3 test would be conducted, which resulted in a 58.8% sediment retention, and a cumulative retention of 71.1% across the three tests. While the sediment retention performance did decrease from L2 to L3, the decrease was small. Finally, L4 test was conducted to strain the CBI until a significant drop in performance was seen. The FlexStorm® only retained 31.2% of the introduced sediment during the L4 test, leaving the cumulative retention at 61.3%. At this point, it was determined that longevity testing could be concluded.

During the L1 test with sandy loam soil, the FlexStorm® retained 64.8% of the sediment introduced, similar to the 65.4% sediment retention when using sandy loam soil at the low flow rate during performance evaluation testing. While this performance is already below the 80% target rate, an L2 test was performed to assure that the 80% rate would not be reached in a following event. During the L2 test, only 49.7% of the introduced sediment was retained, for a cumulative retention of 57.0% at which point longevity testing was concluded. The results from longevity testing show that the FlexStorm® is not capable of meeting the 80% sediment removal rate under the testing conditions.

Table C-11: Longevity Testing for FlexStorm®

(a) Longevity Testing with OK110 Silica Sand							
	L1	L2	L3	L4			
Sediment Introduced, lb	8.12	7.60	7.21	7.50			
(% error)	(14.7%)	(7.3%)	(1.8%)	(5.9%)			
Sediment Captured, lb	7.17	4.90	4.24	2.34			
Sediment Retention, %	88.3	64.5	58.8	31.2			
Cumulative Retention, %	88.3	76.8	71.1	61.3			
Time to Overflow, min	40	29	31	30			
(b) Longevity Te	sting with	Sandy Lo	oam Soil				
	L1	L2	L3	L4			
Sediment Introduced, Ib	2.70	2.90					
(% error)	(-7.2%)	(-0.3%)					
Sediment Captured, lb	1.75	1.44					
Sediment Retention, %	64.8	49.7					
Cumulative Retention, %	64.8	57.0					
Time to Overflow, min	45	1					

Figure C-25 further analyzes the FlexStorm® performance over the longevity tests. Notice the difference between the sediment introduced and sediment capture increases with each test, indicating a decline in performance and a need for maintenance.




Figure C-25: Sediment retention percentage for FlexStorm® over longevity tests.

FLO-GARD® PLUS

The Flo-Gard® Plus was only tested once per soil type for longevity because of the low sediment retention that was verified when compared to performance testing results. Similar to performance evaluation tests, there was little to no impoundment within the CBIs and no overflow.

Table C-12 summarizes longevity data for the Flo-Gard® Plus when introducing OK110 silica sand and sandy loam. During the L1 test with OK110 silica sand, the Flo-Gard® Plus retained 2.3% of the introduced sediment, which was similar to, but slightly lower than, the 10.4% sediment retention determined when evaluating the Flo-Gard® Plus under similar conditions during performance evaluation testing. During the L1 test with sandy loam soil, the Flo-Gard® Plus retained 18.0% of the sediment introduced, which was similar to the sediment retention of 24.7% determined when using sandy loam soil at the low flow rate during performance evaluation testing.

Table C-12: Longevity Testing for Flo-Gard® Plus

(a) Longevity Testing with OK1	10 Silica Sand
	L1
Sediment Introduced, lb	6.91
(% error)	(-2.4%)
Sediment Captured, lb	0.16
Sediment Retention, %	2.3
Cumulative Retention, %	2.3
Time to Overflow, min	_
(b) Longevity Testing with Sar	ıdy Loam Soil
(b) Longevity Testing with San	idy Loam Soil L1
(b) Longevity Testing with San Sediment Introduced, lb	
	L1
Sediment Introduced, lb	2.72
Sediment Introduced, lb (% error)	L1 2.72 (-6.5)
Sediment Introduced, lb (% error) Sediment Captured, lb	2.72 (-6.5) 0.49

Sediment retention and cumulative performance graphs were not developed for Flo-Gard® Plus results because there was only one data point for each metric on each graph.

GULLYWASHER©

Longevity testing of the Gullywasher© using OK110 silica sand was conducted over three tests. Overflow was reached during the three tests at 24, 7 and 2 minutes, respectively. Longevity testing with sandy loam soil was concluded after two tests, with overflow times of 26 minutes and 1 minute, respectively. The difference in overflow times from L1 to L2 indicate that sandy loam soil severely blinded the fabric after the first tests, inhibiting flow-through rate and causing the CBI to fill to the overflow point very quickly. It can be seen in Figure C-26 that the flow coming through the bypass during the L2 test was much more severe than the flow exiting the bypass during the L1 test.



(a) L1 (b) L2 Figure C-26: Gullywasher© during longevity testing with sandy loam soil.

Table C-13 summarizes longevity data for the Gullywasher© when introducing OK110 silica sand and sandy loam. During the L1 test with OK110 silica sand, the Gullywasher© retained 75.9% of the introduced sediment, which was similar to, but slightly higher than, the 67.1% sediment retention determined when evaluating the Gullywasher© under similar conditions during performance evaluation testing. The Gullywasher© was then tested again, with the 5.81 pounds of sediment collected from the L1 test and retained 64.9% of the sediment introduced during the L2 test, bringing the cumulative retention to 70.4%. An L3 test was conducted with a sediment retention of 50.8% and a cumulative retention of 64.2% across the three tests. At this point, it was determined that longevity testing could be concluded. While the Gullywasher© never did actually reach the 80% sediment retention target, results from the testing show the potential to perform near this threshold under these testing conditions. However, the longevity data can also be used to conclude that the Gullywasher© would have to be maintained after almost every small storm event in order to continue performance.

During the L1 test with sandy loam soil, the Gullywasher© retained 53.1% of the sediment introduced, which was similar to the sediment retention of 51.7% determined when using sandy loam soil at the low flow rate during performance evaluation testing. While this performance is already below the 80% target rate, an L2 test was performed assure that the 80% rate would not be reached in a following event. During the L2 test, only 39.8% of the introduced sediment was retained, for a cumulative retention of 46.9%, and longevity testing was concluded. The results from longevity testing show that the Gullywasher© is not capable of meeting the 80% sediment removal rate under the testing conditions.

Table C-13: Longevity Testing for Gullywasher©

(a) Longevity Testing with OK110 Silica Sand							
	L1	L2	L3				
Sediment Introduced, lb	7.65	7.54	7.12				
(% error)	(8.1%)	(6.5%)	(0.6%)				
Sediment Captured, lb	5.81	4.89	3.62				
Sediment Retention, %	75.9	64.9	50.8				
Cumulative Retention, %	75.9	70.4	64.2				
Time to Overflow, min	24	7	2				
(b) Longevity Test	ing with Sand	ly Loam Soil					
	L1	L2	L3				
Sediment Introduced, lb	2.90	2.56	-				
(% error)	(-0.3%)	(-12.0%)					
Sediment Captured, lb	1.54	1.02	-				
Sediment Retention, %	53.1	39.8	-				
Cumulative Retention, %	53.1	46.9	-				
Time to Overflow, min	26	1	-				

Figure C-27 shows the difference between the introduced and captured lines is increasing with each test, indicating a decline in performance and a need for maintenance.




Figure C-27: Sediment retention percentage for Gullywasher© over longevity tests.

STORM SENTINEL®

Two longevity tests were conducted on the Storm Sentinel® with both the OK110 silica sand and sandy loam soil. Overflow was reached during the two OK110 silica sand tests at 22 and 13 minutes, and 22 and 21 minutes during the two sandy loam soil tests.

Table C-14 summarizes longevity data for the Storm Sentinel® when introducing OK110 silica sand and sandy loam. During the L1 test with OK110 silica sand, the Storm Sentinel® retained 46.2% of the introduced sediment, which was lower than the 71.3% sediment retention determined when evaluating the Storm Sentinel® under similar conditions during performance evaluation testing. This difference could be contributed to variations in the product material. The Storm Sentinel® was then tested again, with the 3.43 pounds of sediment collected from the L1 tests and retained 44.1% of the sediment introduced during the L2 test, bringing the cumulative retention to 45.2%. Because there was little difference in performance from L1 to L2, and both tests were well below the 80% target rate longevity testing was concluded. The results from longevity testing show that the Storm Sentinel® is not capable of meeting the 80% sediment removal rate under these testing conditions.

During the L1 test with sandy loam soil, the Storm Sentinel® retained 41.6% of the sediment introduced, which was exactly the same sediment retention determined when using sandy loam soil at the low flow rate during performance evaluation testing. While this performance is already below the 80% target rate, an L2 test was performed in order to be sure that the 80% rate would not be reached in a following event. During the L2 test, only 36.0% of the introduced sediment was retained, for a cumulative retention of 38.8%, and longevity testing was concluded. The results from longevity testing show that the Storm Sentinel® is not capable of meeting the 80% sediment removal rate under these testing conditions.

Table C-14: Longevity Testing for Storm Sentinel®

Table 6 11. Longovity Tooting for Gtorm Continue						
(a) Longevity Testing with	OK110 Silica	Sand				
	L1	L2				
Sediment Introduced, lb	7.43	7.43				
(% error)	(4.9%)	(4.9%)				
Sediment Captured, lb	3.43	3.28				
Sediment Retention, %	46.2	44.1				
Cumulative Retention, %	46.2	45.2				
Time to Overflow, min 22 13						
(b) Longevity Testing with	Sandy Loan	n Soil				
	L1	L2				
Sediment Introduced, lb	2.79	2.78				
(% error)	(-4.1%)	(-4.5%)				
Sediment Captured, lb	1.16	1.00				
Sediment Retention, %	41.6	36.0				
Cumulative Retention, %	41.6	38.8				
Time to Overflow, min	22	21				

Figure C-28 shows the difference between the introduced and captured lines is increasing with each test, indicating a decline in performance and a need for maintenance.





Figure C-28: Sediment retention percentage for Storm Sentinel® over longevity tests.

TRITONTM

Two longevity tests were conducted on the Triton[™] for each soil type. Figure C-29 was included to showcase how the sandy loam soil clogs the cartridge medium and fills the catch basin box faster than with the OK110 silica sand, which also lead to larger impoundment depths, even though untreated bypass was never reached for any of the tests.





(a) L1 test with OK110 silica sand

10 silica sand (b) L1 test with sandy loam soil Figure C-29: Triton™ during longevity testing.

Table C-15 summarizes longevity data for the Triton™ when introducing OK110 silica sand and sandy loam, respectively. During the L1 test with OK110 silica sand, the Triton™ retained 66.2% of the introduced sediment, which was similar to the 68.5% sediment retention determined when evaluating the Triton™ under similar conditions during performance evaluation testing. The Triton™ was then tested again and retained 20.8% of the sediment introduced during the L2 test, bringing the cumulative retention to 42.8%. Results from the longevity testing show that the Triton™ is not capable of meeting performance standards under these testing conditions.

During the L1 test with sandy loam soil, the Triton™ retained 66.7% of the sediment introduced, which was higher than the sediment retention of 40.4% determined when using sandy loam soil at the low flow rate during performance evaluation testing. The Triton™ was then tested again and retained 48.8% of the sediment introduced during the L2 test, bringing the cumulative retention to 57.7%, concluding longevity tests since the Triton™ is not capable of retaining 80% of the introduced sediment under these testing conditions.

Table C-15: Longevity Testing for Triton™

(a) Longevity Testing with OK110 Silica Sand					
	L1	L2			
Sediment Introduced, Ib	6.80	7.22			
(% error)	(-4.0%)	(2.0%)			
Sediment Captured, lb	4.50	1.50			
Sediment Retention, %	66.2	20.8			
Cumulative Retention, %	66.2	42.8			
Time to Overflow, min	-	-			
(b) Longevity Testing with	Sandy Loan	n Soil			
	L1	L2			
Sediment Introduced, lb	2.85	2.87			
(% error)	(-2.1%)	(-1.4%)			
Sediment Captured, lb	1.90	1.40			
Sediment Retention, %	66.7	48.8			
Cumulative Retention, %	66.7	57.7			
Time to Overflow, min	_	_			

Figure C-30 shows that the amount of sediment bypassing, the Triton™ grows with each test, indicating a decline in performance and a need for maintenance.




Figure C-30: Sediment retention percentage for Triton™ over longevity tests.

WATER QUALITY SOLUTIONS (WQS)

Two longevity tests were conducted on the WQS for each soil type. The WQS is not equipped with an overflow bypass mechanism, therefore overflow was not observed during the longevity tests.

Table C-16 summarizes longevity data for the WQS when introducing OK110 silica sand and sandy loam. Target sediment introductions for the tests were 7.08 lb for OK110 tests and 2.91 lb for sandy loam tests. During the L1 test with OK110 silica sand, the WQS retained 41.9% of the introduced sediment, which was higher than the 27.1% sediment retention determined when evaluating the WQS under similar conditions during performance evaluation testing. The WQS was then tested again and retained 55.3% of the sediment introduced during the L2 test, bringing the cumulative retention to 48.7%, concluding longevity testing with the OK110 soil. Results from the longevity testing show that the WQS is not capable of reaching the 80% sediment retention rate under the OK110 soil testing conditions. Unlike most other CBIs tested, the WQS actually performed better at the L2 test than at the L1 test. However, it is worth noting that sediment retention actually increased at higher flow rates with the WQS, suggesting that the product performance may benefit from pre-captured sediment.

During the L1 test with sandy loam soil, the WQS retained 62.7% of the sediment introduced, which was higher than the sediment retention of 42.7% determined when using sandy loam soil at the low flow rate during performance evaluation testing. The WQS was then tested again and retained 55.7% of the sediment introduced during the L2 test, bringing the cumulative retention to 59.2%. At this point, it was determined that longevity testing could be concluded. The results indicate that the WQS is not capable of reaching the 80% sediment retention rate with the sandy loam soil.

Table C-16: Longevity Testing for WQS

3 , 3		
(a) Longevity Testing with	OK110 Silica	Sand
	L1	L2
Sediment Introduced, lb	7.23	7.48
(% error)	(2.1%)	(5.6%)
Sediment Captured, lb	3.03	4.14
Sediment Retention, %	41.9	55.3
Cumulative Retention, %	41.9	48.7
Time to Overflow, min	-	-
(b) Longevity Testing with	Sandy Loan	n Soil
	L1	L2
Sediment Introduced, lb	2.79	2.80
(% error)	(-4.1%)	(-3.8%)
Sediment Captured, lb	1.75	1.56
Sediment Retention, %	62.7	55.7
Cumulative Retention, %	62.7	59.2
Time to Overflow, min	-	-

Figure C-31 shows the distance between the sediment introduction line and the sediment captured line grows greater as testing progresses, indicating a decline in performance and a need for maintenance.




Figure C-31: Sediment retention percentage for WQS over longevity tests.

TOTAL SUSPENDED SOLIDS DATA SUMMARY REPORT

The purpose of this document is to provide ODOT with the total suspended solids (TSS) data acquired during the lab testing phase of the catch basin insert (CBI) research project. During the lab testing phase of the project, conducted at Auburn University's-Erosion & Sediment Control Testing Facility (AU-ESCTF), CBIs were evaluated for both sediment retention percentage, and TSS reduction percentage. Sediment retention percentage was calculated by weighing the CBIs before and after tests to determine the total weight of captured sediment and dividing by the total weight of sediment introduced. During all performance evaluation tests, 32 oz grab samples were taken upstream and downstream of the CBI at five minute intervals over the duration of the 70-minute test. These grab samples were then analyzed for TSS and compared to determine TSS reduction percentage. Figure C-32 to Figure C-39 provide the upstream and downstream TSS data and the corresponding TSS reduction percentage for each test performed on the eight CBI products. TSS samples for longevity tests were only taken for the DrainPac™ using OK110 silica sand, this data can be viewed in Figure C-40.

Upon completion of the performance evaluation tests, it was determined that sediment retention percentage was a truer way of measuring sediment removal capabilities of CBIs. Sediment retention percentage measured performance over the entirety of the test, while TSS reduction percentage was calculated based off of the twenty-eight, 32 oz grab samples taken every five minutes. In order to truly measure performance, TSS samples would have had to been collected at much smaller intervals, increasing the statistical sample size, and therefore providing a much more accurate representation of the true performance.


While sediment retention percentage is the primary performance measure used to evaluate CBIs in the "CBIs for Ohio Roadways" report, this addendum was developed to provide ODOT with the additional TSS data collected. Table C-17 provides a summary of the average TSS reduction values for performance evaluation tests.

Table C-17: Average TSS Reduction Summary of Performance Evaluation Tests (%)


				CT DISCH OK110				OT DISCHARGE ANDY LOAM	
	0.06	0.12	0.18	0.06	0.12	0.18	0.06	0.12	0.18
Adsorb-It™	59.1	67.1	56.6	92.4	85.6	69.0	72.1	70.8	61.1
DrainPac™	45.4	56.4	57.6	76.0	64.9	71.6	63.6	51.7	33.8
FlexStorm®	66.2	42.0	51.1	88.0	39.7	20.6	67.3	71.0	53.6
Flo-Gard® Plus	18.5	11.5	16.7	24.6	15.8	28.8	41.2	27.9	51.3
Gullywasher©	79.4	59.3	33.5	71.9	50.4	39.6	62.4	62.8	23.6
Storm Sentinel®	63.6	25.0	11.2	90.7	76.0	35.1	59.9	53.2	42.2
Triton™	74.7	58.4	47.5	92.1	61.4	45.9	40.0	58.1	49.7
WQS	33.0	38.9	4.3	40.2	48.5	52.0	47.6	66.8	62.9

STORMWATER BMP PRODUCTS ADSORB-IT™ STORMFILTERS


Figure C-32 provides upstream and downstream TSS sample data and the corresponding TSS reduction percentages for each test performed on the Adsorb-It[™]. Target concentrations for upstream samples was 450 mg/L for tests with OK110 silica sand, and 185 mg/L for tests with sandy loam soil.



Avg. TSS reduction = 59.1% Avg. TSS reduction = 67.1% Avg. TSS reduction = 56.6% (a) sheet flow testing with OK110 silica sand



Avg. TSS reduction = 92.4% Avg. TSS reduction = 85.6% Avg. TSS reduction = 69.0% (b) direct discharge testing with OK110 silica sand




Avg. TSS reduction = 72.1% Avg. TSS reduction = 70.8% Avg. TSS reduction = 61.1% (c) direct discharge testing with sandy loam soil


Figure C-32 Avg. TSS analysis data for Adsorb-It™ for performance evaluation tests.

UNITED STORM WATER DRAINPAC™


Figure C-33 provides upstream and downstream TSS sample data and the corresponding TSS reduction percentages for each test performed on the DrainPac[™]. Target concentrations for upstream samples was 450 mg/L for tests with OK110 silica sand, and 185 mg/L for tests with sandy loam soil.



Avg. TSS reduction = 45.4% Avg. TSS reduction = 56.4% Avg. TSS reduction = 57.6% (a) sheet flow testing with OK110 silica sand



Avg. TSS reduction = 76.0% Avg. TSS reduction = 64.9% Avg. TSS reduction = 71.6% (b) direct discharge testing with OK110 silica sand




Avg. TSS reduction = 63.6% Avg. TSS reduction = 51.7% Avg. TSS reduction = 33.8% (c) direct discharge testing with sandy loam soil


Figure C-33 Avg. TSS analysis data for DrainPac™ for performance evaluation tests.

ADVANCED DRAINAGE SYSTEMS FLEXSTORM®


Figure C-34 provides upstream and downstream TSS sample data and the corresponding TSS reduction percentages for each test performed on the FlexStorm®. Target concentrations for upstream samples was 450 mg/L for tests with OK110 silica sand, and 185 mg/L for tests with sandy loam soil.



Avg. TSS reduction = 66.2% Avg. TSS reduction = 42.0% Avg. TSS reduction = 51.1% (a) sheet flow testing with OK110 silica sand



Avg. TSS reduction = 88.0% Avg. TSS reduction = 39.7% Avg. TSS reduction = 20.6% (b) direct discharge testing with OK110 silica sand




Avg. TSS reduction = 67.3% Avg. TSS reduction = 71.0% Avg. TSS reduction = 53.6% (c) direct discharge testing with sandy loam soil


Figure C-34 Avg. TSS analysis data for FlexStorm® for performance evaluation tests.

OLDCASTLE STORMWATER SOLUTIONS FLO-GARD® PLUS


Figure C-35 provides upstream and downstream TSS sample data and the corresponding TSS reduction percentages for each test performed on the Flo-Gard® Plus. Target concentrations for upstream samples was 450 mg/L for tests with OK110 silica sand, and 185 mg/L for tests with sandy loam soil.



Avg. TSS reduction = 18.5% Avg. TSS reduction = 11.5% Avg. TSS reduction = 16.7% (a) sheet flow testing with OK110 silica sand



Avg. TSS reduction = 24.6% Avg. TSS reduction = 15.8% Avg. TSS reduction = 28.8% (b) direct discharge testing with OK110 silica sand




Avg. TSS reduction = 41.2% Avg. TSS reduction = 27.9% Avg. TSS reduction = 51.3% (c) direct discharge testing with sandy loam soil


Figure C-35 Avg. TSS analysis data for Flo-Gard® for performance evaluation tests.

GULLYWASHER® METAL COMPLIANT CBIS


Figure C-36 provides upstream and downstream TSS sample data and the corresponding TSS reduction percentages for each test performed on the Gullywasher©. Target concentrations for upstream samples was 450 mg/L for tests with OK110 silica sand, and 185 mg/L for tests with sandy loam soil.



Avg. TSS reduction = 79.4% Avg. TSS reduction = 59.3% Avg. TSS reduction = 33.5% (a) sheet flow testing with OK110 silica sand



Avg. TSS reduction = 71.9% Avg. TSS reduction = 50.4% Avg. TSS reduction = 39.6% (b) direct discharge testing with OK110 silica sand




Avg. TSS reduction = 62.4% Avg. TSS reduction = 62.8% Avg. TSS reduction = 23.6% (c) direct discharge testing with sandy loam soil


Figure C-36 Avg. TSS analysis data for Gullwasher for performance evaluation tests.

ENPAC STORM SENTINEL®


Figure C-37 provides upstream and downstream TSS sample data and the corresponding TSS reduction percentages for each test performed on the Storm Sentinel®. Target concentrations for upstream samples was 450 mg/L for tests with OK110 silica sand, and 185 mg/L for tests with sandy loam soil.



Avg. TSS reduction = 63.6% Avg. TSS reduction = 25.0% Avg. TSS reduction = 11.2% (a) sheet flow testing with OK110 silica sand



Avg. TSS reduction = 90.7% Avg. TSS reduction = 76.0% Avg. TSS reduction = 35.1% (b) direct discharge testing with OK110 silica sand




Avg. TSS reduction = 59.9% Avg. TSS reduction = 53.2% Avg. TSS reduction = 42.2% (c) direct discharge testing with sandy loam soil


Figure C-37 Avg. TSS analysis data for Storm Sentinel® for performance evaluation tests.

CONTECH ENGINEERED SOLUTIONS TRITON™


Figure C-38 provides upstream and downstream TSS sample data and the corresponding TSS reduction percentages for each test performed on the Triton™. Target concentrations for upstream samples was 450 mg/L for tests with OK110 silica sand, and 185 mg/L for tests with sandy loam soil.



Avg. TSS reduction = 74.7% Avg. TSS reduction = 58.4% Avg. TSS reduction = 47.5% (a) sheet flow testing with OK110 silica sand



Avg. TSS reduction = 92.1% Avg. TSS reduction = 61.4% Avg. TSS reduction = 45.9% (b) direct discharge testing with OK110 silica sand




Avg. TSS reduction = 40.0% Avg. TSS reduction = 58.1% Avg. TSS reduction = 49.7% (c) direct discharge testing with sandy loam soil

Figure C-38 Avg. TSS analysis data for Triton™ for performance evaluation tests.

WATER QUALITY SOLUTIONS STORM-WATER EXFILTRATION BMP

Figure C-39 provides upstream and downstream TSS sample data and the corresponding TSS reduction percentages for each test performed on the WQS. Target concentrations for upstream samples was 450 mg/L for tests with OK110 silica sand, and 185 mg/L for tests with sandy loam soil.




Avg. TSS reduction = 33.0%

Avg. TSS reduction = 38.9%

Avg. TSS reduction = 4.3%

(a) sheet flow testing with OK110 silica sand




Avg. TSS reduction = 40.2%

Avg. TSS reduction = 48.5%

Avg. TSS reduction = 52.0%

(b) direct discharge testing with OK110 silica sand



Avg. TSS reduction = 47.6%

Avg. TSS reduction = 66.8%


Avg. TSS reduction = 62.9%

(c) direct discharge testing with sandy loam soil

Figure C-39 Avg. TSS analysis data for WQS for performance evaluation tests.

LONGEVITY TESTING

During the longevity testing phase of the research, TSS samples were only taken for tests with the DrainPacTM using OK110 silica sand. After these tests, it was decided that TSS data was no longer necessary for CBI evaluation. TSS data from the eight longevity tests of the DrainPacTM with OK110 silica sand, all at the 0.06 ft³/s flow rate, can be found in Figure C-40.



INFLUENT ANALYSIS

Upon completion of CBI testing, it was determined that sediment retention percentage was a better measure of sediment removal performance than TSS reduction, as 14 samples per test was not a large enough sample size to accurately determine the average TSS for each test. However, all upstream samples can be combined to create a large enough sample size to analyze introduction characteristics and ensure that the sediment introduction system was operating within tolerable bounds.

For all tests with OK110 silica sand, target influent concentration was 0.028 lb/ft³ (450 mg/L). The average upstream TSS concentration for all samples with OK110 silica sand was 462.7 mg/L, a 2.8% error, indicating that the sediment introduction system operated well within tolerable limits. Two-sided hypothesis testing was conducted on this data to determine if x was significantly different than μ .

$$H_0$$
: $\mu = 450 \, mg/L$ H_A : $\mu \neq 450 \, mg/L$ (1)

 H_0 = null hypothesis

 H_A = alternate hypothesis

$$z = \frac{x - \mu}{s} = \frac{462.7 - 450}{152.7} = 0.08 \tag{2}$$

z = z-score

x = sample mean µ = target mean

s = sample standard deviation

A two-sided z-score of 0.08 corresponds to a p value of 0.9362. Since the p-value is greater than 0.05, we cannot say that this mean concentration is significantly different than the target concentration.

For all tests with sandy loam, target influent concentration was 0.012 lb/ft³ (185 mg/L). The average upstream TSS concentration for all samples with sandy loam was 257.2 mg/L. A two-sided hypothesis test was conducted below. From this calculation, we cannot say that the mean concentration of 257.2 mg/L is significantly different than the target concentration of 185 mg/L.

$$H_0$$
: $\mu = 185 \, mg/L$ H_A : $\mu \neq 185 \, mg/L$ (3)

 H_0 = null hypothesis

 H_A = alternate hypothesis

$$z = \frac{x - \mu}{s} = \frac{257.2 - 185}{90.6} = 0.80 \tag{4}$$

z = z-score

x = sample mean

 μ = target mean

s = sample standard deviation

A two-sided z score of 0.80 corresponds to a p value of 0.4238. Since the p-value is greater than 0.05, we cannot say that this mean concentration is significantly different than the target concentration.

LINEAR REGRESSION ANALYSES FOR SEDIMENT RETENTION

PRODUCT COMPARISON ANALYSIS

Table C-18 summarizes findings from the statistical comparison portion of the first linear regression analysis, related to the sediment retention capabilities of the CBI products. Based upon the linear regression analysis, the Adsorb-It™ retained sediment at a statistically significant higher rate than any of the other CBI products, while the Flo-Gard Plus® retained sediment at a statistically significant lower rate than any of the other CBI products. When evaluating the results of the regression analysis, if a p-value of less than 0.05 is reported, it suggests that there is a statistically significant difference between the CBI product under consideration compared to other CBI products. A significant p-value paired with a negative comparison coefficient suggests that the CBI product under consideration performs better statistically than the comparison CBI product. In this case, a p-value of less than 0.05 was reported when the Adsorb-It™ was compared to all other CBIs and all comparison coefficients were negative, providing the result that the Adsorb-It™ performed significantly better than all other CBIs tested. Conversely, a significant p-value paired with a positive comparison coefficient suggests that the comparison CBI product performed better statistically than the CBI product under consideration. In this case, the Flo-Gard Plus® had a p-value less than 0.05 when compared to each of the other CBI products and a positive comparison coefficient, providing the result that the Flo-Gard Plus® performed significantly worse than all other CBI products tested.

Table C-18 Product Comparison Using Linear Regression Analysis

Product Name	Product Coefficient	Comparison	Comparison Coefficient	p- value ^[1]	Statistically significant ^[2]
Adsorb-It™	74.0	DrainPac™	-15.96	0.007	Yes
		FlexStorm®	-17.06	0.004	Yes
		Flo-Gard Plus®	-60.50	<0.001	Yes
		Gullywasher©	-20.44	<0.001	Yes
		Storm Sentinel®	-31.52	<0.001	Yes
		Triton™	-20.74	<0.001	Yes
		WQS	-32.72	<0.001	Yes
DrainPac™	58.04	FlexStorm®	-1.1	0.849	
		Flo-Gard Plus®	-44.54	<0.001	Yes
		Gullywasher©	-4.49	0.438	
		Storm Sentinel®	-15.57	0.009	Yes
		Triton™	-4.78	0.424	
		WQS	-16.76	0.004	Yes
FlexStorm®	56.94	Flo-Gard Plus®	-43.44	<0.001	Yes
		Gullywasher©	-3.39	0.558	
		Storm Sentinel®	-14.47	0.015	Yes
		Triton™	-3.68	0.537	
		WQS	-15.66	0.007	Yes
	13.50	Gullywasher©	40.06	<0.001	Yes
Flo-Gard Plus®		Storm Sentinel®	28.98	<0.001	Yes
		Triton™	39.76	<0.001	Yes
		WQS	27.78	<0.001	Yes
	53.55	Storm Sentinel®	-11.08	0.059	
Gullywasher©		Triton™	-0.29	0.961	
		WQS	-12.28	0.033	Yes
Storm Sentinel®	42.48	Triton™	10.79	0.074	Yes
Storm Sentiners	42.40	WQS	-1.20	0.832	
Triton™	53.26	WQS -11.98		0.044	Yes

NOTE: [1] : α= 0.05

[2]: -- = the test failed to identify a statistically significant difference.

FLOW RATE COMPARISON ANALYSIS

The regression analysis also assessed the effects that the other factors (e.g., discharge method, soil type, and flow rate) have on sediment retention, which is summarized in Table C-19. Negative coefficients and p-values less than 0.05 suggest that there is a statistically significant decrease in sediment retention for both the medium and high flow tests compared to the low flow tests. However, because the 0.06 ft³/s flow was used as the constant during this regression analysis, it does not conclude whether there is a difference in sediment retention between medium and high flow tests. Therefore, a separate regression analysis was conducted with 0.12 ft³/s as the base. The coefficient between the 0.12 ft³/s and 0.18 ft³/s flow rate was -7.25 with a p-value of 0.044, suggesting that there is a statistically significant decrease in sediment retention when flow rates increases from 0.12 ft³/s to the 0.18 ft³/s. This suggests that a CBI products' performance is directly associated with the amount of flow entering the catch basin (i.e., sediment retention decreases as flow rate increases, or as drainage area increases).

DISCHARGE METHOD COMPARISON ANALYSIS

It can also be concluded that there was a statistically significant increase in sediment retention between sheet flow and direct discharge method tests. This supports the observations that many of the products were allowing sheet flow to bypass the CBI via a leak between the CBI and the catch basin frame, and therefore treating a smaller percentage of the runoff, and capturing less sediment. Therefore, from a product testing standpoint, it was beneficial to switch to the direct discharge method to assure each CBI product was tested under the same conditions eliminating the variable of leakage at the CBI seal with the catch basin frame.

SOIL TYPE COMPARISON ANALYSIS

Finally, while the data does show that there was a small decrease in sediment retention amongst tests with sandy loam compared to tests with the OK110 silica sand, the p-value is greater than 0.05, meaning we cannot conclude that there is a significant difference in sediment retention amongst the two soil types.

Table C-19 Test Characteristic Comparison

Test Characteristic	Statistical	Significance	Statistically Significant ^[2]				
rest Characteristic	Coefficients	p-value ^[1]					
Constant	74.00	0.00	Yes				
Flow (Base: 0.06 ft ³ /s)							
0.12 ft ³ /s	-8.14	0.024	Yes				
0.18 ft ³ /s	-15.39	<0.001	Yes				
Discharge Method (Base: Sheet Flow)							
Direct Discharge	9.27	0.011	Yes				
Soil Type (Base: OK110)							
Sandy Loam	-5.87	0.101					

Note: [1]: $\alpha = 0.05$

[2]: -- = the test failed to identify a statistically significant difference.

EFFECT OF OVERFLOW ON SEDIMENT RETENTION

Sediment retention data was also used to analyze the effect overflow events had on CBI performance. Sediment retention data was separated into two categories: (1) tests where overflow does not occur, and (2) tests where overflow does occur. To analyze overflow characteristics, Figure C-41(a) plots sediment retention for CBI products that experienced overflow. Products that did not produce overflow were not included in this analysis since high flow through rates would result in no overflow but also little sediment capture, contradicting the results of this analysis. Each CBI that experience overflow was analyzed by comparing the percent of the storm that was treated before overflow occurs. This illustrates the relationship between overflow and sediment retention values. For example, if 90% of the storm is treated before overflow occurs, sediment retention is likely to be greater than if only 10% of the storm was treated before overflow begins. The data was then fit with a logarithmic trendline to measure the relationship between the two variables. It can be seen from the coefficient of determination that there is a positive, moderately strong correlation between time at which overflow occurs and sediment retention. This means that tests that lasted longer before allowing overflow were more likely to retain a higher percentage of the introduced sediment. A logarithmic trendline provided the best-fit trendline because, while sediment retention does continue to increase with increase in time before overflow, sediment retention will eventually approach a maximum and begin to plateau. Therefore, if overflow occurs early, one can expect much less sediment to be captured. However, overflow that begins near the end of the event has little impact on sediment retention. From these analyzes, it appears that the best performing product would be one that minimizes flow through the fabric to the point of water impounding to near the point of overflow. However, overflow should be minimal and begin near the end of the storm event, resulting in the largest percent of particle size capture.

Figure C-41 (b-d) contain the same information as Figure C-41(a) but are separated by the flow rate used for testing. It can be seen that there is little correlation between overflow and sediment retention during low flow tests. However, correlation increases with flow rate. One possible explanation for this is that higher flow rates enter the CBI with greater energy, therefore causing re-suspension of captured particles, and hindering sediment retention. At low flow rates, the influent enters the catch basin with less energy and less potential for re-suspension, therefore having little effect on sediment retention.




Figure C-41 Comparing overflow to sediment retention